#### **Inspect Minnesota & Midwest Soil Testing**

P.O. Box 10853 White Bear Lake, MN 55110 651-492-7550/Brian@Midwestsoiltesting.com

Brian Humpal

MPCA Licensed Advanced Inspector

#### SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

**Inspection Address:** 19435 Olinda Trail, Scandia, MN 55047

#### **REPORT SUMMARY**

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the original design/permit records on file at Washington County. This system consists of two pre-cast septic tanks, a pre-cast lift tank, and a mound. This house is presently vacant.

Predicated on my inspection of the system and my review of the original design/permit records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Inspect Minnesota and Midwest Soil Testing have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Inspect Minnesota and Midwest Soil Testing disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal



## **Compliance Inspection Form**

# Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

<b>Instructions:</b> Inspection results based on Minnesota Pollution Control Agency (MPCA) requirements and attached forms – additional local requirements may also apply.	For local tracking purposes:
Submit completed form to Local Unit of Government (LUG) and system owner within 15 days	
System Status	
System status on date (mm/dd/yyyy): 6/25/2018	
·	npliant – Notice of Noncompliance rade Requirements on page 3)
Reason(s) for noncompliance (check all applicable)  Impact on Public Health (Compliance Component #1) – Imminent threat to Other Compliance Conditions (Compliance Component #3) – Imminent threat the Tank Integrity (Compliance Component #2) – Failing to protect groundwate Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwate Soil Separation (Compliance Component #4) – Failing to protect groundwate Operating permit/monitoring plan requirements (Compliance Component #4)	eat to public health and safety er otect groundwater ater
Property Information Parcel ID# or Sec/Twp/Rang	ge:
	or inspection: Property Transfer
Property owner: Seefert Estate Owner's	phone:
Owner's representative: Ross Brunfelt (Keller Williams) Represer	ntative phone: 651-433-3333
· · · · · · · · · · · · · · · · · · ·	ry authority phone: 651-430-6655
Brief system description: Two pre-cast septic tanks, a pre-cast lift tank, and a moun	d.
Comments or recommendations:	
Certification	
I hereby certify that all the necessary information has been gathered to determine the of determination of future system performance has been nor can be made due to unknown possible abuse of the system, inadequate maintenance, or future water usage.	
Inspector name: Brian Humpal/Christopher Uebe Certification	on number: <u>C5342/C9852</u>
	se number: L2896
Inspector signature: Brian Humpak ffin the Pho	ne number: 651-492-7550
Necessary or Locally Required Attachments	
	local ordinance
☐ Other information (list): _ Report Summary, Property Information, Disclaimer, Lic	ense

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 1 of 3

Property address: 19435 Olinda Trail, Scandia, MN 55047

Inspector initials/Date: 6/25/2018 **24** 

1.	Impact on Public Health – Cor	mpliance component #1 of	f 5
	Compliance criteria:  System discharge sewage to the ground surface.  System discharge sewage to drain tile or surface waters.  System cause sewage backup into dwelling or establishment.  Any "yes" answer above indicates an Imminent Threat to Public Heal  Comments/Explanation:  None of the above found.		Verification method(s):  ☐ Searched for surface outlet ☐ Searched for seeping in yard/backup in home ☐ Excessive ponding in soil system/D-boxes ☐ Homeowner testimony (See Comments/Explanation) ☐ "Black soil" above soil dispersal system ☐ System requires "emergency" pumping ☐ Performed dye test ☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)
2.	Tank Integrity – Compliance com	nponent #2 of 5	
	Compliance criteria:  System consists of a seepage pit, cesspool, drywell, or leaching pit.  Seepage pits meeting 7080.2550 may be compliant if allowed in local ordinance.  Sewage tank(s) leak below their designed operating depth.  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicasystem is Failing to Protect Green Comments/Explanation:  Lowered underwater camera into tanks - Lift pump and alarm were operational at	baffles and tank walls OK. the time of the inspection.	Verification method(s):  ☐ Probed tank(s) bottom ☐ Examined construction records ☐ Examined Tank Integrity Form (Attach) ☐ Observed liquid level below operating depth ☐ Examined empty (pumped) tanks(s) ☐ Probed outside tank(s) for "black soil" ☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)
3.	a. Maintenance hole covers are damaged, cracked, unsecured, or appear to structurally unsound.  ☐ Yes* ☐ No ☐ Unknown b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety. ☐ Yes* ☐ No ☐ Unknown *System is an imminent threat to public health and safety  Explain:  c. System is non-protective of ground water for other conditions as determined by inspector ☐ Yes* ☐ No *System is failing to protect groundwater  Explain:		

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

Pro	perty address: <u>19435 Olinda Trail, Scandia, M</u>	N 55047	Inspector initials/Date: _6/	25/2018 <b>8#</b> (M		
4.	Soil Separation — Compliance compor	nent #4 of 5				
	Date of installation: 2002	Unknown	Verification method(s):			
	Shoreland/Wellhead protection/Food Beverage Lodging?	⊠ Yes □ No	Soil observation does not expire. P observations by two independent p			
	Compliance criteria:			nless site conditions have been altered or local		
	For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	☐ Yes ☐ No	requirements differ.  Conducted soil observation(s) (Attach to the last of the	nch boring logs)		
	Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.		☐ Unable to verify (See Comments.☐ Other (See Comments/Explanation	/Explanation)		
	Non-performance systems built April 1,	⊠ Yes □ No	Comments/Explanation:			
	1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:		Reviewed design and permit record	ds.		
	Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*					
	"Experimental", "Other", or "Performance"	☐ Yes ☐ No	Indicate depths of elevations			
	systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)	_	A. Bottom of distribution media	See Attached Boring Log(s)		
	Drainfield meets the designed vertical		B. Periodically saturated soil/bedrock			
	separation distance from periodically saturated soil or bedrock.		C. System separation			
	Saturated 3011 of bedrock.		D. Required compliance separation*			
	Any "no" answer above indicates the system is Failing to Protect Groundwater.		*May be reduced up to 15 percent Ordinance.	if allowed by Local		
5.	Operating Permit and Nitrogen B	<b>MP*</b> – Compliance	component #5 of 5  Not app	olicable		
	Is the system operated under an Operating Per	mit?	☐ No If "yes", A below is required			
	Is the system required to employ a Nitrogen BM	IP? ☐ Yes ☐	☐ No If "yes", B below is required			
	BMP=Best Management Practice(s) specifi	ied in the system desig	gn			
	If the answer to both questions is "no",	this section does i	not need to be completed.			
	Compliance criteria					
	a. Operating Permit number:		Пу Пр			
	Have the Operating Permit requirements by	peen met?	☐ Yes ☐ No			
	b. Is the required nitrogen BMP in place and	properly functioning?	☐ Yes ☐ No			

Any "no" answer indicates Noncompliance.

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 TTY 651-282-5332 or 800-657-3864 • Available in alternative formats Page 3 of 3


6/25/2010 284

## Inspect Minnesota & Midwest Soil Testing Subsurface Sewage Treatment System Owner/Property Information This information will be used for the purpose of conducting an MPCA Compliance Inspection.

Date of Inspection: June 25, 2018	Time: 8:30 AM		
Property Address: 19435 Olinda Trail, Scandia, MN	Zip: 55047		
Property Owner: Seefert Estate	Phone:		
Tank(s)       Tank(s)Material       Soil Treatment System         Septic 2       Fiberglass       Rock trench         Aerobic       Plastic       Gravelless trench         Lift       Metal       Chamber trench         Holding       Concrete       Seepage bed         Other:       Block       Mound         Other       At-grade	Other  Alternative system Experimental system Cesspool system Other system		
Are the tank maintenance covers accessible? ⊠ Yes ☐ No *If i			
performed through the maintenance holes. Maintenance hole cover			
the ground surface to facilitate access and proper maintenance of t	he system.		
Year house built: 1987 Year septic installed: 2002	Γank size (gals.): 1-1200, 1-1000		
	sidents in home?		
Number of bedrooms? 2 Are all floors drained by gr	•		
Garbage disposal? Whirlpool bath?			
More than one system (laundry, etc.)?			
Does this property have any footing drain tiles connected to the se	ptic system?		
Are any buildings on this property such as garages or out-buildings connected to this system?			
Are there any additional systems on this property serving other bu	ildings?		
Location of septic system on lot? North Side			
Location of water well on lot? North Side	well a deep well? Y		
Have you ever experienced any problems with the system such as:	tree roots, sewage back-ups,		
surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system?  If yes, explain:			
When was the system last pumped? 2015 Name of pum	per:		
How often pumped in previous years?			
Have you received notices from any government agency concerning this system?			
Is your property located in a shoreland management area? Y			
Do you have any additional information that should be given to the new owner?			
I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection			

Owner/Occupant: Date:

by Inspect Minnesota and Midwest Soil Testing.



#### **Log Of Soil Borings**

Location of Project: 19435 Olinda Trail, Scandia, MN 55047					
Borings Made By: Inspect Minnesota			Date:	6/25/18	
Auger Used: Hand/Bucket		Classification System: USDA		USDA	
	Boring Number:	1		Boring Number:	
Surface Elevation Boring	of 42" below	top of mound on inal contour	Surface Elevation Boring	of	
Depth In Inches	Soils E	ncountered	Depth In Inches	Soils Er	countered
0-14 14-19 19-26	10YR 4/4 ( Grey S 10YR 4/4 (	/3 Silt Loam Clay Loam With Silt Coatings Clay Loam With ngs & 5YR 3/4 Redox			
19"	Depth To End Of B	oring Or Redox		Depth To End Of Bo	oring Or Redox
+42"	Elevation Of Boring	g Below Top Of Mound		Elevation Of Boring	Relative To System
-29"		Of Distribution Media			f Distribution Media
=32"	Of Separation		(	Of Separation	
	End Of Paring At-	26"		End Of Paring At-	
	End Of Boring At:			End Of Boring At:	
Redox Present At: 19"			Redox Present At: Water Present At:		
Standing Water Present At: None		Standing	water Fresent At.		

Bottom Of Distribution Medium At: 29 Inches

***		8 of 11	_	
111111	8 7 6	ω 4. ν 	N P	PEPTH
	\$70 p	MEDIUM GAND	REDDISH BROWN CLAY  REDDISH BROWN SANDY CLAY  NOTLED SOIL	HOLE #1
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		TOP SOIL - LEAM REDDISH BROWN CLAY- SOME GRAYS AEDDISH BROWN SANDY CLAY	HOLE #2
	- Moπιε 24"-38",-	m)   1	TOP SOIL - LOAM REDDISH BROWN CLAY FAINT GRAYS FRINT GRAYS	HOLE #3
	Monte 18"	REDDISH BROWN, SANDY CLAY- CRAYS- MOTILED SOIL	TOP SOIL- LOAM REDDISH BROWN CLAY REDDISH BROWN CLAY MOTHED	HOLE #4
1111111	\$70P	CLEAN	REDDISH BROWN CLAY  REDDISH BROWN CLAY  LIGHT MOTTLE	HOLE #5
<del>                                      </del>	<del></del>	BROWN, SANDY CLAY  BROWN, MEDIUM SAND SAND SAND SAND SAND SAND SAND SAND	1.7 1.45 1 0	HOLE #6

PAGE 1 of 2

BOREHOLE DIAMETER 4"-36" HAND AUGER

19435 OLINDA TRAIL

BORING LOG

DATE 9-19-01

DATE

19435 OLINDA TRAIL

BORING LOG

BOREHOLE DIAMETER 4" HAND AUGER

PAGE 2 #2

	9 of 11	
- 10	-	DEPTH FEET 1
	MOTLED ST	HOLE TOP S REDDISH BEDDISH BEDDISH BEDDISH BY
	LED SOIL	HOLE # 7 LOAM  NOY CLAY  NOY CLAY  NOY CLAY
│ │ <del>┤┤┤┤┤┤┤</del> ┼ <del>┤┼</del> ┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼	<del>,                                    </del>	╀╀┩╀╂╂┼┼┼
Motile	REDDISH SANDY REDDISH SANDY MOTLED	HOLE TOP LOGG
±∞.		P SOIL - LOAM SH BROWN
+++++++++++++++++++++++++++++++++++++++	1   1   1   1   1   1   1   1   1   1	+++++++++
		HOLE
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	#
<del>┆╎╸</del>	PRODE TO STR	2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,578 2,
	5 W	CLASSIFICATION REDDISH BROWN CLAST 2.5YR 34 2.5YR 34 5AND SAND SAND SAND SAND SAND SAND
<u></u>		BROWN BROWN BROWN BROWN
		HOLE #
<del>                                      </del>	╀╀┼┼┼┼┼┼┼┼┼┼	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
		HOLE
:		#

#### **DISCLAIMER**

# Brian L. Humpal, Inc. dba. Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1<sup>st</sup> through April 1<sup>st</sup>) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

# Subsurface Sewage Treatment Systems Non-transferable Business License

## Inspect Minnesota, Midwest Soil Testing

License # L2896

License Expires: 12/22/2018

Issued: 10/10/2017

es:

## Specialty Area(s):

Installer
Maintainer
Service Provider
Advanced Designer
Advanced Inspector

## Designated Certified Individual(s):

Cert #	Name	Certification Expir
C9633	Anthony P Scully	7/28/2018
	Installer, Designer (Conditional)	
C5342	Brian L Humpal	10/15/2020
	Installer, Maintainer, Serv Prov,	Adv Designer, Adv Inspector
C9852	Christopher R Uebe	3/4/2018
	Designer, Inspector	



520 Lafayette Road North St. Paul, Minnesota 55155-4194 Charles & Thompson

Charles K Thompson, Supervisor Certification & Training Unit