Inspect Minnesota & Midwest Soil Testing

P.O. Box 10853 White Bear Lake, MN 55110 651-492-7550/Brian@Midwestsoiltesting.com

Brian Humpal

MPCA Licensed Advanced Inspector

SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

Date: May 2, 2019 **Time:** 10:45 AM **Owner:** Lloyd Newman

Inspection Address: 10777 Dellwood Rd N, Grant, MN 55082

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the original design/permit records on file at Washington County. This system consists of two pre-cast septic tanks, a pre-cast lift tank, and a gravelless trench drainfield. This house is presently vacant.

Although not a compliance criteria, it should be noted that gravelless pipe is no longer approved for installation in the State of Minnesota and we have had experience with this product having significantly reduced performance and/or life expectancy. We cannot guarantee the performance of this system beyond the compliance date (5/2/2019). In addition, the septic tanks and lift tank manhole covers are buried. I recommend extending these covers to the ground surface to facilitate easier access and proper maintenance.

Predicated on my inspection of the system and my review of the original design/permit records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Inspect Minnesota and Midwest Soil Testing have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Inspect Minnesota and Midwest Soil Testing disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal



Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

| Instructions: Inspection results based on Minnesota Pollution Control Agency (MPCA) requirements and attached forms – additional local requirements may also apply. | For local tracking purposes: |
|--|---|
| Submit completed form to Local Unit of Government (LUG) and system owner within 15 days | |
| | |
| System Status | |
| System status on date (mm/dd/yyyy): 5/2/2019 | |
| | pliant – Notice of Noncompliance ade Requirements on page 3) |
| Reason(s) for noncompliance (check all applicable) | |
| ☐ Impact on Public Health (Compliance Component #1) – Imminent threat to | public health and safety |
| ☐ Other Compliance Conditions (Compliance Component #3) – Imminent thre | at to public health and safety |
| ☐ Tank Integrity (Compliance Component #2) – Failing to protect groundwate | r |
| ☐ Other Compliance Conditions (Compliance Component #3) – Failing to prot | ect groundwater |
| ☐ Soil Separation (Compliance Component #4) – Failing to protect groundwa | |
| ☐ Operating permit/monitoring plan requirements (Compliance Component # | 5) – Noncompliant |
| Property Information Parcel ID# or Sec/Twp/Range Property address: 10777 Dellwood Rd N, Grant, MN 55082 Reason for Owner's pl Property owner: Lloyd Newman Owner's pl | r inspection: Property Transfer |
| or | |
| Owner's representative: Shaundrea Kenyon - Daughter Represent | ative phone: <u>1-603-286-0018</u> |
| Local regulatory authority: Washington County Regulatory | authority phone: 651-430-6655 |
| Brief system description:Two pre-cast septic tanks, a pre-cast lift tank, and a gravelled | ess trench drainfield. |
| Comments or recommendations: | |
| Although not a compliance criteria, it should be noted that gravelless pipe is no longer a Minnesota and we have had experience with this product having significantly reduced percannot guarantee the performance of this system beyond the compliance date (5/2/2019) manhole covers are buried. I recommend extending these covers to the ground surface | erformance and/or life expectancy. We 9). In addition, the septic tanks and lift tank |
| Minnesota and we have had experience with this product having significantly reduced po- cannot guarantee the performance of this system beyond the compliance date (5/2/2019 manhole covers are buried. I recommend extending these covers to the ground surface maintenance. | erformance and/or life expectancy. We 9). In addition, the septic tanks and lift tank |
| Minnesota and we have had experience with this product having significantly reduced per cannot guarantee the performance of this system beyond the compliance date (5/2/2019) manhole covers are buried. I recommend extending these covers to the ground surface | erformance and/or life expectancy. We 9). In addition, the septic tanks and lift tank to facilitate easier access and proper |
| Minnesota and we have had experience with this product having significantly reduced potential cannot guarantee the performance of this system beyond the compliance date (5/2/2019) manhole covers are buried. I recommend extending these covers to the ground surface maintenance. Certification | erformance and/or life expectancy. We a). In addition, the septic tanks and lift tank to facilitate easier access and proper ampliance status of this system. No |
| Minnesota and we have had experience with this product having significantly reduced potential cannot guarantee the performance of this system beyond the compliance date (5/2/2019) manhole covers are buried. I recommend extending these covers to the ground surface maintenance. Certification I hereby certify that all the necessary information has been gathered to determine the condetermination of future system performance has been nor can be made due to unknown possible abuse of the system, inadequate maintenance, or future water usage. | erformance and/or life expectancy. We a). In addition, the septic tanks and lift tank to facilitate easier access and proper ampliance status of this system. No |
| Minnesota and we have had experience with this product having significantly reduced potential cannot guarantee the performance of this system beyond the compliance date (5/2/2019) manhole covers are buried. I recommend extending these covers to the ground surface maintenance. Certification I hereby certify that all the necessary information has been gathered to determine the condetermination of future system performance has been nor can be made due to unknown possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certification | erformance and/or life expectancy. We and lift tank to facilitate easier access and proper empliance status of this system. No a conditions during system construction, |
| Minnesota and we have had experience with this product having significantly reduced potential cannot guarantee the performance of this system beyond the compliance date (5/2/2019) manhole covers are buried. I recommend extending these covers to the ground surface maintenance. Certification I hereby certify that all the necessary information has been gathered to determine the condetermination of future system performance has been nor can be made due to unknown possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certification Business name: Inspect Minnesota, Midwest Soil Testing Licens | erformance and/or life expectancy. We a). In addition, the septic tanks and lift tank to facilitate easier access and proper empliance status of this system. No a conditions during system construction, on number:C5342/C9852 |
| Minnesota and we have had experience with this product having significantly reduced potential cannot guarantee the performance of this system beyond the compliance date (5/2/2019) manhole covers are buried. I recommend extending these covers to the ground surface maintenance. Certification I hereby certify that all the necessary information has been gathered to determine the condetermination of future system performance has been nor can be made due to unknown possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certification Unspect Minnesota, Midwest Soil Testing Licens Phone | erformance and/or life expectancy. We a). In addition, the septic tanks and lift tank to facilitate easier access and proper empliance status of this system. No a conditions during system construction, on number: C5342/C9852 L2896 |
| Minnesota and we have had experience with this product having significantly reduced potential cannot guarantee the performance of this system beyond the compliance date (5/2/2019) manhole covers are buried. I recommend extending these covers to the ground surface maintenance. Certification I hereby certify that all the necessary information has been gathered to determine the condition of future system performance has been nor can be made due to unknown possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certification Business name: Inspect Minnesota, Midwest Soil Testing Licens | erformance and/or life expectancy. We a). In addition, the septic tanks and lift tank to facilitate easier access and proper ampliance status of this system. No a conditions during system construction, an number: C5342/C9852 Be number: L2896 Be number: 651-492-7550 |

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 1 of 3

Property address: 10777 Dellwood Rd N, Grant, MN 55082

Inspector initials/Date: 5/2/2019 8/4

| 1. | Impact on Public Health – Co | mpliance compone | nt #1 of 5 | | | |
|-------------|--|--|--|--|--|--|
| | Compliance criteria: | | Verification method(s): | | | |
| | System discharge sewage to the ground surface. | ☐ Yes ⊠ No | ☑ Searched for surface outlet☑ Searched for seeping in yard/backup in home | | | |
| | System discharge sewage to drain tile or surface waters. | ☐ Yes ⊠ No | Excessive ponding in soil system/D-boxesHomeowner testimony (See Comments/Explanation) | | | |
| | System cause sewage backup into dwelling or establishment. | ☐ Yes ⊠ No | ☐ "Black soil" above soil dispersal system ☐ System requires "emergency" pumping ☐ Performed dye test | | | |
| | Any "yes" answer above indicate an Imminent Threat to Public Hea | | ☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation) | | | |
| 2. | | e with this product hav nis system beyond the | avelless pipe is no longer approved for installation in the State of ving significantly reduced performance and/or life expectancy. We compliance date (5/2/2019). | | | |
| ۷. | Compliance criteria: | importent #2 of 5 | Verification method(s): | | | |
| | System consists of a seepage pit, cesspool, drywell, or leaching pit. | ☐ Yes ⊠ No | ☑ Probed tank(s) bottom ☑ Examined construction records | | | |
| | Seepage pits meeting 7080.2550 may be compliant if allowed in local ordinance. | | Examined Tank Integrity Form (Attach)Observed liquid level below operating depth | | | |
| | Sewage tank(s) leak below their designed operating depth. | ☐ Yes ⊠ No | ☐ Examined empty (pumped) tanks(s) | | | |
| | If yes, which sewage tank(s) leaks: | | Probed outside tank(s) for "black soil" | | | |
| | Any "yes" answer above indic system is Failing to Protect G | | ☐ Unable to verify (See Comments/Explanation) ☑ Other methods not listed (See Comments/Explanation) | | | |
| | Comments/Explanation: | | | | | |
| | The septic tanks and lift tank manhole covers are buried. I recommend extending these covers to the ground surface to facilitate easier access and proper maintenance. | | | | | |
| 3. | Other Compliance Condition | S – Compliance co | mponent #3 of 5 | | | |
| | Maintenance hole covers are damage | • | • | | | |
| | _ | immediately and adve | ersely impact public health or safety. Yes* No Unknown | | | |
| | Explain: | | | | | |
| | c. System is non-protective of ground w *System is failing to protect ground Explain: | | ns as determined by inspector ☐ Yes* ☒ No | | | |

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

| orop | Property address: 10777 Dellwood Rd N, Grant, MN 55082 Inspector initials/Date: 5/2/2019 BH () | | | | | | | |
|------|--|----------------------|---|--|--|--|--|--|
| 4. | Soil Separation — Compliance component #4 of 5 | | | | | | | |
| | Date of installation: 1998 Shoreland/Wellhead protection/Food Beverage Lodging? Compliance criteria: | ☐ Unknown ☐ Yes ☐ No | Verification method(s): Soil observation does not expire. Previous soil observations by two independent parties are sufficient, unless site conditions have been altered or local | | | | | |
| | For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock. | ☐ Yes ☐ No | requirements differ. Conducted soil observation(s) (Attach boring logs) Two previous verifications (Attach boring logs) Not applicable (Holding tank(s), no drainfield) Unable to verify (See Comments/Explanation) Other (See Comments/Explanation) | | | | | |
| | Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: | ⊠ Yes □ No | Comments/Explanation: Reviewed design and permit records. | | | | | |
| | Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.* | | | | | | | |
| | "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required) | ☐ Yes ☐ No | A. Bottom of distribution media See Attached Boring Log(s) | | | | | |
| | Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock. | | B. Periodically saturated soil/bedrock C. System separation D. Required compliance separation* | | | | | |
| _ | Any "no" answer above indicates the Failing to Protect Groundwater. | <u> </u> | *May be reduced up to 15 percent if allowed by Local Ordinance. | | | | | |
| 5. | Operating Permit and Nitrogen BI Is the system operated under an Operating Perr | | ce component #5 of 5 Not applicable No If "yes", A below is required | | | | | |
| | Is the system required to employ a Nitrogen BM BMP=Best Management Practice(s) specific | | ☐ No If "yes", B below is required esign | | | | | |
| | If the answer to both questions is "no", this section does not need to be completed. | | | | | | | |
| | a. Operating Permit number: Have the Operating Permit requirements by | peen met? | ☐ Yes ☐ No | | | | | |
| | b. Is the required nitrogen BMP in place and Any "no" answer indicates Noncomp | | g? | | | | | |
| | Any no answermundles NonCom | Jiiaiice. | | | | | | |

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.


www.pca.state.mn.us • 651-296-6300 • 800-657-3864 TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 3 of 3

Inspect Minnesota & Midwest Soil Testing Subsurface Sewage Treatment System Owner/Property Information This information will be used for the purpose of conducting an MPCA Compliance Inspection.

| Date of Inspection: May 2, 2019 | Time: 10:45 AM | | | | |
|---|---|--|--|--|--|
| Property Address: 10777 Dellwood Rd N, Grant, MN | Zip: 55082 | | | | |
| Property Owner: Lloyd Newman | Phone: | | | | |
| Tank(s) Tank(s)Material Soil Treatment System Septic 2 Fiberglass Rock trench Aerobic Plastic Gravelless trench Lift Metal Chamber trench Holding Sconcrete Seepage bed Other: Block Mound Other At-grade | Other Alternative system Experimental system Cesspool system Other system | | | | |
| Are the tank maintenance covers accessible? Yes No *I performed through the maintenance holes. Maintenance hole co the ground surface to facilitate access and proper maintenance of | vers should be made accessible to | | | | |
| the ground surface to facilitate access and proper maintenance of | the system. | | | | |
| Year house built: 1998 Year septic installed: 1998 | Tank size (gals.): 2-1000 | | | | |
| | residents in home? | | | | |
| Number of bedrooms? 1 Are all floors drained by | | | | | |
| Garbage disposal? Whirlpool bath | 1? | | | | |
| More than one system (laundry, etc.)? | | | | | |
| Does this property have any footing drain tiles connected to the | | | | | |
| Are any buildings on this property such as garages or out-buildings connected to this system? Are there any additional systems on this property serving other buildings? | | | | | |
| Location of septic system on lot? Tanks - East Side, Drainfield - | Northeast Side | | | | |
| | ne well a deep well? Y | | | | |
| Have you ever experienced any problems with the system such a | | | | | |
| surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? If yes, explain: | | | | | |
| When was the system last pumped? 2017 Name of pu | mper: Ron's Sewer Service | | | | |
| How often pumped in previous years? | | | | | |
| Have you received notices from any government agency concerning this system? | | | | | |
| Is your property located in a shoreland management area? N | | | | | |
| Do you have any additional information that should be given to the new owner? | | | | | |
| I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection | | | | | |

Owner/Occupant: Date:

by Inspect Minnesota and Midwest Soil Testing.



N NO SCALE

Log Of Soil Borings

| Location of Project: 10777 Dellwood Rd N, Grant, MN 55082 | | | | | | |
|---|---|---|--|------------------------------------|---|--|
| Borings Made By: Inspect Minnesota | | | | Date: | 5/2/19 | |
| Auger Used: Hand/Bucket | | | Class | assification System: USDA | | |
| В | oring Number: | 1 | | Boring Number: | 2 | |
| Surface Same ground surface as last | | Surface Elevation of Boring Same ground surface as drainfield trench | | | | |
| Depth In Inches | Soils E | ncountered | Depth In Inches | Soils Encountered | | |
| 0-10 10-37 37-55 55-61 | 10YR 3/4 Lo Trace 10YR 3/4 Loam Gravel ≈10-15 5YR 4/4 | 2 Sandy Loam Damy Sand With Doamy Sand With Of Gravel Y Sand (Moist) With SW Rock Fragments Sandy Loam Sal At 61" | 0-12 12-30 30-56 | 10YR 3/4 5YR 4/4 Sandy Trace | 2 Sandy Loam 3 Loamy Sand 4 Loamy Sand 5 Loam (Moist) With 6 Of Gravel 6 Sal At 56" | |
| 61" Depth To End Of Boring Or Redox | | 56" | Depth To End Of Boring Or Redox | | | |
| Same Elevation Of Boring Relative To System | | Same | | | | |
| | epth To Bottom (f Separation | Of Distribution Media | -23" Depth To Bottom Of Distribution Media ≥33" Of Separation | | Of Distribution Media | |
| End Of Boring At: 61" | | | | End Of Boring At: | 56" | |
| | Redox Present At: None | | | Redox Present At: | | |
| Standing W | ater Present At: | None | Standing | Water Present At: | None | |

Bottom Of Distribution Medium At: 23 Inches

| DATE 4-25 + 27-98 | - HELM | NORTH TEST SI GRAVEL-LESS PIPE GRADED | EAADED. | BOREHOLE DIAMETER 4"- | 3/2"-21/2" HAND AUG |
|---|-----------------------|--|----------------|-----------------------|--------------------------|
| DEPTH HOLE #1 | HOLE #2 | HOLE #3 | HOLE #4 | HOLE #5 | HOLE #6 |
| TOP SOIL | SANDY LOAM | FILL- | SANDY LOAM | 78P SOIL | TOP SOIL |
| BROWN, FINE - | - | SANDY LOAM | - - | BROWN, SANDY . | BROWN, FINE SAND WITH |
| 2 + - | | - - | | MOTTLED SOIL | LOAM |
| 3 - REDDISH BROWN, - | <u>-</u> - | - - | <u>+</u> - | Srop _ | REDDISH BROWN |
| 4 = = | | | - - | - | MOTTLE |
| 5 | | BURIED BRUSH | OBSTRUCTION | - | 570 P |
| FAINT MOTTLE | | | STOP | MOTILE 20" | Ŧ <i>""</i> |
| 6 REDDISH BROWN, SANDY LOAM - CLEAN | 5TOP _ | - | - - | - | MOTTLE 40" |
| 7 - 0,5,7 | OKAY L' | STOP | <u>+</u> - | - | THOTTLE 40 |
| 8 | BORING IN GRADED AREA | - | FIRST 12" - | - | ‡ |
| FAINT MOTTLE | FIRST 8" - | <u>.</u> | COMPACTED | | - |
| | COMPACTED - | + | + - | | + |

| DATE | PELLWOOD ROAD - | HELM 1898 ET | BORING LOG GRTH TEST S HOEL-LESS PRE | TE . | · | PAGE 2 OF 3 |
|----------------|-------------------------------|----------------|--|----------------------|--------------|-------------------|
| DEPTH FEET | HOLE #:7 | HOLE #8 | HOLE # | 5014 | HOLE # | #"- 3½" HAND AUGE |
| | | | | CLASSIFICATION | HOLL # | HOLE # |
| 1 + | TOP SOIL - | TOP SOIL | • | I BROWN SAND - I | - | ± |
| 1 1 | BROWN, FINE - | BROWN, FINE | | BROWN LOAM | | + |
| 1 + | SAND WITH . | SAND WITH | - | 7.5 YR 4/4 | _ | + : |
| 1 + | LOAM - | -LOAM - | | \pm_{ρ} . \pm | - | ニ |
| 2 | _ | + + | | LOAM - CLAY | • | + |
| - + | | T T | - | 2.5 YR 5/4 | _ | |
| 1 + | - | + $-$ | | 工 | - | ユ |
|] 3 🛨 | | + + | | + $+$ | | 4 |
| 1,1 | · - | | - | + | - | |
| 1 + | 70. | REDDISH BROWN, | | エニュ | · - | 土 |
| 1 a 1 ~ | ЕОБІЗН ВКОШИ, . БАИБУ LOAM | SANDY LOAM | | + + | • | T . |
| 1 1 | WITH LIGHT | | - | + + | _ | |
| | SAND LAYERS- | MOTTLED SOIL - | | <u> </u> | • | + |
| '_ + | FAINT GRAYS . | SOIL IS WET | | T I | - | T |
| 5 | — | STOP _ | _ | + $+$ | _ | <u></u> |
| 1 1 | MOTTLED SOIL | 工 "" 土 | | + + | • | + |
| 1 + | STOP. | + . + | • | T I | - | |
| 16 — | · - | + + | _ | ++ | _ | エ |
| | _ | <u> </u> | • | + + | | + |
| 1 <u>+</u> | | MOTTLE 4'Z" | • | エ エ | - | + |
| 7 — | 00 | + + | - | $+$ \bot | <u>.</u> | ユ |
| I エ | MOTILE 5 - | <u> </u> | | + + | • | + |
| 1 + | | + ∓ | • | T | - | + |
| 8 | SOIL WET | + | _ | + | | ユ |
| | RED LOAM | <u> </u> | | + + | | + |
| 1 +· | | + = | | I t | - | + |
| 9 | | + | | <u> </u> | _ | ユ |
| I | | <u> </u> | | + . + | | + |
| 1 + | - | + | • | T + | - | + |
| 10 | · _ | + | · | + I | · . | ユ |
| 1 工 | · • | T T | • | ↑ *** | | + |
| , | | 1 | · - | | - | -+- |

DISCLAIMER

Brian L. Humpal, Inc. dba. Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems

Non-transferable

Business License

Inspect Minnesota, Midwest Soil Testing

License # L2896

License Expires: 12/22/2019

Issued: 11/20/2018

Specialty Area(s):

Installer
Maintainer
Service Provider
Advanced Designer
Advanced Inspector

Designated Certified Individual(s):

| Cert # | Name | Certification Expires: |
|--------|---------------------------------------|-------------------------|
| C9633 | Anthony P Scully | 3/5/2020 |
| | Installer, Designer (Apprentice) | |
| C5342 | Brian L Humpal | 10/15/2023 |
| | Installer, Maintainer, Serv Prov, Adv | Designer, Adv Inspector |
| C9852 | Christopher R Uebe | 3/4/2021 |
| | Designer, Inspector | |



520 Lafayette Road North St. Paul, Minnesota 55155-4194 Mich Haig

Nick Haig, Supervisor Certification and Training Unit