Inspect Minnesota & Midwest Soil Testing

P.O. Box 10853 White Bear Lake, MN 55110 651-492-7550/Brian@Midwestsoiltesting.com

Brian Humpal MPCA Licensed Advanced Inspector

SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

Inspection Address: 16780 Jeffrey Ave N, Hugo, MN 55038

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the original design/permit records, along with a previous compliance inspection from 2011 and 2007, which were on file at Washington County. This system consists of two pre-cast septic tanks (installed in 2007), a pre-cast lift tank, and an older rock trench drainfield (installed in approximately 1989). It should be noted that the average life expectancy of a septic system is approximately 30 years.

Although not a compliance criteria, it should be noted that a soil boring over the drainfield indicated gray/black soils. This is an indication that the drainfield <u>may be</u> at the end of its useful life.

Predicated on my inspection of the system and my review of the records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Inspect Minnesota and Midwest Soil Testing have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Inspect Minnesota and Midwest Soil Testing disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal



Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspection results based on Minnesota Pollution Control Agency (MPCA)	
requirements and attached forms – additional local requirements may also apply.	For local tracking purposes:
Submit completed form to Local Unit of Government (LUG) and system owner within 15 days	
System Status	
System status on date (mm/dd/yyyy):9/30/2019	
<u> </u>	mpliant – Notice of Noncompliance grade Requirements on page 3)
Reason(s) for noncompliance (check all applicable) Impact on Public Health (Compliance Component #1) – Imminent threat to Other Compliance Conditions (Compliance Component #3) – Imminent the Tank Integrity (Compliance Component #2) – Failing to protect groundware Other Compliance Conditions (Compliance Component #3) – Failing to protect groundware Soil Separation (Compliance Component #4) – Failing to protect groundware Operating permit/monitoring plan requirements (Compliance Component	reat to public health and safety ter otect groundwater vater
Property Information Parcel ID# or Sec/Twp/Ran	qe:
· ·	J
Property address: 16780 Jeffrey Ave N, Hugo, MN 55038 Reason	for inspection: Property Transfer
· · · · · · · · · · · · · · · · · · ·	for inspection: Property Transfer phone: 651-295-0618
Property owner: Joan Benner Owner's	
Property owner: Joan Benner Owner's or Owner's representative: Represe	phone: 651-295-0618 ntative phone:
Property owner: Joan Benner Owner's or Owner's representative: Represe Local regulatory authority: Washington County Regulator	phone: 651-295-0618
Property owner: Joan Benner Owner's or Owner's representative: Represe Local regulatory authority: Washington County Regulator Brief system description: Two pre-cast septic tanks, a pre-cast lift tank, and a rock	phone: 651-295-0618 ntative phone: 651-430-6655
Property owner: Joan Benner Owner's or Owner's representative: Represe Local regulatory authority: Washington County Regulator Brief system description: Two pre-cast septic tanks, a pre-cast lift tank, and a rock Comments or recommendations: Although not a compliance criteria, it should be noted that a soil boring over the drainf	phone: 651-295-0618 Intative phone: 651-430-6655 Itrench drainfield.
Property owner: Joan Benner Owner's or Owner's representative: Represe Local regulatory authority: Washington County Regulator Two pre-cast septic tanks, a pre-cast lift tank, and a rock Comments or recommendations: Although not a compliance criteria, it should be noted that a soil boring over the drainfindication that the drainfield may be at the end of its useful life.	phone: 651-295-0618 Intative phone: 651-430-6655 Itrench drainfield.
Property owner: Joan Benner Owner's or Owner's representative: Represe Cocal regulatory authority: Washington County Regulator Comments or recommendations: Although not a compliance criteria, it should be noted that a soil boring over the drainfindication that the drainfield may be at the end of its useful life. Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknown.	phone: 651-295-0618 Intative phone: 651-430-6655 Itrench drainfield. eld indicated gray/black soils. This is an compliance status of this system. No
Property owner: Joan Benner Owner's or Owner's representative: Represe Local regulatory authority: Washington County Regulator Brief system description: Two pre-cast septic tanks, a pre-cast lift tank, and a rock Comments or recommendations: Although not a compliance criteria, it should be noted that a soil boring over the drainfindication that the drainfield may be at the end of its useful life. Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknow possible abuse of the system, inadequate maintenance, or future water usage.	phone: 651-295-0618 Intative phone: 651-430-6655 Itrench drainfield. eld indicated gray/black soils. This is an compliance status of this system. No
Property owner: Joan Benner Owner's or Owner's representative: Represe Local regulatory authority: Washington County Regulator Brief system description: Two pre-cast septic tanks, a pre-cast lift tank, and a rock Comments or recommendations: Although not a compliance criteria, it should be noted that a soil boring over the drainfindication that the drainfield may be at the end of its useful life. Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknow possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certifica	phone: 651-295-0618 Intative phone: 651-430-6655 Itrench drainfield. The eld indicated gray/black soils. This is an accompliance status of this system. No year conditions during system construction,
Property owner: Joan Benner Owner's or Owner's representative: Represe Local regulatory authority: Washington County Regulator Brief system description: Two pre-cast septic tanks, a pre-cast lift tank, and a rock Comments or recommendations: Although not a compliance criteria, it should be noted that a soil boring over the drainfindication that the drainfield may be at the end of its useful life. Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknow possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certifica Business name: Inspect Minnesota, Midwest Soil Testing Lice	phone: 651-295-0618 Intative phone: 651-430-6655 Itrench drainfield. The properties of the system of this system. No vin conditions during system construction, stion number: C5342/C9852
Property owner: Joan Benner Owner's or Owner's representative: Represe Local regulatory authority: Washington County Regulator Brief system description: Two pre-cast septic tanks, a pre-cast lift tank, and a rock Comments or recommendations: Although not a compliance criteria, it should be noted that a soil boring over the drainfindication that the drainfield may be at the end of its useful life. Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknow possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certifica Business name: Inspect Minnesota, Midwest Soil Testing Lice Philippector signature: Philippect Minnesota Midwest Soil Testing Philippector Signature: Philippector Signature	phone: 651-295-0618 Intative phone: 651-430-6655 Itrench drainfield. eld indicated gray/black soils. This is an compliance status of this system. No yn conditions during system construction, tion number: C5342/C9852 Inse number: L2896
Property owner: Joan Benner Owner's or Owner's representative: Represe Local regulatory authority: Washington County Regulator Brief system description: Two pre-cast septic tanks, a pre-cast lift tank, and a rock Comments or recommendations: Although not a compliance criteria, it should be noted that a soil boring over the drainfindication that the drainfield may be at the end of its useful life. Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknow possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certifica Business name: Inspect Minnesota, Midwest Soil Testing Lice Inspector signature: Photocally Required Attachments	phone: 651-295-0618 Intative phone: 651-430-6655 Itrench drainfield. eld indicated gray/black soils. This is an compliance status of this system. No yn conditions during system construction, tion number: C5342/C9852 Inse number: L2896

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 1 of 3

Property address: <u>16780 Jeffrey Ave N, Hugo, MN 55038</u>

Inspector initials/Date: 9/30/2019 8/4

1.	Impact on Public Health – C	ompliance componer	nt #1 of 5		
	Compliance criteria:		Verification method(s):		
	System discharge sewage to the ground surface.	☐ Yes ⊠ No	 ✓ Searched for surface outlet ✓ Searched for seeping in yard/backup in home 		
	System discharge sewage to drain tile or surface waters.	☐ Yes ⊠ No	 ☑ Excessive ponding in soil system/D-boxes ☐ Homeowner testimony (See Comments/Explanation) 		
	System cause sewage backup into dwelling or establishment.	☐ Yes ⊠ No	"Black soil" above soil dispersal systemSystem requires "emergency" pumpingPerformed dye test		
	Any "yes" answer above indicat an Imminent Threat to Public He		☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)		
	Comments/Explanation: Although not a compliance criteria, it sindication that the drainfield may be at		oil boring over the drainfield indicated gray/black soils. This is an		
2.	Tank Integrity — Compliance c	omponent #2 of 5			
	Compliance criteria:		Verification method(s):		
	System consists of a seepage pit, cesspool, drywell, or leaching pit.	☐ Yes ⊠ No	☑ Probed tank(s) bottom☑ Examined construction records		
	Seepage pits meeting 7080.2550 may be compliant if allowed in local ordinance.		Examined Tank Integrity Form (Attach)Observed liquid level below operating depth		
	Sewage tank(s) leak below their designed operating depth.	☐ Yes ⊠ No	☐ Examined empty (pumped) tanks(s)		
	If yes, which sewage tank(s) leaks:		☐ Probed outside tank(s) for "black soil"☐ Unable to verify (See Comments/Explanation)		
	Any "yes" answer above indi system is Failing to Protect (☐ Official to Verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)		
3.	Comments/Explanation: Lowered underwater camera into tank Lift pump and alarm were operational Other Compliance Conditio	at the time of the inspec	ction.		
	·	· · · · · · · · · · · · · · · · · · ·	,or appear to structurally unsound. ☐ Yes* ☒ No ☐ Unknown		
		o immediately and adver	sely impact public health or safety. ☐ Yes* ☒ No ☐ Unknown		
	Explain:				
	c. System is non-protective of ground *System is failing to protect ground Explain:		s as determined by inspector ☐ Yes* ☒ No		

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

Property address: 16780 Jeffrey Ave N, Hugo, MN 55038

Inspector initials/Date: 9/30/2019 **BH**

4.	Soil Separation – Compliance compor	nent #4 of 5			
	Date of installation: 1989/2007 Shoreland/Wellhead protection/Food Beverage	☐ Unknown☐ Yes ☒ No	Verification method(s): Soil observation does not expire. Pro	evious soil	
	Lodging? Compliance criteria:		observations by two independent parties ar unless site conditions have been altered or		
	For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.	☐ Yes ☐ No	requirements differ. Conducted soil observation(s) (A Two previous verifications (Attact Not applicable (Holding tank(s), not Unable to verify (See Comments/E Other (See Comments/Explanation)	h boring logs) o drainfield) Explanation)	
	Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	⊠ Yes □ No	Comments/Explanation: Reviewed previous compliance insp Reviewed design and permit records		
	Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*				
	"Experimental", "Other", or "Performance"	☐ Yes ☐ No	Indicate depths of elevations		
	systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)		A. Bottom of distribution media	See Attached Boring Log(s)	
	Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.		B. Periodically saturated soil/bedrock C. System separation		
	Any "no" answer above indicates t	he system is	D. Required compliance separation*		
5.	Any "no" answer above indicates the system is Failing to Protect Groundwater. *May be reduced up to 15 percent if allowed by Local Ordinance. Operating Permit and Nitrogen BMP* – Compliance component #5 of 5 Not applicable				
'·	Is the system operated under an Operating Per		e component #5 of 5 ☑ Not appl □ No If "yes", A below is required	ICable	
	Is the system required to employ a Nitrogen BM		☐ No If "yes", B below is required		
	BMP=Best Management Practice(s) specific		•		
	If the answer to both questions is "no",	this section does	s not need to be completed.		
	Compliance criteria		·		
	a. Operating Permit number:				
	Have the Operating Permit requirements been met?		☐ Yes ☐ No		
	b. Is the required nitrogen BMP in place and	? ☐ Yes ☐ No			
	Any "no" answer indicates Noncompliance.				

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 wq-wwists4-31 • 1/24/12 Page 3 of 3

Inspect Minnesota & Midwest Soil Testing Subsurface Sewage Treatment System Owner/Property Information


This information will be used for the purpose of conducting an MPCA Compliance Inspection.

Date of Inspection: September 30, 2019	Time: 9:15 AM			
•				
Property Address: 16780 Jeffrey Ave N, Hugo, MN	Zip: 55038			
Property Owner: Joan Benner	Phone: 651-295-0618			
Tank(s) Tank(s)Material Soil Treatment System Septic 2 Fiberglass Scok trench Aerobic Plastic Gravelless trench Lift Metal Chamber trench Holding Concrete Seepage bed Other: Block Mound Other At-grade	Other Alternative system Experimental system Cesspool system Other system			
Are the tank maintenance covers accessible? ⊠ Yes ☐ No *If no	o, proper maintenance must be			
performed through the maintenance holes. Maintenance hole cover				
the ground surface to facilitate access and proper maintenance of th				
Year house built: 1975 Year septic installed: 1989/2007 Ta	ank size (gals.): 2-1000			
How long has seller owned the property? Number of resi				
Number of bedrooms? 4 Are all floors drained by gra				
Garbage disposal? N Whirlpool bath? Y				
More than one system (laundry, etc.)? N				
Does this property have any footing drain tiles connected to the sep	tic system? N			
Are any buildings on this property such as garages or out-buildings connected to this system? N				
Are there any additional systems on this property serving other buil	dings? N			
Location of septic system on lot? Tanks - North Side, Drainfield - E	East Side			
	well a deep well? Y			
Have you ever experienced any problems with the system such as: t surfacing of sewage onto the ground, septic tank overflowing, etc.; to the system? If yes, explain:				
When was the system last pumped? 2018 Name of pumper: Smilie's Sewer Service				
How often pumped in previous years? Is system on a monitoring plan? N				
Have you received notices from any government agency concerning this system? N				
Is your property located in a shoreland management area? N				
Do you have any additional information that should be given to the	new owner? N			
I hereby certify that the above information is correct to the best of my knowledge. considered "non-compliant/failing" per MPCA rules, that the inspector must by local government unit within 15 days of the date of inspection completion. I also	aw submit a copy of this report to the			

Owner/Occupant: Date:

this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection

by Inspect Minnesota and Midwest Soil Testing.



Log Of Soil Borings

Location of Project: 16780 Jeffrey Ave N, Hugo, MN 55038					
Borings Made By: Inspect Minnesota		Date:	6/6/11		
	Auger Used:	Bucket/P.H. Digger			USDA
В	oring Number:	1		Boring Number:	
Surface	Same ground	surface as drainfield	Surface		
Elevation of	f at east side	e of east drainfield	Elevation	of	
Boring		trench	Boring		
Depth In	Soils E	ncountered	Depth In	Soils Er	ncountered
Inches 0-6	7 5VD 2	5/2 Silt Loam	Inches		
6-20		4 Sandy Loam			
20-46	7.5YR 4/4	Clay Loam With			
46.66		l & Cobbles			
46-66 66-80		4 Sandy Loam 4 Loamy Sand			
	713110 17	T Louiny June			
80" D	epth To End Of B	oring Or Redox		Depth To End Of Bo	oring Or Redox
Same El	levation Of Boring	g Relative To System		Elevation Of Boring	Relative To System
-40" Depth To Bottom Of System			Depth To Bottom C	of System	
≥40" O	f Separation			Of Separation	
_	nd Of Bosing At-	80"		End Of Boring At-	
	nd Of Boring At:			End Of Boring At:	
Redox Present At: None Standing Water Present At: None		Redox Present At: Standing Water Present At:			
Standing W	rater Present At:	None	Standing	water Present At:	

Bottom	Of Distribut	ion Medium At:	40	Inches
DULLUIII	OI DISHIDUL	ion riculum At.	40	HICHES

DATE 6-7- 2007

8 of-10	
---------	--

TOP TOP SOIL LOAM LOAM TOP SOIL BROWN BROWN TISTER 3/4	OLE #6
TOP SOIL SOIL CLASSIFICATION TOP SOIL BROWN BROWN TOP SOIL	· -
T LOAM LOAM T BROWN TOP SOIL T	·
BROWN BROWN TOFY 3/4	
BROWN BROWN TO TONK 3/4	
15 KOWM 1 15 KOWN 1 17,5 YR 3/4 1	
+ LOAMY + LOAMY + BROWN LOAMY	
2 + SAND + SAND + GAND +	
T T T T T T T T T T T T T T T T T T T	
+ REDDISH BROWN	•
$\frac{1}{2.5} \times \frac{CLAY}{R} \times \frac{1}{5.14}$. ·
BROWN SAMP	
+ REDDISH + 7.5YR 414	
4 - Republic	• .
+ REVVISA + SAMON + + + + + + +	
T BROWN T (LAN)	
5 + SANDY + + + + + + + + + + + + + + + + + + +	
+ + + + + +	
6 Rocks T	
BROWN SAND STOP	
<u>+ 571P</u> + + +	
T ON 6'B" T ON 6' T	•
* <u>+</u> <u>+</u> <u>+</u> <u>+</u> <u>+</u>	
+ + + + + + +	
<u>, †</u> † † † † † †	
	-
<u>, †</u> + + + + +	
+	

DISCLAIMER

Brian L. Humpal, Inc. dba. Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems

Non-transferable

Business License

Inspect Minnesota, Midwest Soil Testing

License # L2896

License Expires: 12/22/2019

Issued: 11/20/2018

Specialty Area(s):

Installer
Maintainer
Service Provider
Advanced Designer
Advanced Inspector

Designated Certified Individual(s):

Cert #	Name	Certification Expires:
C9633	Anthony P Scully	3/5/2020
	Installer, Designer (Apprentice)	
C5342	Brian L Humpal	10/15/2023
	Installer, Maintainer, Serv Prov, Adv	Designer, Adv Inspector
C9852	Christopher R Uebe	3/4/2021
	Designer, Inspector	



520 Lafayette Road North St. Paul, Minnesota 55155-4194 Mich Haig

Nick Haig, Supervisor Certification and Training Unit