Inspect Minnesota & Midwest Soil Testing

P.O. Box 383 Hugo, MN 55038

Brian Humpal

651-492-7550/Brian@midwestsoiltesting.com

MPCA Licensed Designer & Inspector

SUBSURFACE SEWAGE TREATMENT SYSTEM COMPLIANCE REPORT

Inspection Address: 9440 239th St N, Forest Lake, MN 55025

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this septic system, and have reviewed the original design/permit records, along with a previous compliance inspection from 2014, which were on file at Washington County. This very old system consists of a pre-cast septic tank, a "bull valve", and two separate rock trench drainfields (one drainfield was installed in 1973 and the other was installed 1987). The 1973 drainfield should be disconnected if the system is to remain in place.

My inspection indicates that this system is presently "non-compliant" in accordance with MPCA rules 7080.1500 Subp.4(B)(E) because of the lack of the required two foot separation between the bottom of the drainfield and seasonally saturated soils. Washington County issued sewage treatment permit #4498 for the installation of this septic system.

In accordance with MPCA rules, I am sending a copy of this complete report to Washington County. I cannot officially speak on behalf of the County relative to the upgrade requirements of these non-compliant systems. Please contact Washington County Environmental Specialist, Mr. Chris LeClair (651-430-4052), to verify the County's position.

Please advise buyer, agents, lender, etc. to contact me should they have any questions regarding this system.

Brian Humpal Brian Humpal



St. Paul, MN 55155-4194

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

		27	
	esults based on Minnesota Pollution Control Agency (MPCA) forms – additional local requirements may also apply.	For local tracking purpose	es:
Submit completed form t within 15 days	o Local Unit of Government (LUG) and system owner		
System Status			
System status on d	ate (mm/dd/yyyy): <u>12/12/2016</u>		
(Valid for 3 years	<u>-</u>	npliant – Notice of No rade Requirements on page	-
☐ Impact on Pub☐ Other Complia☐ Tank Integrity☐ Other Complia☐ Soil Separation	Incompliance (check all applicable) Incompliance (component #1) – Imminent threat ince Conditions (Compliance Component #3) – Imminent the (Compliance Component #2) – Failing to protect groundwance Conditions (Compliance Component #3) – Failing to protect groundwant (Compliance Component #4) – Failing to protect groundwant (Compliance Component #4) – Failing to protect groundwant (Compliance Component #4)	reat to public health and saf ter otect groundwater ater	ety
Property Information	on Parcel ID# or Sec/Twp/Rar	ge:	
Property address: 9440 2	239 th St N, Forest Lake, MN 55025 Reason	or inspection: Property S	ale
Property owner:Jeremy or	Schwieger Owner's	phone: 612-369-6049	
Owner's representative:	Represe	ntative phone:	
Local regulatory authority:		ry authority phone: 651-4	
Brief system description:	This very old system consists of a pre-cast septic tank, a drainfields (one drainfield was installed in 1973 and the o		e rock trench
Comments or recommenda	ations:		
Certification			
determination of future sys	necessary information has been gathered to determine the tem performance has been nor can be made due to unknot em, inadequate maintenance, or future water usage.		
Inspector name: Brian H	lumpal Certifica	ion number: L5342	
		nse number: L2896	
Inspector signature:	Brian Humpal Ph	one number: 651-492-755	0
-	ly Required Attachments		
Soil boring logs		local ordinance	

☑ Other information (list): Report Summary, Property Information, Disclaimer, License

1.	Impact on Public Health - Compliance component #1 of 5						
	Sy gro	estem discharge sewage to the bund surface. Instem discharge sewage to drain tile surface waters. Instem cause sewage backup into welling or establishment. In y "yes" answer above indicates of Imminent Threat to Public Heal of Imminent Sexplanation: one of the above found.		Verification method(s): Searched for surface outlet Searched for seeping in yard/backup in home Excessive ponding in soil system/D-boxes Homeowner testimony (See Comments/Explanation) "Black soil" above soil dispersal system System requires "emergency" pumping Performed dye test Unable to verify (See Comments/Explanation) Other methods not listed (See Comments/Explanation)			
2.	Ta	ank Integrity — Compliance com	nponent #2 of 5				
3.	Sy ce: Se con Se de If y	estem consists of a seepage pit, aspool, drywell, or leaching pit. sepage pits meeting 7080.2550 may be impliant if allowed in local ordinance. swage tank(s) leak below their signed operating depth. yes, which sewage tank(s) leaks: ny "yes" answer above indicates and its Failing to Protect Green is Failing to Protect Green is were allowed in local ordinance. The protect Green is the protect of the prote	oundwater. paffles and tank walls O				
	a. Maintenance hole covers are damaged, cracked, unsecured, or appear to structurally unsound. ☐ Yes* ☒ No ☐ Unknown						
	 b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety. ☐ Yes* ☐ No ☐ Unknown *System is an imminent threat to public health and safety Explain: c. System is non-protective of ground water for other conditions as determined by inspector ☐ Yes* ☐ No 						
	*System is failing to protect groundwater Explain:						

Property address: 9440 239th St N, Forest Lake, MN 55025

Inspector initials/Date: 12/15/2016

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • 3 off9TY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

Date of installation: 1987	Unkn	iown	٧	erification method(s):		
Shoreland/Wellhead protection/Food Beverage Lodging?	☐ Yes	⊠ No		Soil observation does not expire. F	ependent parties are sufficient,	
Compliance criteria:				bservations by two independent p nless site conditions have been a		
For systems built prior to April 1, 1996, and	☐ Yes	⊠ No	re	equirements differ.		
not located in Shoreland or Wellhead				Conducted soil observation(s)		
Protection Area or not serving a food, beverage or lodging establishment:			L	Two previous verifications (Atta		
Drainfield has at least a two-foot vertical				☐ Not applicable (Holding tank(s), no drainfield)☐ Unable to verify (See Comments/Explanation)		
separation distance from periodically saturated soil or bedrock.				Other (See Comments/Explanation	n)	
Non-performance systems built April 1,	☐ Yes [No No	C	Comments/Explanation:		
1996, or later or for non-performance systems located in Shoreland or Wellhead				eviewed design and permit record	ds.	
Protection Areas or serving a food, beverage, or lodging establishment:			R	Reviewed previous compliance from	m 2014.	
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*						
"Experimental", "Other", or "Performance"	☐ Yes	П No	- In	ndicate depths of elevations		
systems built under pre-2008 Rules; Type IV				Tarouto aoptirio di diovationo	See Attached	
or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)			_A	. Bottom of distribution media	Boring Log(s)	
Drainfield meets the designed vertical			В	. Periodically saturated soil/bedrock		
separation distance from periodically saturated soil or bedrock.			_ <u>C</u>	. System separation		
			D	. Required compliance separation*		
Any "no" answer above indicates to Failing to Protect Groundwater.	he syste	em is		May be reduced up to 15 percent Ordinance.	if allowed by Local	
Operating Permit and Nitrogen B	MD* ←	ompliano	0.00m	ponent #5 of 5 🔀 Not app	olicable	
Is the system operated under an Operating Peri				If "yes", A below is required	nicable	
ls the system required to employ a Nitrogen BM		☐ Yes		-		
BMP=Best Management Practice(s) specifi				ii yes , b below is required		
If the answer to both questions is "no",		-	•	need to be completed.		
•						
Compliance criteria a. Operating Permit number:						
Have the Operating Permit requirements to	peen met?	·		☐ Yes ☐ No		
b. Is the required nitrogen BMP in place and properly functioning?				+		

Property address: 9440 239th St N, Forest Lake, MN 55025

Inspector initials/Date: 12/15/2016

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • 4 of 19TY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 3 of 3


Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas,

Inspect Minnesota & Midwest Soil Testing

Subsurface Sewage Treatment System Owner/Property Information This information will be used for the purpose of conducting an MPCA Compliance Inspection.

Date of Inspection: December 12, 2016	Time: 10:00 AM				
Property Address: 9440 239 th St N, Forest Lake, MN	Zip: 55025				
Property Owner: Jeremy Schwieger	Phone: 612-369-6049				
Tank(s) Tank(s)Material Soil Treatment System Septic 1 Fiberglass Rock trench Aerobic Plastic Gravelless trench Lift Metal Chamber trench Holding Concrete Seepage bed Other: Block Mound Other At-grade	Other Alternative system Experimental system Cesspool system Other system				
Are the tank maintenance covers accessible? Yes No *If no, proper maintenance must be performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system.					
1	Γank size (gals.): 1200				
	sidents in home?				
Number of bedrooms? 4 Are all floors drained by g					
Garbage disposal? Whirlpool bath?					
More than one system (laundry, etc.)?					
Does this property have any footing drain tiles connected to the se	ptic system?				
Are any buildings on this property such as garages or out-buildings connected to this system?					
Are there any additional systems on this property serving other buildings?					
Location of septic system on lot? South Side					
	e well a deep well? Y				
Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? If yes, explain:					
When was the system last pumped? Name of pum	1				
How often pumped in previous years? Is system on a monitoring plan?					
Have you received notices from any government agency concerning this system?					
Is your property located in a shoreland management area? N					
Do you have any additional information that should be given to the new owner?					
I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing.					
Owner/Occupant:	Date:				



Log Of Soil Borings

Location of Project: 9440 239th St N, Forest Lake, MN 55025					
Borings Made By: Inspect Minnesota		Date:		12/12/16	
Auger Used: Hand/Bucket		Classification System:		USDA	
	Boring Number:	1	Boring Number:		
Surface	Samo grou	ınd surface as last	Surface	!	
Elevation	MEI -	nfield trench	Elevation	of	
Boring	uran	illeid treffcff	Boring		
Depth In	Soils F	ncountered	Depth In Soils Encou		ncountered
Inches		-	Inches	20110 21	<u>icountercu</u>
0-28		/3 Loamy Sand			
28-34 34-48		4 Loam (Moist) oam (Moist) With			
34-40		10YR 6/2 Redox			
48-61		Clay Loam With			
		10YR 6/3 Redox			
34" Depth To End Of Boring Or Redox			Depth To End Of Bo	oring Or Redox	
				•	Relative To System
Same Elevation Of Boring Relative To System				•	
-34" Depth To Bottom Of Distribution Media =0" Of Separation			Of Separation	of Distribution Media	
-o joi Separation			or Separation		
End Of Boring At: 61"			End Of Boring At:		
Redox Present At: 34"				Redox Present At:	
Standing Water Present At: None		Standing	Water Present At:		

Bottom Of Distribution Medium At: 34 Inches

DISCLAIMER

Brian L. Humpal, Inc. dba. Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems



Business License

Inspect Minnesota, Midwest Soil Testing

License # L2896

License Expires: 12/22/2017

Issued: 11/29/2016

Specialty Area(s):

Installer
Maintainer
Service Provider
Advanced Designer
Advanced Inspector

Designated Certified Individual(s):

Cert #

Name

Certification Expires:

C5342

Brian L Humpal

10/15/2017

Installer, Maintainer, Serv Prov, Adv Designer, Adv Inspector

C9852

Christopher R Uebe

3/4/2018

Designer, Inspector



St. Paul, Minnesota 55155-4194

Steven Giddings, Manager

Prevention and Solid Waste Management Section