

520 Lafayette Road North St. Paul, MN 55155-4194

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

structions: Inspection results based on Minnesota Pollution Control Agency (MPCA) equirements and attached forms – additional local requirements may also apply.	For local tracking purposes:
ubmit completed form to Local Unit of Government (LUG) and system owner ithin 15 days	
ystem Status	
System status on date (mm/dd/yyyy): 11/4/2015	
	mpliant – Notice of Noncompliance grade Requirements on page 3)
Reason(s) for noncompliance (check all applicable)	
Impact on Public Health (Compliance Component #1) - Imminent threat	to public health and safety
Other Compliance Conditions (Compliance Component #3) - Imminent to	hreat to public health and safety
☐ Tank Integrity (Compliance Component #2) - Failing to protect groundw	ater
☐ Other Compliance Conditions (Compliance Component #3) – Failing to p	rotect groundwater
Soil Separation (Compliance Component #4) - Falling to protect ground	water
Operating permit/monitoring plan requirements (Compliance Component	#3) — Noncompliant
	22 024 20 04 0009
Property address: 11755 126th ST N., Stillwater, MN Reason	nge: 32.031.20.24.0008 n for inspection: Property Transfer s phone: 651-260-92225
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Or	for inspection: Property Transfer s phone: 651-260-92225
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Dr Owner's representative: Brad Torgerson Representative:	for inspection: Property Transfer s phone: 651-260-92225 entative phone: 612-987-5963
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Owner's Dwner's representative: Brad Torgerson Repres Local regulatory authority: Washington County Regula	of for inspection: Property Transfer s phone: 651-260-92225 entative phone: 612-987-5963 tory authority phone:
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Dr Dwner's representative: Brad Torgerson Repres Local regulatory authority: Washington County Regula Brief system description: 2000 split solid septic tank and four gravity flow trenches	n for inspection: Property Transfer s phone: 651-260-92225 entative phone: 612-987-5963 tory authority phone:
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Owner's Dwner's representative: Brad Torgerson Repres Local regulatory authority: Washington County Regula	of for inspection: Property Transfer s phone: 651-260-92225 entative phone: 612-987-5963 tory authority phone:
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Dr Dwner's representative: Brad Torgerson Repres Local regulatory authority: Washington County Regula Brief system description: 2000 split solid septic tank and four gravity flow trenches	of for inspection: Property Transfer s phone: 651-260-92225 entative phone: 612-987-5963 tory authority phone:
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Dr Dwner's representative: Brad Torgerson Repres Local regulatory authority: Washington County Regula Brief system description: 2000 split solid septic tank and four gravity flow trenches	of for inspection: Property Transfer s phone: 651-260-92225 entative phone: 612-987-5963 tory authority phone:
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Dr Dwner's representative: Brad Torgerson Repres Local regulatory authority: Washington County Regula Brief system description: 2000 split solid septic tank and four gravity flow trenches	entative phone: 612-987-5963 hor inspection: Property Transfer property Transfer 612-987-5963 hor authority phone:
Property address:11755 126th ST N., Stillwater, MN Reason Property owner:Bank of America c/o Steve Ritt Owner' Dwner's representative:Brad Torgerson Representative:Washington County Regula Brief system description:2000 split solid septic tank and four gravity flow trenches Comments or recommendations:	of for inspection: Property Transfer s phone: 651-260-92225 entative phone: 612-987-5963 tory authority phone:
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner Dwner's representative: Brad Torgerson Repres Local regulatory authority: Washington County Regula Brief system description: 2000 split solid septic tank and four gravity flow trenches Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknown.	e compliance status of this system. No
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Dwner's representative: Brad Torgerson Representative: Washington County Regula Brief system description: 2000 split solid septic tank and four gravity flow trenches Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknown possible abuse of the system, inadequate maintenance, or future water usage.	e compliance status of this system. No
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Dwner's representative: Brad Torgerson Repres Local regulatory authority: Washington County Regula Brief system description: 2000 split solid septic tank and four gravity flow trenches Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unkn possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Jeff Fertig Certific	e compliance status of this system. No own conditions during system construction,
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Dwner's representative: Brad Torgerson Repres Local regulatory authority: Washington County Regula Brief system description: 2000 split solid septic tank and four gravity flow trenches Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknown possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Jeff Fertig Certific Sunrise Septic Services Lice	e compliance status of this system. No own conditions during system construction,
Property address:	e compliance status of this system. No own conditions during system construction, cation number: 2942 cense number: 2299
Property address: 11755 126th ST N., Stillwater, MN Reason Property owner: Bank of America c/o Steve Ritt Owner' Owner's representative: Brad Torgerson Representative: Washington County Regulation Strief system description: 2000 split solid septic tank and four gravity flow trenches Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknipossible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Jeff Fertig Certific Sunrise Septic Services Lice Inspector signature: A Necessary or Locally Required Attachments	entative phone: 612-987-5963 tory authority phone: 612-987-5963 entative compliance status of this system. No own conditions during system construction, eation number: 2942 ense number: 2299

ropert <u>y</u>	address: 11755 126th ST N., Stillw	ater, MN	Inspector initials/Date: 11/4/2015 447				
. Im	npact on Public Health – Cor	mpliance component	#1 of 5				
Co	ompliance criteria:		Verification method(s):				
	stem discharge sewage to the ound surface.	☐ Yes ⊠ No	 ✓ Searched for surface outlet ✓ Searched for seeping in yard/backup in home 				
	stem discharge sewage to drain tile surface waters.	☐ Yes ⊠ No	 ☐ Excessive ponding in soil system/D-boxes ☐ Homeowner testimony (See Comments/Explanation) ☐ "Black soil" above soil dispersal system 				
	stem cause sewage backup into velling or establishment	☐ Yes ⊠ No	System requires "emergency" pumping Performed dye test				
	ny "yes" answer above indicate n Imminent Threat to Public Hea		☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation				
Co	omments/Explanation:						
	ank Integrity – Compliance cor	mponent #2 of 5	Verification models added:				
<u>C</u>	ompliance criteria:		Verification method(s):				
	ystem consists of a seepage pit, esspool, drywell, or leaching pit.	☐ Yes ☒ No	☐ Probed tank(s) bottom☐ Examined construction records				
	eepage pits meeting 7080.2550 may be impliant if allowed in local ordinance.		 Examined Tank Integrity Form (Altach) Observed liquid level below operating depth 				
	ewage tank(s) leak below their esigned operating depth.	☐ Yes ☒ No	 ☐ Examined empty (pumped) tanks(s) ☐ Probed outside tank(s) for "black soil" 				
lf	yes, which sewage tank(s) leaks:		Unable to verify (See Comments/Explanation)				
	ny "yes" answer above indic ystem is Failing to Protect Gi		☑ Other methods not listed (See Comments/Explanation				
pl	omments/Explanation: umper testimony. Hassle Free Septic lace. No cracks or leaks were detecte	id.	1/5/2015. Reported normal operating levels and all baffles in specific properties and all baffles in specific properties.				
a,	Maintenance hole covers are damage	ed, cracked, unsecured,	or appear to structurally unsound. ☐ Yes* ☒ No ☐ Unknow				
þ.	Other issues (electrical hazards, etc.) to *System is an imminent threat to p		sely impact public health or safety. ☐ Yes* ☒ No ☐ Unknow V				
	Explain:						
C.	System is non-protective of ground water for other conditions as determined by inspector Yes* No *System is failing to protect groundwater						
	Explain:						

4.	Soil Separation - Compliance compor	ent #4 of 5				
	Date of installation: 1999	Unknown	Verification method(s):			
	Shoreland/Wellhead protection/Food Beverage Lodging?	☐ Yes ⊠ No	Soil observation does not expire. Previous soil observations by two independent parties are sufficient.			
	Compliance criteria:		unless site conditions have been altered or local requirements differ. Conducted soil observation(s) (Attach boring logs) Two previous verifications (Attach boring logs) Not applicable (Holding tank(s), no drainfield)			
	For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	☐ Yes. ☐ No				
	Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.		☐ Unable to verify (See Comments/Explanation) ☐ Other (See Comments/Explanation)			
	Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	⊠ Yes □ No	Comments/Explanation:			
	Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*					
	"Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)	☐ Yes ☐ No	Indicate depths of elevations			
			A. Bottom of distribution media 32" B. Periodically saturated soil/bedrock >68"			
	Drainfield meets the designed vertical		C. System separation 36"			
S	separation distance from periodically saturated soil or bedrock.		D. Required compliance separation* 34.8 30			
	Any "no" answer above indicates t Failing to Protect Groundwater.	*May be reduced up to 15 percent if allowed by Loc Ordinance.				
5.	Operating Permit and Nitrogen B	MP* – Compliar	nce component #5 of 5 🛛 Not applicable			
	is the system operated under an Operating Pe	rmit? ☐ Yes	☐ No. If "yes", A below is required			
îniş vî	Is the system required to employ a Nitrogen BI BMP=Best Management Practice(s) speci	viP? ☐ Yes	s ☐ No If "yes", B below is required design			
	If the answer to both questions is "no"	, this section do	es not need to be completed.			
	Compliance criteria					
	a. Operating Permit number:		El You El No			
		☐ Yes ☐ No				

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

SUNRISE SEPTIC SERVICES, INC.

Jeffrey Fertig
Licensed and Bonded, PCA Certified #2942
12180 Saint Croix Trail, North Branch, MN 55056
(651) 253-2969/jafertig@gmail.com

ON-SITE SEPTIC SYSTEM CONDITION REPORT

DATE:

PID#:

November 4, 2015

OWNER: ADDRESS: Bank of America c/o Steve Ritt 11755 126th ST N., Stillwater, MN

32.031.20.24.0008

REPORT SUMMARY:

At the request of the seller of this property, I have completed an MPCA Compliance Inspection for the septic system located on the parcel. It is my opinion that this onsite sewage treatment system is compliant. The system consists of a 2000 split solid septic tank and four gravity flow trenches. Predicated on my inspection of the system it is my opinion that this system presently meets MPCA minimum compliance inspection requirements.

Redoximorphic features were not found in a 68 inch soil boring. The bottom of the rock bed was essentially 32" below grade rendering the system with at least 36" inches of separation as required by code. The septic and lift tanks appeared to be watertight and all baffles were in place and functioning properly. Water levels were found to be at normal operating levels. Hapsle Free Septic pumped the septic and lift tanks.

Sincerely,

Jeffrey A. Fertig

Sunrise Septic Services, Inc.

NOTE: This report is not complete without the inclusion/attachment of the respective MPCA Septic System Compliance Inspection form, which consists of three separate pages, a site diagram, a soil boring log(s) and a Sunrise Septic Services, Inc. disclaimer sheet. This report/inspection is being done for only the seller and the buyer of this property. There is no contract between Sunrise Septic Services and any other party except the seller/buyer. Liability to Sunrise Septic Services Inc. is limited to the cost of this inspection.

Sunrise Septic Services DISCLAIMER SHEET

Relative to Septic System Compliance Inspections:

- 1. This inspection/report is being performed for only the seller/owner or of the property on which the septic system is located; there is no contract between Sunrise Septic Services, Inc. and any other party except the seller/owner unless otherwise noted. In such case that the buyer of the property is paying for the inspection, the contract is between only the buyer of the property and Sunrise Septic Services, Inc., there is no contract with any other party unless otherwise noted. Liability to Sunrise Septic Services Inc. is limited to the cost of this inspection.
- 2. Sunrise Septic Services, Inc. has not been retained to warrant, guarantee, or certify the proper functioning of the system for any period of time beyond the date of inspection or the future. Because of the numerous factors (usage, maintenance, tank pumping, soil characteristics, previous failures, etc.) which may affect the proper operation of a septic system, as well as the inability of Sunrise Septic Services, Inc. to supervise or monitor the use or maintenance of the system, the report shall not be construed as a warranty by Sunrise Septic Services, Inc. that the system will function properly for any particular person for any period of time.
- 3. Minimum Compliance Inspection requirements relative to this inspection and this report include only verification that the septic system has a water tight septic tank(s) and lift tank, the required separation from the bottom of the drainfield/mound distribution medium and saturated soils, no back-ups of sewage into the dwelling, and no discharge of sewage/effluent onto the ground surface or surface water (lakes, streams, etc.) Sunrise Septic Services, Inc. does not inspect basement ejector pumps or exterior lift tank pumps as they are considered to be a "maintenance item". Sewage backup verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the dwelling prior to inspection Sunrise Septic Services, Inc. cannot guarantee that the information given to them by the last occupants of the dwelling prior to inspection relative to backups or failure is accurate. Some persons may attempt to hide or conceal signs of previous back-ups.
- 4. Certification of this system does not warranty future use beyond the date of the inspection. Any system, old or new, can be hydraulically overloaded as a result of more people moving into the house than were previously occupying the house, improper maintenance and/or heavy usage, tree roots, freezing conditions, surface drainage problems, or the system can simply stop working because of its age. The average life expectancy of a properly maintained septic system is twenty five years.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the septic system, a Compliance Inspection is strictly for the purpose of determining if the septic system is polluting the environment at the date and time the inspection is performed. This inspection is not intended to determine if the septic system was originally designed or installed to past or present MPCA or Local Unit of Government code requirements.
- 6. WINTER WORK: Client (person paying for inspection) understands that inspections conducted during winter weather (approximately November 1st through April 1st) are more difficult to perform because of the possible snow cover and ground frost. Septic system components such as tanks, tank covers, drop boxes, drop box covers and soil treatment areas are more difficult to locate because of snow cover and ground frost. Soil borings and locating drainfields are more difficult to perform because of ground frost. Sunrise Septic Services, Inc. will attempt to use the same level of standards when performing winter work as when performing non-winter work. However, the client understands that because of aforementioned considerations, the same level of standards may not be possible.

Respectfully.

Jeffrey A. Fertig Inspector/Owner Soil Boring Log

→	@3	1.0						_
Depth of System or			hes		1	Flood Plain	: Yes	(No)
Depth to Restrictive	Layer >4	inc	hes	1		Shoreland	: Yes	No
Type of Observation	a: Probe	Pit	Boring	Well Hea	ad Protect	tion area:	Yes	NO
General Soil Textur	e: Sand	Loam	Clay				2 - 20	٣
Draina		Problen			/			
- A TELLER	g c. 000a	Tigoton	us.	Well Info	: I	ocation	Fron	k
						Depth	>50	•
	Site Dray	ving			Depth	Texture	Color	Structure
					0-8"	fine Sund	104K	Blocky Platy Prismatic
	ge A	Hacl	led		8-24"	Sendy Clay Loam	104R 414	Blocky Platy Prismatic
5	'sl	. \$.			24-66	SIND	7.54ª 5/4	Błocky Platy Prismatic
							·	Blocky
								Platy Prismatic
				<u> </u>	to de	Additiona	al Notes:	ATISHALIA
						,		
Inspection Perform	ned by:	Sunrise Se	ptic Service	<u>s</u> 444	Registrat	ilon Number		299
Site Address Legal Description	North Star Ban 1755 126TH S CELLER FARM 32.031.20.24.0	T N, Stillwa			<u>_</u> .	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	······································

