

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 10		for Maintenance: _		10.011:	1 am 14 3 C	
Property Address: 1433	3 136 TV 53		roperty Owner's Na	me: NCK	10010(=	
Municipality: <u>STULL</u>	MYCR ZIP: 550	Property Ider	tification Number:			
Maintenance Permit No:	5265a 88911	Maintainer Name an	d License No. <u>Smili</u>	e's Sewer Service/L	2428	
						
Maintenance	Performed	Tänk Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped Sludge and scum measured			Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in			
				Scum Level in Tank evel X 100		
Do tanks need to be pumped?				nks must be pumped		
☐ Yes ☐ No (if no p	rovide measurements)	<u> </u>				
1. Access used to remove	septage: Maintena	nce Hole \square Other (e	enter authorization co	ode)		
 Were all covers securely replaced? Yes \(\subseteq \) No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? \(\subseteq \) Yes \(\subseteq \) No 						
3. Is there evidence of ta	ink leakage from a sej	otic, holding, pretr			erating depth or	
3. Is there evidence of ta	ink leakage from a sej	otic, holding, pretr			erating depth or	
3. Is there evidence of ta evidence of damaged	nk leakage from a sep , cracked, or structur	otic, holding, pretrally unsound main	tenance hole cove	rs? 🗌 Yes 📈	erating depth or	
3. Is there evidence of ta evidence of damaged	nk leakage from a sep , cracked, or structur Tank	otic, holding, pretr ally unsound main Leaking Out	tenance hole cove	rs?	erating depth or	
3. Is there evidence of ta evidence of damaged Sep	nk leakage from a seg , cracked, or structur Tank otic/Holding Tank #1	Leaking Out Yes Aloo	Leaking In Yes ANO	Cover Damage Yes No	erating depth or	
3. Is there evidence of ta evidence of damaged Sep Pre	Tank otic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes No Yes No	Cover Damage Yes ANO Yes No	erating depth or	
3. Is there evidence of ta evidence of damaged Sep Pre	Tank Tank Otic/Holding Tank #1 otic/Holding Tank #2	Leaking Out Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No	erating depth or	
3. Is there evidence of ta evidence of damaged Sep Pre Pu 4. How many gallons of s Tank #1 200 ga	Tank Tank Tank Otic/Holding Tank #1 Otic/Holding Tank #2 etreatment Tank mp Tank eeptage were removed	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	gal	
3. Is there evidence of ta evidence of damaged Sep Pre Pu 4. How many gallons of s	Tank Tank Tank Otic/Holding Tank #1 Otic/Holding Tank #2 etreatment Tank mp Tank eeptage were removed	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	gal	
3. Is there evidence of ta evidence of damaged Sep Pre Pu 4. How many gallons of s Tank #1 200 ga	Tank Tank Tank Otic/Holding Tank #1 Otic/Holding Tank #2 etreatment Tank mp Tank eeptage were removed	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	gal	

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073 License# 2428 P: 651-433-3934