

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Property Address: 18280 Henna Au	<u>د</u> P	roperty Owner's Na	ame: <u>ぴょ ブ</u>	ensco	
Municipality: Hago ZIP: 550	25 Property Ider	tification Number:			
Waintenance Permit No: 43921 2 8426	——— . Maintainer Name an	d License No. Smili	e's Sewer Service/	 L2428	
waliteriance Fermit No. 7 7 7 5 7 5 7 7 7 7 7 7 7 7 7 7 7 7 7	nameanor rame an	<u> </u>			
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	s NOT pumped)	
Tank(s) Pumped	Liquid Level of 1	Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100				
Do tanks need to be pumped?	Sludge + Scum _	/ Liquid L	evel X 10 iks must be pumped	U d if 25% or greater	
Yes No (if no provide measurements)	- % studge & set	rai	ms mast be pamper	3 11 20% OF SECULO.	
1. Access used to remove septage: Maintena	nnce Hole Other (6	enter authorization co	ode)		
			· :		
2. Were all covers securely replaced? Ves	□ NO				
2. Is there evidence of tank leakage from a se	ntic, holding, preti	eatment or pump	tank below the op	erating depth or	
<ol><li>Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure</li></ol>	ptic, holding, pretr rally unsound main	eatment or pump tenance hole cove	tank below the opers? $\square$ Yes $\square$ No	erating depth or	
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure.  Tank	ptic, holding, pretically unsound main  Leaking Out	eatment or pump tenance hole cove Leaking In	tank below the opers?    Yes	erating depth or	
evidence of damaged, cracked, or structu	rally unsound main	tenance hole cove	rs? 🗌 Yes 🖰 No	erating depth or	
evidence of damaged, cracked, or structu	Leaking Out	Leaking In	Cover Damage	erating depth or	
evidence of damaged, cracked, or structure  Tank  Septic/Holding Tank #1	Leaking Out  Yes Ko	Leaking In  Yes No	Cover Damage  Yes No	erating depth or	
evidence of damaged, cracked, or structure  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2	Leaking Out  Yes No	Leaking In  Yes No  Yes No	Cover Damage  Yes No  Yes No	erating depth or	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out  Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No	erating depth or	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out  Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No	erating depth or	
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were remove  Tank #1 1200 gal Tank #2	Leaking Out  Yes No Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Yes No Yes No	gal	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  4. How many gallons of septage were remove	Leaking Out  Yes No Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Yes No Yes No	gal	
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were remove  Tank #1 1200 gal Tank #2	Leaking Out  Yes No Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Yes No Yes No	gal	

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934