

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 7/10/17 Reason for Maintenance: ROUTINE						
Property Address: 7420 PINE HURST RD Property Owner's Name: BRIAN KEENAN						
Municipality: PINE SPRING-SZIP: 55/15 Property Identification Number:						
Maintenance Permit I	No: <u>9 33880 691 4</u>	, Maintainer Name a	nd License No. Mey	er Sewer Service. In	 c./L915	
	0					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
 ✓ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements) 			Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in				
		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater				
		- // Studge & Se	um ra	nks must be pumpet	in 25% or greater	
1. Access used to re	move septage: Maintena	nce Hole Other	enter authorization c	ode)		
 Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes No 						
·						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
evidence of daili	aged, cracked, or structur	ally unsound main	tenance hole cove	ers?		
evidence of dail	aged, cracked, or structur	ally unsound main	tenance hole cove	Cover Damage		
evidence of dail	-	·		·		
Evidence of dail	Tank	Leaking Out	Leaking In	Cover Damage		
Evidence of dail	Tank Septic/Holding Tank #1	Leaking Out ☐ Yes ☐ No	Leaking In ☐ Yes ☐ No	Cover Damage ☐ Yes ☐ No		
Evidence of dail	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Yes No	Leaking In ☐ Yes ☐ No ☐ Yes ☐ No	Cover Damage Yes No Yes No		
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No		
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No		
4. How many gallons Tank #1_{250	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Pes No	gal	
4. How many gallons Tank #1 (25°) 5. Other information	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out Yes No Yes No Yes No Yes No gal Pretreatment	Leaking In Yes No Yes No Yes No Yes No tank ganducted, tank safe	Cover Damage Yes No Yes No Yes No Yes No Pump Tank ty concerns, or oth	gal	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162