

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 7/11/7 Reason	on for Maintenance:	ROUTIN	E		
Property Address: 7118 GRANADA	AVE S.	Property Owner's N	Name: MIKE	CHULTZ	
Municipality: <u>COTTAGE GROVE</u> ZIP: <u>55</u>					
Maintenance Permit No: <u>V.2750g6929</u>	Maintainer Name a	nd license No. Mex	ver Sewer Service Ir		
7 9 9 1	manifed Harrie a	ind Licerise No. Mey	er sewer service, il	IC./L915	
		ngananan angangan an	Three Marian		
Maintenance Performed			completed if tank	s NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
\square Yes \square No (if no provide measurements	s) = % studge & sc				
1. Access used to remove septage: Mainter	nance Hole (Cother 6	enter authorization c	nda)		
2. Were all covers securely replaced? X Yes	s I INo				
		reatment or pump itenance hole cove	tank below the opers?	erating depth or	
		reatment or pump Itenance hole cove	tank below the opers? Cover Damage	erating depth or	
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu	eptic, holding, pret urally unsound main	·		erating depth or	
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu	eptic, holding, preturally unsound main	Leaking In	Cover Damage	erating depth or	
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu Tank Septic/Holding Tank #1	eptic, holding, preturally unsound main Leaking Out Yes Aho	Leaking In Yes No	Cover Damage Yes No	erating depth or	
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structular and sevidence of damaged, cracked, or structular and sevidence of damaged, cracked, or structular and sevidence of tank leakage from a second sevidence of	Leaking Out Yes No	Leaking In Yes No	Cover Damage Yes No Yes No	erating depth or	
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structular Tank Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No		
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure. Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were remove Tank #1 200 gal Tank #2 5. Other information: List any troubleshootin	Leaking Out Yes No Yes No Yes No Yes No gal Pretreatment	Leaking In Yes No Yes No Yes No Yes No tankg	Cover Damage Yes No Yes No Yes No Yes No Pump Tank ty concerns, or oth	gal	
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure. Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were remove Tank #1 200 gal Tank #2 5. Other information: List any troubleshootin	Leaking Out Yes No Yes No Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No tankg	Cover Damage Yes No Yes No Yes No Yes No Pump Tank ty concerns, or oth	gal	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162