

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 1/13/17 Reason for Maintenance: ROUTINE						
Property Address:	5770 Hestra		Property Owner's I		Haugen	
Municipality:	ZIP:530	942 Property Ide	entification Number	r:		
Maintenance Permit N	10: 13939p6934	 Maintainer Name a	nd License No. Mey	er Sewer Service. In	 c./L915	
	/				37 = 7 (5	
Maintena	nce Performed	Tank Mea	surement (must be	completed if tanks	s NOT pumped)	
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped?		II '	Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in				
			Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if	no provide measurements)			Was in particular	in 25% of greater	
1. Access used to ren	nove septage: Maintenar	nce Hole Other (enter authorization c	ode)		
2. Were all covers securely replaced? Yes No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
 3. Is there evidence 	of tank leakage from a sep	tic, holding, preti	reatment or pump	tank below the ope	erating depth or	
3. Is there evidence evidence of dama	of tank leakage from a sep aged, cracked, or structura	tic, holding, preti ally unsound main	reatment or pump Itenance hole cove	tank below the ope ers?	erating depth or	
3. Is there evidence evidence of dama	of tank leakage from a sep aged, cracked, or structura Tank	tic, holding, preti ally unsound main Leaking Out	reatment or pump itenance hole cove	tank below the ope ers? Cover Damage	erating depth or	
3. Is there evidence evidence of dama		***			erating depth or	
3. Is there evidence evidence of dama	Tank	Leaking Out	Leaking In	Cover Damage	erating depth or	
3. Is there evidence evidence of dama	Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Ves No	Cover Damage Ves No	erating depth or	
3. Is there evidence evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Yes No	Leaking In Yes No Yes No	Cover Damage Yes No Yes No	erating depth or	
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No	erating depth or	
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed?	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No		
4. How many gallons Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed? gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Pes No	gal	
4. How many gallons Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed?	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No tankg	Cover Damage Yes No Yes No Yes No Yes No Pes No	gal	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162