

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:						
Property Address: <u>91</u> 9			,	ama: Danisa	Ramick	
	·	•			Nemich_	
Municipality: <u>らすれい</u>		<u>08∂</u> Property Ide				
Maintenance Permit No:	: f6 3884 10001	Maintainer Name a	nd License No. <u>Smil</u>	<u>ie's Sewer Service</u>	/L2428	
Maintenand	ce Performed	Tank Meas	surement (must be	completed if tan	ks NOT pumped)	
☐ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped?		II '	Tank in		·	
			Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greate			
		= % Sludge & Sci				
Yes 🗌 No (if no	Yes No (if no provide measurements)				3	
1 . A	ove septage: Mainter	ange Hele Cother (ode)		
2. Were all covers secu 3. Is there evidence of	urely replaced? Yes	i □ No eptic, holding, preti	reatment or pump	tank below the op		
2. Were all covers secu 3. Is there evidence of	urely replaced? Yes	i □ No eptic, holding, preti	reatment or pump	tank below the op		
2. Were all covers secu 3. Is there evidence of evidence of damag	urely replaced? Yes tank leakage from a se ed, cracked, or structu	s □ No eptic, holding, preto urally unsound main	reatment or pump	tank below the opers?		
2. Were all covers secu 3. Is there evidence of evidence of damag	urely replaced? Yes tank leakage from a se ed, cracked, or structu Tank	No Pptic, holding, pretourally unsound main Leaking Out	reatment or pump itenance hole cove Leaking In	tank below the opers? Yes No		
2. Were all covers secu 3. Is there evidence of evidence of damag	tank leakage from a so ed, cracked, or structu Tank	Pos No Leaking Out	reatment or pump itenance hole cove Leaking In	tank below the opers?		
2. Were all covers secu 3. Is there evidence of evidence of damag	tank leakage from a second cracked, or structured. Tank Septic/Holding Tank #1 Septic/Holding Tank #2	No eptic, holding, pretoration in the properties of the pretoration in	reatment or pump itenance hole cove Leaking In Yes No Yes No	tank below the opers?		
2. Were all covers secu 3. Is there evidence of evidence of damag	Tank Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No	reatment or pump Itenance hole cove Leaking In Yes No Yes No Yes No	tank below the opers?		
2. Were all covers secu 3. Is there evidence of evidence of damag	tank leakage from a seed, cracked, or structured, cracked, or structured to the seed of th	No eptic, holding, pretigrally unsound main Leaking Out Yes No Yes No Yes No Yes No	reatment or pump Itenance hole cove Leaking In Yes No Yes No Yes No	tank below the opers?		
2. Were all covers secula. Is there evidence of evidence of damag	Tank Septic/Holding Tank #2 Pretreatment Tank	By Control of the con	reatment or pump itenance hole cove Leaking In Yes No Yes No Yes No Yes No	tank below the opers?		

Smilie's Sewer Service **PO BOX 100** Scandia, MN 55073 License# 2428 P: 651-433-3934