

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: ///9//7 Reason	for Maintenance:	Routine		
Property Address: 10120 Stillwat	erio Tane n.	Property Owner's N	lame: Steve	Kallevano
Municipality Lake Elmo ZIP: 550				1
Maintenance Permit No: <u>Q3622</u> n9170 M				
Maintenance Fermit No. 2000 M	allitallier Naille a	nd License No. Mey	er sewer service, in	C./L915
	1			
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of Tank in			
Sludge and scum measured	Lancas and the same of the sam		in Scum Level in Tank in	
Do tanks need to be pumped?		Sludge + Scum / Liquid Level _ = % Sludge & Scum Tanks mu		
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenan	ce Hole Other	enter authorization c	odo)	
2. Were all covers securely replaced? Yes \( \sum_{No} \)  3. Is there evidence of tank leakage from a centic, helding, protreatment or nump tank helevy the energing depth or				
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
Toul	Lanking Out	Lastinatio		1
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 1200 gal Tank #2 gal Pretreatment tank gal Pump Tank gal				
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.				
, , , , , , , , , , , , , , , , , , , ,				
				<del></del>
6. Location of septage disposal:				

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162