

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

| Date of Maintenance: $\frac{12/18/17}{2}$ Reason f | | | | |
|---|--|--|---|---------------------|
| Property Address: 15392 AFTON HIL | LS. DR.S. | Property Owner's N | lame: JOE D | UFFY |
| | | ntification Number | | · |
| Maintenance Permit No: X83 794 10189 M | aintainer Name aı | nd License No. <u>Mey</u> | er Sewer Service, In | c./L915 |
| | | | | |
| Maintenance Performed | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| ☑ Tank(s) Pumped | Liquid Level of Tank in | | | |
| Sludge and scum measured | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| \square Yes \square No (if no provide measurements) | 70 Staage a Set | | ins must be pumper | THE ZOTO OF GREATER |
| 1. Access used to remove septage: Maintenan | ce Hole Other (| enter authorization co | ode) | |
| 2. Were all covers securely replaced? Yes | | | SF | |
| | | costmont or numn | tank balaw the one | |
| 3. Is there evidence of tank leakage from a sent | ic. notaing prefi | | TAUK DELOW THE ODE | rating denth or |
| Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structura | lly unsound main | tenance hole cove | ers? | erating depth or |
| evidence of damaged, cracked, or structura | | | | erating depth or |
| Tank | Leaking Out | Leaking In | Cover Damage | erating depth or |
| Tank Septic/Holding Tank #1 | Leaking Out Ves No | Leaking In Yes No | Cover Damage See No | erating depth or |
| Tank | Leaking Out | Leaking In | Cover Damage | erating depth or |
| Tank Septic/Holding Tank #1 | Leaking Out Ves No | Leaking In Yes No | Cover Damage See No | erating depth or |
| Tank Septic/Holding Tank #1 Septic/Holding Tank #2 | Leaking Out Yes No Yes No | Leaking In Yes No Yes No | Cover Damage Yes No Yes No | |
| Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank | Leaking Out Yes No Yes No Yes No | Leaking In Yes No Yes No Yes No | Cover Damage Yes No Yes No Yes No | erating depth or |
| Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed? | Leaking Out Yes No Yes No Yes No Yes No | Leaking In Yes No Yes No Yes No Yes No | Cover Damage Yes No Yes No Yes No Yes No | |
| Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed? Tank #1 / COO gal Tank #2 / COO C | Leaking Out Yes No Yes No Yes No Yes No | Leaking In Yes No Yes No Yes No Yes No Yes No | Cover Damage Yes No Yes No Yes No Yes No | gal |
| Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed? | Leaking Out Yes No Yes No Yes No Yes No | Leaking In Yes No Yes No Yes No Yes No Yes No | Cover Damage Yes No Yes No Yes No Yes No | gal |
| Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed? Tank #1 / COO gal Tank #2 / COO C | Leaking Out Yes No Yes No Yes No Yes No | Leaking In Yes No Yes No Yes No Yes No Yes No | Cover Damage Yes No Yes No Yes No Yes No | gal |

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162