

check # 17929
 pd \$
 17.00

C1441g14789

SSTS MAINTENANCE REPORT

System Location		
Address <u>19900 Maxwell Ave N.</u>	Telephone Number <u>651-338-5231</u>	
City <u>Maric on St. Croix</u>	State <u>ZIP 55047</u>	Property ID No./GEO Code
Owner <u>Thomas Owczarzak</u>	Pumping Date	
Contractor <u>Northside Septic Service</u>		
Maintainer <u>Kyle Carpenter</u>	MPCA License No. <u>930</u>	Telephone Number <u>763-444-7898</u>

What was done to the system?

Tank(s) Pumped
 Sludge and scum measured.
 Do tanks need to be pumped?
 Yes No (If no provide measurements below)

Report Liquid Capacity in Gallons

Tank 1: 1250 Pumped Tank 2: 1250 Pumped
 Tank 3: 1000 Pumped Tank 4: _____ Pumped
 Total Gallons Pumped: 2700

Visual Inspection (note any problems with the system):

NOTE: This does not serve as a compliance inspection.

2nd Septic was pumped & at 13%

RECEIVED

JAN 26 2018


PUBLIC HEALTH

***Tank Measurements-Use Only If Tank(s) Were NOT Pumped**

Liquid Level of Tank (Distance from invert of outlet pipe to bottom of tank) 43 in. 1st septic

Sludge Level 13 in. + Scum Level 6 in. = Total Sludge and Scum Level 19

Total Sludge and Scum Level _____ / Liquid Level _____ = Percent Sludge and Scum in Tank 44 %



*Tanks must be pumped if either of the following conditions exist:
 1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or
 2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity.

Liquid Level measured from invert of outlet pipe to bottom of tank

Signature _____

Date

9-19-2017

Reset Form