1 of 9

Inspect Minnesota & Midwest Soil Testing

P.O. Box 10853 White Bear Lake, MN 55110		Brian Humpal	
· · · · · · · · · · · · · · · · · · ·		MPCA Licensed Advanced Inspector	
SUBSURFACE SEWAG	E TREATMENT SYSTE	EM (SSTS) COMPLIANCE REPORT	
Date: April 9, 2018	Time: 9:00 AM	Owner: Dan Meyer	
Inspection Address: 2389 Legion Ln N, Lake Elmo, MN 55042			

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system, have reviewed the history of the system with the owner, Dan Meyer, and have reviewed the original design/permit records on file at the City of Lake Elmo. This very old system (installed in 1977) consists of a pre-cast septic tank and a rock trench drainfield.

Predicated on my inspection of the system, my review of the history of the system with the owner, and my review of the original design/permit records, it is my opinion that this system presently meets MPCA minimum compliance inspection requirements.

Inspect Minnesota and Midwest Soil Testing have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Inspect Minnesota and Midwest Soil Testing disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Brian Humpal

Brian Humpal

Minnesota Pollution Control Agency	Comp	
520 Lafayette Road North St. Paul. MN 55155-4194	Existing Su	

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspection results based on Minnesota Pollution Control Agency (MPCA)
requirements and attached forms – additional local requirements may also apply.

For local tracking purposes:

Submit completed form to Local Unit of Government (LUG) and system owner within 15 days

System Status

System status on date (mm/dd/yyyy): 4/9/2018

Compliant – Certificate of Compliance

(Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)

] Noncompliant – Notice of Noncompliance

(See Upgrade Requirements on page 3)

Reason(s) for noncompliance (check all applicable)

Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety

Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety

2 of 9

Tank Integrity (Compliance Component #2) – Failing to protect groundwater

Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater

Soil Separation (Compliance Component #4) – Failing to protect groundwater

Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant

Property Information

Parcel ID# or Sec/Twp/Range:

Property address: 2389 Legio	on Ln N, Lake Elmo, MN 55042	Reason for inspection:	Property Transfer
Property owner: Dan Meyer		Owner's phone:	
or			
Owner's representative: Emil	ly Yasgar - Keller Williams	Representative phone:	651-436-5958
Local regulatory authority: W	/ashington County	Regulatory authority phon	e: 651-430-4052
Brief system description: A p	pre-cast septic tank and a rock trench drainfiel	d.	
Comments or recommendations	S:		

Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.

Inspector name:	Brian Humpal	Certification number:	L5342
Business name:	Inspect Minnesota, Midwest Soil Testing	License number:	L2896
Inspector signature	: Brian Humpal	Phone number:	651-492-7550

Necessary or Locally Required Attachments

 ☑ Soil boring logs
 ☑ System/As-built drawing
 □ Forms per local ordinance

 ☑ Other information (list):
 Report Summary, Property Information, Disclaimer, License

Impact on Public Health – Compliance component #1 of 5 1.

Compliance criteria:	
System discharge sewage to the ground surface.	🗌 Yes 🖾 No
System discharge sewage to drain tile or surface waters.	🗌 Yes 🛛 No
System cause sewage backup into dwelling or establishment.	🗌 Yes 🖾 No
Any "yes" anower above indicate	a the aveter is

Any "yes" answer above indicates the system is an Imminent Threat to Public Health and Safety.

Comments/Explanation:

None of the above found.

Verification method(s):

- Searched for surface outlet
- Searched for seeping in yard/backup in home
- Excessive ponding in soil system/D-boxes
- Homeowner testimony (See Comments/Explanation)
- "Black soil" above soil dispersal system
- System requires "emergency" pumping
- Performed dye test
- Unable to verify (See Comments/Explanation)
- Other methods not listed (See Comments/Explanation)

2. Tank Integrity – Compliance component #2 of 5

Compliance criteria:

Seepage pits meeting 7080.2550 may be compliant if allowed in local ordinance.Sewage tank(s) leak below their designed operating depth.If yes, which sewage tank(s) leaks:	System consists of a seepage pit, cesspool, drywell, or leaching pit.	🗌 Yes	🛛 No
designed operating depth.			
If yes, which sewage tank(s) leaks:	3	🗌 Yes	🛛 No
	If yes, which sewage tank(s) leaks:		

Any "yes" answer above indicates the system is Failing to Protect Groundwater.

Comments/Explanation:

Lowered underwater camera into tank - baffles and tank walls OK.

Verification method(s):

- Probed tank(s) bottom Examined construction records Examined Tank Integrity Form (Attach) Observed liquid level below operating depth Examined empty (pumped) tanks(s)
- Probed outside tank(s) for "black soil"
- Unable to verify (See Comments/Explanation)
- Other methods not listed (See Comments/Explanation)

Other Compliance Conditions - Compliance component #3 of 5 3.

a.	Maintenance hole covers are damaged, cracked, unsecured, or appear to structurally unsound.	□ Yes*	🛛 No	Unknown
	· · · · · · · · · · · · · · · · · · ·			

Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety. 🗌 Yes* 🛛 No 📋 Unknown *System is an imminent threat to public health and safety

Explain:

C.	System is non-protective of ground water for other conditions as determined by inspector	□ Yes*	🛛 No
	*System is failing to protect groundwater		

Explain:

4. Soil Separation – Compliance component #4 of 5

Date of installation: 1977	Unknown	Verification method(s):	
Shoreland/Wellhead protection/Food Beverage Lodging?	🛛 Yes 🗌 No	Soil observation does not expire. Problem observations by two independent particular problem of the second se	
Compliance criteria:		unless site conditions have been all	
For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	🗌 Yes 🔲 No	requirements differ. ☐ Conducted soil observation(s) (<i>i</i> ☐ Two previous verifications (Attac ☐ Not applicable (<i>Holding tank</i> (s), <i>n</i>	ch boring logs)
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.		 Unable to verify (See Comments/ Other (See Comments/Explanation) 	
Non-performance systems built April 1,	🛛 Yes 🗌 No	Comments/Explanation:	
1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:		Reviewed design and permit record	S.
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*			
"Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV		Indicate depths of elevations	
or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)		A. Bottom of distribution media	See Attached Boring Log(s
Drainfield meets the designed vertical		B. Periodically saturated soil/bedrock	
separation distance from periodically saturated soil or bedrock.		C. System separation	
		D. Required compliance separation*	
Any "no" answer above indicates the failing to Protect Groundwater.	he system is	*May be reduced up to 15 percent in Ordinance.	allowed by Loca
Operating Permit and Nitrogen B	MD* Compliana	e component #5 of 5 🛛 🖂 Not app	liaabla
• • •		· · · ·	
s the system operated under an Operating Per		- , , ,	
s the system required to employ a Nitrogen BN		•	
BMP=Best Management Practice(s) specified in the sy		sign	

a.	Operating Permit number:	🗌 Yes 🗌 No
	Have the Operating Permit requirements been met?	
b.	Is the required nitrogen BMP in place and properly functioning?	🗌 Yes 🔲 No

Any "no" answer indicates Noncompliance.

Upgrade Requirements (*Minn. Stat.* § 115.55) *An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.*

Inspect Minnesota & Midwest Soil Testing

Subsurface Sewage Treatment System Owner/Property Information

This information will be used for the purpose of conducting an MPCA Compliance Inspection.

Date of Inspection: April 9, 2018	Time: 9:00 AM		
Property Address: 2389 Legion Ln N, Lake Elmo, MN	Zip: 55042		
Property Owner: Dan Meyer	Phone:		
Property Owner: Dan Meyer Tank(s) Tank(s)Material Soil Treatment S Septic 1 Fiberglass Rock trench Aerobic Plastic Gravelless tre Lift Metal Chamber trend Holding Concrete Seepage bed Other: Block Mound Other At-grade Are the tank maintenance covers accessible? Yes N performed through the maintenance holes. Maintenance holes. Maintenance holes.	ystem Other Alternative system		
Year house built: 1977 Year septic installed: 1977	Tank size (gals.): 1000		
	er of residents in home? 2		
Number of bedrooms?2-3Are all floors drained			
	ol bath? Y		
More than one system (laundry, etc.)? N			
Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N			
Are there any additional systems on this property serving o	ther buildings? N		
Location of septic system on lot? East Side			
Location of water well on lot? Southwest Side	Is the well a deep well? Y		
Have you ever experienced any problems with the system s	such as: tree roots, sewage back-ups,		
surfacing of sewage onto the ground, septic tank overflowing to the system? N If yes, explain:	ng, etc.; or have any repairs been made		
When was the system last pumped? 2017 Name	of pumper: Meyer's Sewer Service		
	system on a monitoring plan? N		
Have you received notices from any government agency concerning this system? N			
Is your property located in a shoreland management area? Y			
Do you have any additional information that should be give			

I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing.

Owner/Occupant: Dan Meyer's Signature On File

Garage Driveway Septic Tank OB-1 By Inspect MN House Drainfield Area - \bigcirc Well 2389 Legion Ln N, Lake Elmo, MN 55042 NO SCALE Ń

Log Of Soil Borings

Location of Project: 2389 Legion Ln N, Lake Elmo, MN 55042						
Borings Made By: Inspect Minneso			Date:		4/9/18	
		Hand/Bucket			USDA	
Boring Number:		1	Boring Number:			
Surface Elevation of Same grou		und surface as last nfield trench	s last Elevation of Boring			
Depth In Inches	Soils Encountered		Depth In Inches	<u>Soils Er</u>	Soils Encountered	
0-11 11-35 35-70 70-85	10YR 4/3 F 10YR 4/4 Loa Trace 10YR 5/4	Fine Sandy Loam Fine Sandy Loam My Fine Sand With e of Gravel Fine Sand With amellae Banding				
85" De	epth To End Of B	oring Or Redox	Depth To End Of Boring Or Redox			
Same El	levation Of Boring Relative To System		Elevation Of Boring Relative To System			
-48"Depth To Bottom Of Distribution Media≥37"Of Separation			Depth To Bottom Of Distribution Media Of Separation			
End Of Boring At: 85"				End Of Boring At:		
Redox Present At: None				Redox Present At:		
Standing Water Present At: None			Standing \	Water Present At:		

Bottom Of Distribution Medium At: 48 Inches

Brian L. Humpal, Inc. dba. Inspect Minnesota, Midwest Soil Testing

Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems Non-transferable Business License

Inspect Minnesota, Midwest Soil Testing

License # L2896

License Expires: 12/22/2018

Issued: 10/10/2017

Specialty Area(s):

Installer Maintainer Service Provider Advanced Designer Advanced Inspector

Designated Certified Individual(s):

Name	Certification Expires:	
Anthony P Scully	7/28/2018	
Installer, Designer (Conditional	1)	
Brian L Humpal	10/15/2020	
Installer, Maintainer, Serv Prov	, Adv Designer, Adv Inspector	
Christopher R Uebe	3/4/2018	
Designer, Inspector		
	Anthony P Scully Installer, Designer (Conditional Brian L Humpal Installer, Maintainer, Serv Prov Christopher R Uebe	

MINNESOTA POLLUTION CONTROL AGENCY

520 Lafayette Road North St. Paul, Minnesota 55155-4194

Charles K Thompson, Supervisor Certification & Training Unit