

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

| Date of Maintenance: <u>名/ン・</u> | 4/17 Reason f | or Maintenance: _ | ROUTINE | | <u>_</u> | |
|--|---|--|--|--|-------------------|-----------------------------|
| Property Address: <u>8388</u> | 3 11324 St. | <u>S</u> p | Property Owner's Na | ame: <u>LYNDA</u> | FRIKSEN | |
| Municipality: <u>COTIAGE</u> | ROUE ZIP: 550/ | Property Ider | ntification Number: | | | |
| Maintenance Permit No: 14 | _ | | | | | |
| · · · · · · · · · · · · · · · · · · · | | | | | | |
| Maintenance Pe | rformed | Tank Meas | urement (must be | completed if tanks | NOT pumped) | |
| ☐ Sludge and scum measured | | Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in | | | | |
| | | | | | | Do tanks need to be pumped? |
| ☐ Yes ☐ No (if no provide measurements) | | | , states a seam ranks made so partipo a seaso si si care | | | |
| 1. Access used to remove se | eptage: Maintenan | ce Hole 🗌 Other (e | enter authorization co | ode) | | |
| | | | | | | |
| 2. Were all covers securely replaced? Yes No 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | | |
| 3. 13 there evidence or tank | | iia, notanigi prati | - and the state of | comme below the op- | aracing depair or | |
| evidence of damaged, c | racked, or structura | illy unsound main | tenance hole cove | rs? | | |
| evidence of damaged, c | racked, or structura Tank | lly unsound main Leaking Out | tenance hole cove | Cover Damage | | |
| | | | | | | |
| Septio | Tank | Leaking Out | Leaking In | Cover Damage | | |
| Septio | Tank :/Holding Tank #1 | Leaking Out Yes No | Leaking In Yes No | Cover Damage Yes No | | |
| Septio | Tank :/Holding Tank #1 :/Holding Tank #2 :atment Tank | Leaking Out Yes No | Leaking In ☐ Yes ☐ No ☐ Yes ☐ No | Cover Damage Yes No | | |
| Seption Seption Pretree Pump | Tank :/Holding Tank #1 :/Holding Tank #2 eatment Tank Tank | Leaking Out Yes No Yes No Yes No Yes No | Leaking In Yes No Yes No Yes No | Cover Damage Yes No Yes No | | |
| Seption Seption Seption Pretres Pump 4. How many gallons of sep | Tank :/Holding Tank #1 :/Holding Tank #2 eatment Tank :Tank tage were removed? | Leaking Out Yes No Yes No Yes No Yes No | Leaking In Yes No Yes No Yes No Yes No | Cover Damage Yes No Yes No Yes No Yes No | | |
| Seption Seption Pretress Pump 4. How many gallons of seption Tank #1 1500 gal | Tank :/Holding Tank #1 :/Holding Tank #2 eatment Tank Tank tage were removed? Tank #2 | Leaking Out Yes No Yes No Yes No Yes No | Leaking In Yes No Yes No Yes No Yes No | Cover Damage Yes No Yes No Yes No Yes No Pes No | gal | |
| Seption Seption Seption Pretres Pump 4. How many gallons of sep | Tank :/Holding Tank #1 :/Holding Tank #2 eatment Tank Tank tage were removed? Tank #2 | Leaking Out Yes No Yes No Yes No Yes No | Leaking In Yes No Yes No Yes No Yes No | Cover Damage Yes No Yes No Yes No Yes No Pes No | gal | |
| Seption Seption Pretress Pump 4. How many gallons of seption Tank #1 1500 gal | Tank :/Holding Tank #1 :/Holding Tank #2 eatment Tank Tank tage were removed? Tank #2 | Leaking Out Yes No Yes No Yes No Yes No | Leaking In Yes No Yes No Yes No Yes No | Cover Damage Yes No Yes No Yes No Yes No Pes No | gal | |

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162