

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:		•				
Property Address: _//	775 122 ND	St.S. 1	Property Owner's N	lame: Ray	Bland	
Municipality: <u>Len</u>	mark ZIP: 55	7033 Property Ide	ntification Number	:		
Maintenance Permit N	o: <u>e1551r10211</u>	Maintainer Name a	nd License No. <u>Mey</u>	<u>er Sewer Service, In</u>	nc./L915	
Maintenar	nce Performed	Tank Meas	surement (must be	completed if tank	s NOT pumped)	
☐ Tank(s) Pumped		11	Liquid Level of Tank in			
Studge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b		11	Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if r	no provide measurements	s) = % studge & sci	um ra	nks must be pumped	o II 25% or greater	
1. Access used to rem	nove septage: Mainten	ance Hole 🗆 Other (6	enter authorization c	ode)		
	<i>/</i>			•		
 2. Were all covers securely replaced? Yes \(\subseteq \) Yes \(\subseteq \) No 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 						
	II TANK IBAKAOB ITOM A SE	411 IV 111111111111111111111111111111111	earment of numb	TARK REIOW TRE ARE	arating danth ar	
evidence of dama	ged, cracked, or structu	rally unsound main	tenance hole cove	ers?	erating depth or	
evidence of dama	ged, cracked, or structu	rally unsound main Leaking Out	tenance hole cove	Cover Damage	erating depth or	
evidence of dama				Cover Damage	erating depth or	
evidence of dama	Tank Septic/Holding Tank #1	Leaking Out ☐ Yes ☐ No	Leaking In	Cover Damage ☐ Yes ☑ No	erating depth or	
evidence of dama	Tank	Leaking Out	Leaking In	Cover Damage	erating depth or	
evidence of dama	Tank Septic/Holding Tank #1	Leaking Out ☐ Yes ☐ No	Leaking In	Cover Damage ☐ Yes ☑ No	erating depth or	
evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Yes No	Leaking In Yes No Yes No	Cover Damage Yes No Yes No	erating depth or	
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No	erating depth or	
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No		
4. How many gallons of Tank #1 _ 1500	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	OO gal	
4. How many gallons of Tank #1 _ 1500	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	OO gal	
4. How many gallons of Tank #1 _ 1500	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	OO gal	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162