

10/20/17

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 10/30/17 Reason for Maintenance: Routine						
Property Address: //	589 Upper 4	th St. 7.	Property Owner's N	Name: Derri	Kohl	
			ntification Number			
	o: f1511 c 9/36					
manreenance remners	0.1101121102	Nameanier Name a	nd License No. Mey	er sewer service, ir	IC./L913	
TO CASE AND PROPERTY OF THE STATE OF THE REPORT OF THE STATE OF THE ST		To several constitutions				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
☐ Tank(s) Pumped ☐ Sludge and scum measured			Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100   = % Sludge & Scum Tanks must be pumped if 25% or greater				
$\square$ Yes $\square$ No (if no provide measurements)			70 Stadge & Seam Tanks must be pumped if 25% of greater			
1. Access used to ren	nove septage: 🗹 Maintena	nce Hole 🗌 Other (	enter authorization c	ode)	<del></del>	
				,		
2. Were all covers securely replaced? Yes No  3. Is there evidence of tank leakage from a sentic holding pretreatment or nump tank below the operating depth or						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
evidence of dama	iged, cracked, or structur	ally unsound main	tenance hole cove	ers?		
evidence of dama	ged, cracked, or structur Tank	ally unsound main Leaking Out			1	
evidence of dama		Leaking Out	Leaking In	Cover Damage		
evidence of dama	Tank Septic/Holding Tank #1	Leaking Out  Yes No	Leaking In	Cover Damage  Ves No		
evidence of dama	Tank	Leaking Out	Leaking In	Cover Damage		
evidence of dama	Tank Septic/Holding Tank #1	Leaking Out  Yes No	Leaking In	Cover Damage  Ves No		
evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out  Yes No Yes No	Leaking In  Yes No  Yes No	Cover Damage  Yes No  Yes No		
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out  Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No		
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out  Yes No Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No		
4. How many gallons Tank #1 <u>人</u> う のぞ	Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were removed  gal Tank #2	Leaking Out  Yes No Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Pes No	gal	
4. How many gallons Tank #1 <u>人</u> う のぞ	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out  Yes No Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Pes No	gal	
4. How many gallons Tank #1 <u>人</u> う のぞ	Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were removed  gal Tank #2	Leaking Out  Yes No Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Pes No	gal	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162