### **Inspect Minnesota & Midwest Soil Testing**

P.O. Box 383 Hugo, MN 55038

Brian Humpal

651-492-7550/Brian@midwestsoiltesting.com

MPCA Licensed Designer & Inspector

### SUBSURFACE SEWAGE TREATMENT SYSTEM COMPLIANCE REPORT

**Inspection Address:** 1208 St. Johns Dr, Woodbury, MN 55129

### **REPORT SUMMARY**

I have performed an "MPCA Compliance Inspection" on this septic system and have reviewed the original design/permit records, along with a previous compliance inspection from 2002, which were on file at the City of Woodbury. This older system (installed in 1987) consists of a pre-cast septic tank and a rock trench drainfield.

My inspection indicates that this system is presently "non-compliant" in accordance with MPCA rules 7080.1500 Subp.4(B)(D) because of the lack of the required three foot separation between the bottom of the drainfield and seasonally saturated soils. This system <u>is not</u> an imminent threat to public health or safety per MPCA rule 7080.1500 Subp. 4(A).

In accordance with MPCA rules, I am sending a copy of this complete report to Washington County. I cannot officially speak on behalf of the County relative to the upgrade requirements of these non-compliant systems. Please contact Washington County Environmental Specialist, Mr. Chris LeClair (651-430-4052), to verify the County's position.

Please advise buyer, agents, lender, etc. to contact me should they have any questions regarding this system.

Brian Humpal



St. Paul, MN 55155-4194

### **Compliance Inspection Form**

### Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

(Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)    Reason(s) for noncompliance (check all applicable)   Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety   Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety   Tank Integrity (Compliance Component #2) – Failing to protect groundwater   Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater   Other Compliance Component #4) – Failing to protect groundwater   Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant    Property Information		5, 5, 11 p
System Status  System status on date (mm/dd/yyyy): _4/25/2016  Compliant – Certificate of Compliance (Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)  Reason(s) for noncompliance (check all applicable)  Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety  Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater  Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater  Soil Separation (Compliance Component #4) – Failing to protect groundwater  Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant  Property Information  Parcel ID# or Sec/Twp/Range:  Property owner: Kristin Miller  Owner's representative:  Owner's representative:  Coal regulatory authority:  Washington County  Regulatory authority phone: 651-430-4052  Brief system description:  Pre-cast septic tank and a rock trench drainfield.	requirements and attached forms – additional local requirements may also appl	ly.
System status on date (mm/dd/yyyy): 4/25/2016  Compliant – Certificate of Compliance (Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)  Reason(s) for noncompliance (check all applicable)   Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety   Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety   Tank Integrity (Compliance Component #2) – Failing to protect groundwater   Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater   Soil Separation (Compliance Component #4) – Failing to protect groundwater   Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant  Property Information Parcel ID# or Sec/Twp/Range:   Property address: 1208 St. Johns Dr, Woodbury, MN 55129 Reason for inspection: Property Sale Property owner: Kristin Miller Owner's representative: Representative phone: 651-230-1999  Or Owner's representative: Representative phone: Mashington County Regulatory authority: Pre-cast septic tank and a rock trench drainfield.  Comments or recommendations:		owner
System status on date (mm/dd/yyyy): 4/25/2016  Compliant – Certificate of Compliance (Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)  Reason(s) for noncompliance (check all applicable)   Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety   Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety   Tank Integrity (Compliance Component #2) – Failing to protect groundwater   Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater   Soil Separation (Compliance Component #4) – Failing to protect groundwater   Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant  Property Information Parcel ID# or Sec/Twp/Range:   Property address: 1208 St. Johns Dr, Woodbury, MN 55129 Reason for inspection: Property Sale Property owner: Kristin Miller Owner's representative: Representative phone: 651-230-1999  Or Owner's representative: Representative phone: Mashington County Regulatory authority: Pre-cast septic tank and a rock trench drainfield.  Comments or recommendations:		
Compliant − Certificate of Compliance (Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)  Reason(s) for noncompliance (check all applicable)    Impact on Public Health (Compliance Component #1) − Imminent threat to public health and safety    Other Compliance Conditions (Compliance Component #3) − Imminent threat to public health and safety    Tank Integrity (Compliance Component #2) − Failing to protect groundwater    Other Compliance Conditions (Compliance Component #3) − Failing to protect groundwater    Other Compliance Component #4) − Failing to protect groundwater    Operating permit/monitoring plan requirements (Compliance Component #5) − Noncompliant  Property Information  Parcel ID# or Sec/Twp/Range:  Property address: 1208 St. Johns Dr, Woodbury, MN 55129  Reason for inspection: Property Sale  Property owner: Kristin Miller  Owner's phone: 651-230-1999  or  Owner's representative:  Local regulatory authority: Washington County  Regulatory authority phone: 651-430-4052  Brief system description: Pre-cast septic tank and a rock trench drainfield.  Comments or recommendations:	System Status	
(Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)    Reason(s) for noncompliance (check all applicable)   Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety   Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety   Tank Integrity (Compliance Component #2) – Failing to protect groundwater   Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater   Other Compliance Component #4) – Failing to protect groundwater   Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant    Property Information	System status on date (mm/dd/yyyy): 4/25/2016	
Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety   Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety   Tank Integrity (Compliance Component #2) – Failing to protect groundwater   Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater   Soil Separation (Compliance Component #4) – Failing to protect groundwater   Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant    Property Information	(Valid for 3 years from report date, unless shorter time	Noncompliant – Notice of Noncompliance (See Upgrade Requirements on page 3)
Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety   Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety   Tank Integrity (Compliance Component #2) – Failing to protect groundwater   Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater   Soil Separation (Compliance Component #4) – Failing to protect groundwater   Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant    Property Information	Reason(s) for noncompliance (check all applicable)	
Property address: 1208 St. Johns Dr, Woodbury, MN 55129  Property owner: Kristin Miller  Owner's phone: 651-230-1999  Or  Owner's representative: Representative phone: 4651-430-4052  Brief system description: Pre-cast septic tank and a rock trench drainfield.  Comments or recommendations:	<ul> <li>☐ Other Compliance Conditions (Compliance Component #3) – Imred</li> <li>☐ Tank Integrity (Compliance Component #2) – Failing to protect g</li> <li>☐ Other Compliance Conditions (Compliance Component #3) – Failing</li> <li>☐ Soil Separation (Compliance Component #4) – Failing to protect</li> </ul>	minent threat to public health and safety groundwater ling to protect groundwater groundwater
Property address: 1208 St. Johns Dr, Woodbury, MN 55129  Property owner: Kristin Miller  Owner's phone: 651-230-1999  Or  Owner's representative: Representative phone: 4651-430-4052  Brief system description: Pre-cast septic tank and a rock trench drainfield.  Comments or recommendations:		
Property address: 1208 St. Johns Dr, Woodbury, MN 55129  Property owner: Kristin Miller  Owner's phone: 651-230-1999  Or  Owner's representative: Representative phone: 651-430-4052  Brief system description: Pre-cast septic tank and a rock trench drainfield.  Comments or recommendations:	Property Information Parcel ID# or Sec/	Twp/Range:
Owner's representative:  Local regulatory authority:  Brief system description:  Comments or recommendations:  Representative phone:  Regulatory authority phone:  651-430-4052  Pre-cast septic tank and a rock trench drainfield.		
Owner's representative:  Local regulatory authority:  Brief system description:  Comments or recommendations:  Representative phone:  Regulatory authority phone:  651-430-4052  Pre-cast septic tank and a rock trench drainfield.	Property owner: Kristin Miller	Owner's phone: 651-230-1999
Local regulatory authority: Washington County Regulatory authority phone: 651-430-4052  Brief system description: Pre-cast septic tank and a rock trench drainfield.  Comments or recommendations:		<b>5</b>
Brief system description: Pre-cast septic tank and a rock trench drainfield.  Comments or recommendations:		
Comments or recommendations:		Regulatory authority priorie. 031-430-4032
	·	
Certification	Certification	
I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction possible abuse of the system, inadequate maintenance, or future water usage.	determination of future system performance has been nor can be made due to	o unknown conditions during system construction,
Inspector name: Brian Humpal Certification number: L5342	Inspector name: Brian Humpal	Certification number: <u>L5342</u>
Business name: Inspect Minnesota, Midwest Soil Testing License number: L2896	Business name: Inspect Minnesota, Midwest Soil Testing	License number: L2896
Inspector signature: Phone number: 651-492-7550	Inspector signature: Brian Humpal	Phone number: 651-492-7550
Necessary or Locally Required Attachments	Necessary or Locally Required Attachments	
Soil boring logs	· · · · · _ ·	orms per local ordinance
☐ Soli boling logs ☐ System/As-built drawing ☐ Forms per local ordinance ☐ Solitoring logs ☐ System/As-built drawing ☐ Forms per local ordinance		•

1.	Impact on Public He	<b>ealth</b> – Cor	mpliance compone	nt #1 of 5		
	Compliance criteria:	criteria:		Verification method(s):		
	System discharge sewage ground surface.	to the	☐ Yes ⊠ No	<ul><li>☑ Searched for surface outlet</li><li>☑ Searched for seeping in yard/backup in home</li></ul>		
	System discharge sewage or surface waters.	to drain tile	☐ Yes ⊠ No	<ul> <li>☑ Excessive ponding in soil system/D-boxes</li> <li>☐ Homeowner testimony (See Comments/Explanation)</li> </ul>		
	System cause sewage back dwelling or establishment.	kup into	☐ Yes ⊠ No	<ul> <li>"Black soil" above soil dispersal system</li> <li>System requires "emergency" pumping</li> <li>Performed dye test</li> </ul>		
	Any "yes" answer abo an Imminent Threat to			☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)		
	Comments/Explanation: None of the above found.					
2.	Tank Integrity – Com	npliance con	nponent #2 of 5			
Compliance criteria: Verification method(s):			Verification method(s):			
System consists of a seepage pit, cesspool, drywell, or leaching pit.						
	Seepage pits meeting 7080.25 compliant if allowed in local ord			<ul><li>Examined Tank Integrity Form (Attach)</li><li>Observed liquid level below operating depth</li></ul>		
	Sewage tank(s) leak below designed operating depth.	their	☐ Yes ⊠ No	<ul> <li>☐ Examined empty (pumped) tanks(s)</li> <li>☐ Probed outside tank(s) for "black soil"</li> </ul>		
	If yes, which sewage tank(s	•		☐ Unable to verify (See Comments/Explanation)		
	Any "yes" answer at system is Failing to I			☐ Other methods not listed (See Comments/Explanation)		
Comments/Explanation: Lowered underwater camera into tank - baffles and tank walls OK.				OV		
	Lowered underwater came	ra into tank - I	baffles and tank wall	s OK.		
3.	Other Compliance C	Conditions	6 – Compliance co	mponent #3 of 5		
	a. Maintenance hole covers are damaged, cracked, unsecured, or appear to structurally unsound. ☐ Yes* ☒ No ☐ Unknown					
	b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety. ☐ Yes* ☒ No ☐ Unknown *System is an imminent threat to public health and safety					
	Explain:					
	c. System is non-protective of ground water for other conditions as determined by inspector ☐ Yes* ☒ No *System is failing to protect groundwater					
	Explain:					

Property address: 1208 St. Johns Dr, Woodbury, MN 55129

Inspector initials/Date: 4/25/2016

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • 30 of ISY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12

4.	Soil Separation – Compliance compor	nent #4 o	of 5				
	Date of installation: 1987  Shoreland/Wellhead protection/Food Beverage Lodging?	_ □ Unkn	nown	So	erification method(s): il observation does not expire. Po		
	Compliance criteria:				observations by two independent parties are sufficient, unless site conditions have been altered or local		
	For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	☐ Yes	☐ Yes ☐ No	red	unless site conditions have been altered or local requirements differ.   ☐ Conducted soil observation(s) (Attach boring logs)  ☐ Two previous verifications (Attach boring logs)  ☐ Not applicable (Holding tank(s), no drainfield)		
	Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.				Unable to verify (See Comments/	Explanation)	
	Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	☐ Yes	⊠ No		nmments/Explanation: eviewed previous compliance insp	pection from 2002.	
	Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*						
	"Experimental", "Other", or "Performance" Systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)			Inc	dicate depths of elevations		
				_A	Bottom of distribution media	See Attached Boring Log(s)	
	Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.			-	Periodically saturated soil/bedrock  System separation		
5.	Any "no" answer above indicates the system is Failing to Protect Groundwater.  D. Required compliance separation*  *May be reduced up to 15 percent if allowed by Local Ordinance.  Ordinance.  D. Required compliance separation*  *May be reduced up to 15 percent if allowed by Local Ordinance.						
	Is the system operated under an Operating Permit? ☐ Yes ☒ No ☐ If "yes", A below is required						
	Is the system required to employ a Nitrogen BMP?						
	BMP=Best Management Practice(s) specified in the system design						
If the answer to both questions is "no", this section does not need to be completed.							
	Compliance criteria			I			
	a. Operating Permit number:				☐ Yes ☐ No		
	Have the Operating Permit requirements been met?				<u></u>		
	b. Is the required nitrogen BMP in place and			?	Yes No		
	Any "no" answer indicates Noncompliance.						

Property address: 1208 St. Johns Dr, Woodbury, MN 55129

Inspector initials/Date: 4/25/2016

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • 4 of 191 Y 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 3 of 3


Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

**Upgrade Requirements** (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas,

### **Inspect Minnesota & Midwest Soil Testing**

### Subsurface Sewage Treatment System Owner/Property Information This information will be used for the purpose of conducting an MPCA Compliance Inspection.

Date of Inspection: April 25, 2016	Time: 12:00 PM				
Property Address: 1208 St. Johns Dr, Woodbury, MN	Zip: 55129				
Property Owner: Kristin Miller	Phone: 651-230-1999				
Tank(s)       Tank(s)Material       Soil Treatment System         Septic 1       Fiberglass       ⊠Rock trench         Aerobic       Plastic       Gravelless trench         Lift       Metal       Chamber trench         Holding       ⊠Concrete       Seepage bed         Other:       Block       Mound         Other       At-grade	Other  Alternative system Experimental system Cesspool system Other system				
Are the tank maintenance covers accessible?   Yes   No *If performed through the maintenance holes. Maintenance hole cover the ground surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface access and the second surface access access access access and the second surface access	ers should be made accessible to				
-	Γank size (gals.): 1500				
How long has seller owned the property? 2002 Number of re					
Number of bedrooms? Are all floors drained by g					
Garbage disposal? Whirlpool bath?					
More than one system (laundry, etc.)?  Does this property have any footing drain tiles connected to the se	ptic system?				
Are any buildings on this property such as garages or out-buildings connected to this system?					
Are there any additional systems on this property serving other buildings?					
Location of septic system on lot? West Side					
Location of water well on lot? East Side					
Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system?  If yes, explain:					
When was the system last pumped? Name of pumper:					
	on a monitoring plan?				
Have you received notices from any government agency concerning	ng this system?				
Is your property located in a shoreland management area? N					
Do you have any additional information that should be given to the new owner?					
I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing.					
Owner/Occupant:	Date:				



### **Log Of Soil Borings**

Loc	cation of Project:	1208 St. Johns Dr, W	oodbury, M	N 55129	
Borings Made By: Inspect Minnesota				Date:	4/25/16
Auger Used: Hand/Bucket			Classification System: USDA		USDA
Boring Number: 1				Boring Number:	
Surface Elevation of Boring  Same ground surface as last drainfield trench		Surface Elevation of Boring	of		
Depth In Inches	Soils E	ncountered	Depth In Inches	· I Solis Encollorered	
Tinches   Tinc					
40" Depth To End Of Boring Or Redox			]	Depth To End Of Bo	oring Or Redox
Same Elevation Of Boring Relative To System			E	Elevation Of Boring	Relative To System
-57" Depth To Bottom Of Distribution Media				Depth To Bottom C	of Distribution Media
=0" Of Separation				Of Separation	
5 LOSD : AL			End Of Daving At-		
	End Of Boring At:	63" 40"		End Of Boring At:	
	Redox Present At:			Redox Present At: Water Present At:	
Standing Water Present At: None			Standing	water Present At:	

E	Bottom Of Distribution Medium At:	57 Inches

### **DISCLAIMER**

### Brian L. Humpal, Inc. dba. Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1<sup>st</sup> through April 1<sup>st</sup>) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

# Sulbsurface Sewage Treatment Systems

Non-transferable



License # L2896

Maintainer License Expires:

Adv Inspector License Expires:

Oct 28, 2015 Dec 22, 2016 Dec 22, 2016 Dec 22, 2016 Dec 22, 2016

Adv Designer License Expires:

Date of Issuance:

Installer License Expires:

### Certification

Inspect Minnesota, Midwest Soil Testing

Expires

10/15/2017 10/15/2017

Advanced Designer (Certified) Advanced Inspector (Certified)

Maintainer (Certified)

Certification Type

**Designated Certified** 

Individual (DCI) Brian L. Humpal Brian L. Humpal Brian L. Humpal Brian L. Humpal Brian L. Humpal

10/15/2017

10/15/2017

10/15/2017

Service Provider (Certified)

Installer (Certified)

Designer (Certified) Inspector (Certified)

Christopher R. Uebe Christopher R. Uebe

03/04/2018

03/04/2018

Steven Giddings Manager Environmental Business Assistance Section



## Minnesota Pollution Control Agency

520 Lafayette Road North St. Paul, Minnesota 55155-4194