Inspect Minnesota & Midwest Soil Testing

P.O. Box 383 Hugo, MN 55038

Brian Humpal

651-492-7550/Brian@midwestsoiltesting.com

MPCA Licensed Advanced Inspector

SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

Date: April 19, 2016 **Time:** 12:00 PM **Owner:** Jim & Marilyn Helseth

Inspection Address: 4251 Dorchester Dr, Woodbury, MN 55129

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system, have reviewed the history of the system with the owner, Jim Helseth, and have reviewed the original design/permit records, which were in the owner's possession. This older system (installed in 1987) consists of a pre-cast septic tank and a rock trench drainfield.

Predicated on my inspection of the system, my review of the history of the system with the owner, and my review of the original design/permit records, it is my opinion that this system presently meets MPCA minimum compliance inspection requirements.

Inspect Minnesota and Midwest Soil Testing have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Inspect Minnesota and Midwest Soil Testing disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Brian Humpal



St. Paul, MN 55155-4194

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

System Status System Status on date (mm/dd/yyyy): 4/19/2016 Compliant - Certificate of Compliance (Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.) Reason(s) for noncompliance (check all applicable) Impact on Public Health (Compliance Component #1) - Imminent threat to public health and safety Other Compliance Conditions (Compliance Component #3) - Imminent threat to public health and safety Other Compliance Component #2) - Failing to protect groundwater Other Compliance Component #3) - Imminent threat to public health and safety Other Compliance Compliance Component #3) - Imminent threat to public health and safety Other Compliance Compliance Component #3) - Imminent threat to public health and safety Other Compliance Compliance Component #3) - Failing to protect groundwater Other Compliance Component #4) - Failing to protect groundwater Other Compliance Component #4) - Failing to protect groundwater Operating permit/monitoring plan requirements (Compliance Component #3) - Noncompliant Property Information Parcel ID# or Sec/Twp/Range: Property sale Owner's representative Owner's phone: 612-867-7572 Owner's representative Washington County Representative phone: Regulatory authority; Washington County Representative phone: 651-430-4052 Reason for inspection: Property Sale Owner's representative phone: 651-430-4052 Reason for inspection: Property Sale Owner's sphone: 612-867-7572 Owner's representative phone: 651-430-4052 Representative phone: Regulatory authority; Pre-cast septic tank and a rock trench drainfield. Certification Inereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, popossible abuse of the system, inadequate maintenance, or future water usage. Certification number: L5342 License number: L5342		, , , , , , , , , , , , , , , , , , ,
System Status System status on date (mm/dd/yyyy): 4/19/2016 Compliant - Certificate of Compliance (Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.) Reason(s) for noncompliance (check all applicable)	Instructions: Inspection results based on Minnesota Pollution Control Agency (MPCA) requirements and attached forms – additional local requirements may also apply.	For local tracking purposes:
System status on date (mm/dd/yyyy): 4/19/2016 Compliant - Certificate of Compliance (Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.) Reason(s) for noncompliance (check all applicable)	Submit completed form to Local Unit of Government (LUG) and system owner within 15 days	
Compliant - Certificate of Compliance (Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.) Reason(s) for noncompliance (check all applicable) Impact on Public Health (Compliance Component #1) - Imminent threat to public health and safety Impact on Public Health (Compliance Component #3) - Imminent threat to public health and safety Impact on Public Health (Compliance Component #3) - Imminent threat to public health and safety	System Status	
(Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)	System status on date (mm/dd/yyyy):4/19/2016	
Impact on Public Health (Compliance Component #1) - Imminent threat to public health and safety Other Compliance Conditions (Compliance Component #3) - Imminent threat to public health and safety Tank Integrity (Compliance Component #2) - Failing to protect groundwater Other Compliance Conditions (Compliance Component #3) - Failing to protect groundwater Soil Separation (Compliance Component #4) - Failing to protect groundwater Operating permit/monitoring plan requirements (Compliance Component #5) - Noncompliant Property Information	(Valid for 3 years from report date, unless shorter time (See Upg	
Impact on Public Health (Compliance Component #1) - Imminent threat to public health and safety Other Compliance Conditions (Compliance Component #3) - Imminent threat to public health and safety Tank Integrity (Compliance Component #2) - Failing to protect groundwater Other Compliance Conditions (Compliance Component #3) - Failing to protect groundwater Operating permit/monitoring plan requirements (Compliance Component #5) - Noncompliant Property Information	Reason(s) for noncompliance (check all applicable)	
Property address:	 □ Other Compliance Conditions (Compliance Component #3) – Imminent this □ Tank Integrity (Compliance Component #2) – Failing to protect groundward □ Other Compliance Conditions (Compliance Component #3) – Failing to protect groundward □ Soil Separation (Compliance Component #4) – Failing to protect groundward 	reat to public health and safety ter otect groundwater rater
Property address:		
Property address:	Property Information Parcel ID# or Sec/Twn/Range	ne.
Property owner: Jim & Marilyn Helseth Owner's phone: 612-867-7572 Owner's representative: Representative phone: 651-430-4052 Brief system description: Pre-cast septic tank and a rock trench drainfield. Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal Certification number: L5342 Business name: Inspect Minnesota, Midwest Soil Testing License number: L2896 Inspector signature: Phone number: 651-492-7550		
Owner's representative: Local regulatory authority: Brief system description: Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal Business name: Inspect Minnesota, Midwest Soil Testing Inspector signature: Phone number: Representative phone: Regulatory authority phone: 651-430-4052 Regulatory authority phone: 651-430-4052 Regulatory authority phone: 651-430-4052 Regulatory authority phone: 651-430-4052	· · · · · · · · · · · · · · · · · · ·	•
Regulatory authority: Washington County Regulatory authority phone: 651-430-4052 Pre-cast septic tank and a rock trench drainfield. Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal Certification number: L5342 Business name: Inspect Minnesota, Midwest Soil Testing License number: L2896 Inspector signature: Phone number: 651-492-7550	or	
Brief system description: Pre-cast septic tank and a rock trench drainfield. Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal Certification number: L5342 Business name: Inspect Minnesota, Midwest Soil Testing License number: L2896 Inspector signature: Phone number: 651-492-7550	· · · · · · · · · · · · · · · · · · ·	
Certification I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal Certification number: L5342 Business name: Inspect Minnesota, Midwest Soil Testing License number: L2896 Inspector signature: Rumpal Phone number: 651-492-7550		ry authority phone: <u>651-430-4052</u>
Certification I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal Certification number: L5342 Business name: Inspect Minnesota, Midwest Soil Testing License number: L2896 Inspector signature: Phone number: 651-492-7550	• • •	
I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal Certification number: L5342 Business name: Inspect Minnesota, Midwest Soil Testing License number: L2896 Inspector signature: Phone number: 651-492-7550		
determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal Certification number: L5342 Business name: Inspect Minnesota, Midwest Soil Testing License number: L2896 Inspector signature: Phone number: 651-492-7550	Certification	
Business name: Inspect Minnesota, Midwest Soil Testing License number: L2896 Inspector signature: Phone number: 651-492-7550		
Inspector signature: Phone number: 651-492-7550	Inspector name: Brian Humpal Certificat	ion number: _L5342
	Business name: Inspect Minnesota, Midwest Soil Testing Licer	nse number: L2896
Necessary or Locally Required Attachments	Inspector signature: Brian Humpal Pho	one number:651-492-7550
necessary or Locally Required Actachinents	Necessary or Locally Required Attachments	
⊠ Soil boring logs		local ordinance
☐ Soli borning logs ☐ System/As-built drawing ☐ Forms per local ordinance ☐ Soli borning logs ☐ System/As-built drawing ☐ Forms per local ordinance		

1.	Impa	Impact on Public Health – Compliance component #1 of 5					
	Compliance criteria:			Verification method(s):			
		em discharge sewage to the and surface.	☐ Yes ⊠ No	 ✓ Searched for surface outlet ✓ Searched for seeping in yard/backup in home 			
		m discharge sewage to drain tile face waters.	☐ Yes ⊠ No	 ☑ Excessive ponding in soil system/D-boxes ☑ Homeowner testimony (See Comments/Explanation) ☐ "Black soil" above soil dispersal system 			
		m cause sewage backup into ing or establishment.	☐ Yes ⊠ No	System requires "emergency" pumping Performed dye test			
		"yes" answer above indicates nminent Threat to Public Heal		☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)			
		ments/Explanation: of the above found.					
2.	Tanl	k Integrity – Compliance con	nponent #2 of 5				
	Com	pliance criteria:		Verification method(s):			
		em consists of a seepage pit,	☐ Yes ⊠ No	□ Probed tank(s) bottom □			
	-	pool, drywell, or leaching pit.		Examined construction records			
		age pits meeting 7080.2550 may be iant if allowed in local ordinance.		Examined Tank Integrity Form (Attach)Observed liquid level below operating depth			
		ge tank(s) leak below their ned operating depth.	☐ Yes ⊠ No	☐ Examined empty (pumped) tanks(s)			
		, which sewage tank(s) leaks:		Probed outside tank(s) for "black soil"			
	-	"yes" answer above indicated in the second i		 ☐ Unable to verify (See Comments/Explanation) ☑ Other methods not listed (See Comments/Explanation) 			
		ments/Explanation:		OV.			
	Lowe	red underwater camera into tank - l	parties and tank walls	OK.			
3.	Othe	er Compliance Conditions	- Compliance con	nponent #3 of 5			
	a. Ma	aintenance hole covers are damage	d, cracked, unsecured	or appear to structurally unsound. ☐ Yes* ☒ No ☐ Unknown			
	b. Of	_	mmediately and adver	sely impact public health or safety. ☐ Yes* ☒ No ☐ Unknown			
	Ex	kplain:					
	-	ystem is non-protective of ground wa System is failing to protect ground		s as determined by inspector ☐ Yes* ☒ No			
	Ex	xplain:					

Property address: 4251 Dorchester Dr, Woodbury, MN 55129

Inspector initials/Date: 4/19/2016

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • 3 of TBTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

Date of installation: 1987	Unkn	iown	Ve	erification method(s):	
Shoreland/Wellhead protection/Food Beverage Lodging?	⊠ Yes	☐ No		il observation does not expire. I servations by two independent	
Compliance criteria:			un	less site conditions have been a	
For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	☐ Yes	□ No		quirements differ. Conducted soil observation(s) Two previous verifications (Att Not applicable (Holding tank(s),	ach boring logs)
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.				Unable to verify (See Comment: Other (See Comments/Explanation	
Non-performance systems built April 1,		□No	Co	mments/Explanation:	
1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:			Re	viewed design and permit reco	rds.
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*					
"Experimental", "Other", or "Performance"	☐ Yes	□ No	Inc	dicate depths of elevations	3
systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)			<u>A.</u>	Bottom of distribution media	See Attached Boring Log(s)
Drainfield meets the designed vertical separation distance from periodically				Periodically saturated soil/bedrock System separation	
saturated soil or bedrock.					
Any "no" answer above indicates to Failing to Protect Groundwater.	he syste	em is	*M	Required compliance separation* ay be reduced up to 15 percent rdinance.	if allowed by Local
Operating Permit and Nitrogen B	MP* – C	ompliance	e comp	oonent #5 of 5 🛮 🗵 Not ap	plicable
Is the system operated under an Operating Per	mit?	☐ Yes	⊠ No	If "yes", A below is required	I
Is the system required to employ a Nitrogen BM	IP?	☐ Yes	⊠ No	If "yes", B below is required	i
BMP=Best Management Practice(s) specifi	ied in the	system des	sign		
If the answer to both questions is "no",	this sec	tion does	not n	eed to be completed.	
Compliance criteria					
a. Operating Permit number:					
Have the Operating Permit requirements by	peen met?	>		☐ Yes ☐ No	

Property address: 4251 Dorchester Dr, Woodbury, MN 55129

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 wq-wwists4-31 • 1/24/12 Page 3 of 3

Inspector initials/Date: 4/19/2016

Inspect Minnesota & Midwest Soil Testing


Subsurface Sewage Treatment System Owner/Property Information

This information will be used for the purpose of conducting an MPCA Compliance Inspection.

Date of Inspection: April 19, 2016	Time: 12:00 PM				
Property Address: 4251 Dorchester Dr, Woodbury,	MN Zip: 55129				
Property Owner: Jim & Marilyn Helseth	Phone: 612-867-7572				
Property Owner: Jim & Marilyn Helseth Phone: 612-867-7572 Tank(s) Tank(s)Material Soil Treatment System Other Septic 1 Fiberglass ⊠Rock trench Alternative system Experimental system Experimental system Chamber trench Cesspool system Other: Seepage bed Other: Seepage bed Other: Seepage bed Other System Are the tank maintenance covers accessible? Yes ⊠No *If no, proper maintenance must performed through the maintenance holes. Maintenance hole covers should be made accessible the ground surface to facilitate access and proper maintenance of the system.					
Year house built: 1987 Year septic installed:	1987 Tank size (gals.): 1250 Number of residents in home? 2				
	drained by gravity? Lower Pumped				
	hirlpool bath? N				
More than one system (laundry, etc.)? N	milpool outil. IV				
Does this property have any footing drain tiles conne	ected to the septic system? N				
Are any buildings on this property such as garages o	r out-buildings connected to this system? N				
Are there any additional systems on this property ser	rving other buildings? N				
Location of septic system on lot? East Side					
Location of water well on lot? Northwest Side Is the well a deep well? Y					
Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain:					
	Name of pumper: Pinky's Sewer Service				
How often pumped in previous years? Every 2-3					
Have you received notices from any government agency concerning this system? N					
Is your property located in a shoreland management area? Y					
Do you have any additional information that should	be given to the new owner? N				

I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing.

Owner/Occupant: Jim Helseth's Signature On File Date: 4/19/2016



Log Of Soil Borings

Location of Project: 4251 Dorchester Dr, Woodbury, MN 55129					
Borings Made By: Inspect Minnesota			,.	Date:	4/18/16
Auger Used: Hand/Bucket		Classification System:		USDA	
	Boring Number:	1		Boring Number:	
Surface Elevation Boring	of Same grou	and surface as last ofield trench	Surface Elevation Boring	of	
Depth In Inches	Soils E	ncountered	Depth In Inches	Soils Er	<u>icountered</u>
0-5 5-17 17-52 52-86	10YR 10YR 3/4 Mediu ≈20% Ro 10YR 5/4 Mediu ≈10% Ro Refu	3/2 Loam 4/3 Loam 4/3 Loam Im Sand With Gravel ock & Cobbles Im Sand With Gravel ock Fragments sal At 86"			
86" Depth To End Of Boring Or Redox		Depth To End Of Boring Or Redox			
Same Elevation Of Boring Relative To System		Į.	Elevation Of Boring	Relative To System	
-46" Depth To Bottom Of Distribution Media		Depth To Bottom Of Distribution Media			
≥40" Of Separation		(Of Separation		
End Of Boring At: 86"			End Of Boring Att		
	End Of Boring At: Redox Present At:			End Of Boring At: Redox Present At:	
Redox Present At: None Standing Water Present At: None		Standing Water Present At:			
Standing	THE COURT ALL	None	Standing	Tracer i reserie Att	

Bottom Of Distribution Medium At: 46 Inches

DISCLAIMER

Brian L. Humpal, Inc. dba. Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Sulbsurface Sewage Treatment Systems

Non-transferable



License # L2896

Maintainer License Expires:

Adv Inspector License Expires:

Oct 28, 2015 Dec 22, 2016 Dec 22, 2016 Dec 22, 2016 Dec 22, 2016

Adv Designer License Expires:

Date of Issuance:

Installer License Expires:

Certification

Inspect Minnesota, Midwest Soil Testing

Expires

10/15/2017 10/15/2017

Advanced Designer (Certified) Advanced Inspector (Certified)

Maintainer (Certified)

Certification Type

Designated Certified

Individual (DCI) Brian L. Humpal Brian L. Humpal Brian L. Humpal Brian L. Humpal Brian L. Humpal

10/15/2017

10/15/2017

10/15/2017

Service Provider (Certified)

Installer (Certified)

Designer (Certified) Inspector (Certified)

Christopher R. Uebe Christopher R. Uebe

03/04/2018

03/04/2018

Steven Giddings Manager Environmental Business Assistance Section



Minnesota Pollution Control Agency

520 Lafayette Road North St. Paul, Minnesota 55155-4194