

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730



## **Subsurface Sewage Treatment System Maintenance Permit**

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	0		A .			
ate of Maintenance: $oldsymbol{\bot}$	Reason	for Maintenance:	DIM.			
roperty Address: 100	20 Joyth St		Property Owner's N	lame: Duyes &	marian good	
unicipality: A number	John ZIP:	Property Ide	ntification Number			
aintenance Permit No:	10727, 13113			on's Sewer Service/L	216	
antenante remitero.		manicanjer Hanie di	ild License 140. Olsc	III 3 Jewel Jelvice/L	210	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped  Sludge and scum measured Do tanks need to be pumped?  Yes No (if no provide measurements)			Tank in			
		Sludge Level in Tank in Scum Level in Tank in   Sludge + Scum / Liquid Level X 100				
						= % Studge & SC
		Acces used to some				
Access ased to tellio	ove septage:   Maintena	ance Hole L Other (	enter authorization co	ode)		
	urely replaced?  Yes					
Is there evidence of	tank leakage from a sep	ptic, holding, preti			erating depth or	
. Is there evidence of	•	ptic, holding, preti			erating depth or	
Is there evidence of	tank leakage from a sep	ptic, holding, preti			erating depth or	
Is there evidence of evidence of damag	tank leakage from a sepended, cracked, or structur	ptic, holding, preti rally unsound main	tenance hole cove	ers?    Yes    No	erating depth or	
Is there evidence of evidence of damag	tank leakage from a se ed, cracked, or structur Tank	ptic, holding, preti rally unsound main Leaking Out	tenance hole cove	Cover Damage	erating depth or	
Is there evidence of evidence of damag	tank leakage from a seped, cracked, or structur  Tank  Septic/Holding Tank #1	ptic, holding, pretorally unsound main  Leaking Out  Yes No	Leaking In  Yes No	Cover Damage  Yes No  Yes No	erating depth or	
. Is there evidence of evidence of damag	tank leakage from a seped, cracked, or structur  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2	Leaking Out  Yes No	Leaking In  Yes No	Cover Damage  Yes No Yes No Yes No	erating depth or	
. Is there evidence of evidence of damage	tank leakage from a seped, cracked, or structur  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank	teaking Out  Leaking Out  Yes No  Yes No  Yes No  Yes No	Leaking in  Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Yes No	gal	

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025

License# 216 P: 651-464-2082