

RECEIVED

DEC 12 3

PUBLIC HEALTH

SSTS MAINTENANCE REPORT

System Location		
Address	12575 Frish Ave N	Telephone Number 651 303 9522
City	Hugo	State MN ZIP 55038 Property ID No./GEO Code
Owner	Debbie Letourneau	Pumping Date 6/6/18
Contractor		
Maintainer	DT Septic Services	MPCA License No. #3663 Telephone Number (763) 286-1815

What was done to the system?

Tank(s) Pumped

Sludge and scum measured.

Do tanks need to be pumped?

Yes No (If no provide measurements below)

Report Liquid Capacity in Gallons

Tank 1: 1200 Pumped Tank 2: Pumped

Tank 3: Pumped Tank 4: Pumped

Total Gallons Pumped: _____

Visual Inspection (note any problems with the system):

NOTE: This does not serve as a compliance inspection.


+4664g/1509g

***Tank Measurements-Use Only if Tank(s) Were NOT Pumped**

Liquid Level of Tank (Distance from invert of outlet pipe to bottom of tank) _____ in.

Sludge Level _____ in. + Scum Level _____ in. = Total Sludge and Scum Level _____

Total Sludge and Scum Level _____ / Liquid Level _____ = Percent Sludge and Scum in Tank _____ %



*Tanks must be pumped if either of the following conditions exist:

1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or
2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity.

Liquid Level measured from invert of outlet pipe to bottom of tank

Signature Bruce M... Date 6/6/18 Reset Form

PA
22-county
entry