Inspect Minnesota & Midwest Soil Testing

P.O. Box 10853 White Bear Lake, MN 55110 651-492-7550/Brian@Midwestsoiltesting.com

Brian Humpal

MPCA Licensed Advanced Inspector

SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

Date: April 15, 2019 **Time:** 10:45 AM **Owner:** Lillian Johnson

Inspection Address: 6764 Manning Ave N, Grant, MN 55082

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the history of the system with the owner, Lillian Johnson. I have contacted Washington County and was advised that there are no records for this system. This very old system (installed in approximately 1959) consists of cesspool. Additional cesspool(s) and/or a drainfield may exist beyond the first cesspool.

My inspection indicates that this system is presently "non-compliant" in accordance with MPCA rules 7080.1500 Subp.4(B) because of cesspool(s).

In accordance with MPCA rules, I am sending a copy of this complete report to Washington County. I cannot officially speak on behalf of the County relative to the upgrade requirements of these non-compliant systems. Please contact the Washington County Department of Public Health & Environment (651-430-6655) to <u>verify</u> the County's position.

Please advise buyer, agents, lender, etc. to contact me should they have any questions regarding this system.

Christopher Uebe

Brian Humpal

Brian Humpal



Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspection results based on Minnesota Pollution Control Agency (M requirements and attached forms – additional local requirements may also apply.	PCA) For local track	ing purposes:
Submit completed form to Local Unit of Government (LUG) and system ow within 15 days	ner	
System Status		
System status on date (mm/dd/yyyy):4/15/2019		
— · — · —	ncompliant – Not e Upgrade Requireme	ice of Noncompliance nts on page 3)
Reason(s) for noncompliance (check all applicable) ☐ Impact on Public Health (Compliance Component #1) – Imminent the ☐ Other Compliance Conditions (Compliance Component #3) – Immine ☐ Tank Integrity (Compliance Component #2) – Failing to protect ground other Compliance Conditions (Compliance Component #3) – Failing ☐ Soil Separation (Compliance Component #4) – Failing to protect ground operating permit/monitoring plan requirements (Compliance Component #4)	ent threat to public hea ndwater to protect groundwate undwater	alth and safety
Property Information Parcel ID# or Sec/Twi	/Range:	
Property address: 6764 Manning Ave N, Grant, MN 55082 Re		Property Transfer 39-9489
Property address: 6764 Manning Ave N, Grant, MN 55082 Re Property owner: Lillian Johnson Owner	nson for inspection:ner's phone:651-43	39-9489
Property address: 6764 Manning Ave N, Grant, MN 55082 Re- Property owner: Lillian Johnson Owor Owner's representative: Bill Johnson (Son) Re-	uson for inspection: ner's phone: 651-4; presentative phone: julatory authority phor	39-9489 651-269-0720
Property address: _6764 Manning Ave N, Grant, MN 55082 Re Property owner: _Lillian Johnson Ow or Owner's representative: _Bill Johnson (Son) Re Local regulatory authority: _Washington County Re	uson for inspection: ner's phone: 651-4; presentative phone: julatory authority phor	39-9489 651-269-0720
Property address: 6764 Manning Ave N, Grant, MN 55082 Re Property owner: Lillian Johnson Owor Owner's representative: Bill Johnson (Son) Re Local regulatory authority: Washington County Re Brief system description: A cesspool with possible additional cesspool(s) and Comments or recommendations:	uson for inspection: ner's phone: 651-4; presentative phone: julatory authority phor	39-9489 651-269-0720
Property address: _6764 Manning Ave N, Grant, MN 55082 Re Property owner: _Lillian Johnson Owor Owner's representative: _Bill Johnson (Son) Re Local regulatory authority: _Washington County Re Brief system description: _A cesspool with possible additional cesspool(s) and Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine determination of future system performance has been nor can be made due to use the property of the property o	son for inspection: ner's phone: oresentative phone: julatory authority phor or a drainfield.	39-9489 651-269-0720 ne: 651-430-6655q as of this system. No
Property address: _6764 Manning Ave N, Grant, MN 55082 Re Property owner: _Lillian Johnson Owor Owner's representative: _Bill Johnson (Son) Re Local regulatory authority: _Washington County Re Brief system description: _A cesspool with possible additional cesspool(s) and Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine determination of future system performance has been nor can be made due to upossible abuse of the system, inadequate maintenance, or future water usage.	son for inspection: ner's phone: oresentative phone: julatory authority phor or a drainfield.	39-9489 651-269-0720 ne: 651-430-6655q as of this system. No ing system construction,
Property address: _6764 Manning Ave N, Grant, MN 55082 Re Property owner: _Lillian Johnson Owor Owner's representative: _Bill Johnson (Son) Re Local regulatory authority: _Washington County Re Brief system description: _A cesspool with possible additional cesspool(s) and Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine determination of future system performance has been nor can be made due to upossible abuse of the system, inadequate maintenance, or future water usage.	son for inspection: ner's phone: 651-4; presentative phone: julatory authority phore or a drainfield. e the compliance statunknown conditions during	39-9489 651-269-0720 ne: 651-430-6655q s of this system. No ing system construction,
Property address: 6764 Manning Ave N, Grant, MN 55082 Reproperty owner: Lillian Johnson Owner's representative: Bill Johnson (Son) Reproperty authority: Washington County Reprint System description: A cesspool with possible additional cesspool(s) and Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine determination of future system performance has been nor can be made due to upossible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certification	son for inspection: her's phone: 651-43 presentative phone: julatory authority phore or a drainfield. ethe compliance statucture in the compliance of the	39-9489 651-269-0720 ne: 651-430-6655q s of this system. No ing system construction, 5342/C9852
Property address: 6764 Manning Ave N, Grant, MN 55082 Reproperty owner: Lillian Johnson Owner's representative: Bill Johnson (Son) Reprise Local regulatory authority: Washington County Reprise system description: A cesspool with possible additional cesspool(s) and Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine determination of future system performance has been nor can be made due to upossible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Cemposity Bria	e the compliance statuthknown conditions during tification number: License number:	39-9489 651-269-0720 ne: 651-430-6655q s of this system. No ing system construction, 5342/C9852
Property address: 6764 Manning Ave N, Grant, MN 55082 Re Property owner: Lillian Johnson Owner's representative: Bill Johnson (Son) Re Local regulatory authority: Washington County Re Brief system description: A cesspool with possible additional cesspool(s) and. Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determine determination of future system performance has been nor can be made due to upossible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Ce Business name: Inspect Minnesota, Midwest Soil Testing Inspector signature: Necessary or Locally Required Attachments	e the compliance statuthknown conditions during tification number: License number:	39-9489 651-269-0720 ne: 651-430-6655q s of this system. No ing system construction, 5342/C9852

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 1 of 3

Property address: 6764 Manning Ave N, Grant, MN 55082

Inspector initials/Date: 4/15/2019 **24**

1.	Impact on Public Health - Compliance component #1 of 5							
	Co	Compliance criteria:			Verification method(s):			
		stem discharge sewage to the ound surface.	☐ Yes	⊠ No		Searched for seeping in yard/backup in home		
		stem discharge sewage to drain tile surface waters.	☐ Yes	⊠ No		Excessive ponding in soil system/D-boxes Homeowner testimony (See Comments/Explanation) "Black soil" above soil dispersal system		
		System cause sewage backup into dwelling or establishment.		☐ Yes		☐ "Black soil" above soil dispersal system☐ System requires "emergency" pumping☐ Performed dye test		
		Any "yes" answer above indicates the system is an Imminent Threat to Public Health and Safety.				☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)		
		omments/Explanation: one of the above found.						
2.	Ta	ank Integrity — Compliance com	ponent :	#2 of 5				
	Compliance criteria:				Ve	rification method(s):		
		stem consists of a seepage pit, sspool, drywell, or leaching pit.	⊠ Yes	□ No	☑ Probed tank(s) bottom☐ Examined construction records			
	Se	epage pits meeting 7080.2550 may be mpliant if allowed in local ordinance.				Examined Tank Integrity Form (Attach) Observed liquid level below operating depth		
	Sewage tank(s) leak below their designed operating depth.		☐ Yes	□ No		Examined empty (pumped) tanks(s)		
	If yes, which sewage tank(s) leaks:		All Tank	s		Probed outside tank(s) for "black soil" Unable to verify (See Comments/Explanation)		
	Any "yes" answer above indicates the system is Failing to Protect Groundwater.				☐ Officially (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)			
Comments/Explanation:								
	Lowered underwater camera into tank - tank of block construction.							
3.	Ot	ther Compliance Conditions	. – Comp	oliance componer	nt #3	s of 5		
	a.	Maintenance hole covers are damaged	d, cracked	l, unsecured, or app	ear t	o structurally unsound. ☐ Yes* ☒ No ☐ Unknown		
						public health or safety. ☐ Yes* ☒ No ☐ Unknown		
	Explain:							
	C.	*System is failing to protect ground	em is non-protective of ground water for other conditions as determined by inspector					
	Explain:							

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

4 of 8 Inspector initials/Date: 4/15/2019 24(1) Property address: 6764 Manning Ave N, Grant, MN 55082 **Soil Separation** – Compliance component #4 of 5 Date of installation: □ Unknown Verification method(s): Shoreland/Wellhead protection/Food Beverage ☐ Yes ⊠ No Soil observation does not expire. Previous soil Lodging? observations by two independent parties are sufficient, unless site conditions have been altered or local Compliance criteria: requirements differ. For systems built prior to April 1, 1996, and ☐ Yes ☐ No not located in Shoreland or Wellhead ☐ Conducted soil observation(s) (Attach boring logs) Protection Area or not serving a food. ☐ Two previous verifications (Attach boring logs) beverage or lodging establishment: Not applicable (Holding tank(s), no drainfield) Drainfield has at least a two-foot vertical ☐ Unable to verify (See Comments/Explanation) separation distance from periodically ☐ Other (See Comments/Explanation) saturated soil or bedrock. ☐ Yes ☐ No Non-performance systems built April 1, Comments/Explanation: 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.* "Experimental", "Other", or "Performance" ☐ Yes ☐ No Indicate depths of elevations systems built under pre-2008 Rules; Type IV See Attached or V systems built under 2008 Rules (7080. Boring Log(s) A. Bottom of distribution media 2350 or 7080.2400 (Advanced Inspector License required) B. Periodically saturated soil/bedrock Drainfield meets the designed vertical separation distance from periodically C. System separation saturated soil or bedrock. D. Required compliance separation* Any "no" answer above indicates the system is *May be reduced up to 15 percent if allowed by Local Failing to Protect Groundwater. Ordinance. 5. Operating Permit and Nitrogen BMP* – Compliance component #5 of 5 Not applicable ☐ Yes ☐ No If "yes", A below is required Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP? ☐ Yes ☐ No If "yes", B below is required BMP=Best Management Practice(s) specified in the system design

If the answer to both questions is "no", this section does not need to be completed.

Compliance criteria

a.	Operating Permit number: Have the Operating Permit requirements been met?	☐ Yes ☐ No
b.	Is the required nitrogen BMP in place and properly functioning?	☐ Yes ☐ No

Any "no" answer indicates Noncompliance.

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 TTY 651-282-5332 or 800-657-3864 • Available in alternative formats Page 3 of 3


Inspect Minnesota & Midwest Soil Testing Subsurface Sewage Treatment System Owner/Property Information

This information will be used for the purpose of conducting an MPCA Compliance Inspection.

Date of Inspection: April 15, 2019	Time: 10:45 AM			
Property Address: 6764 Manning Ave N, Grant, MN	Zip: 55082			
Property Owner: Lillian Johnson	Phone: 651-439-9489			
Tank(s) Tank(s)Material Soil Treatment System Septic Fiberglass Rock trench Aerobic Plastic Gravelless trench Lift Metal Chamber trench Holding Concrete Seepage bed Other: Block Mound Other At-grade	Other Alternative system Experimental system Cesspool system 1 or more Other system			
Are the tank maintenance covers accessible? \square Yes \boxtimes No *If no, proper maintenance must be performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system.				
Year house built: 1959 Year septic installed: Unknown				
	sidents in home? 1-5			
Number of bedrooms? 3 Are all floors drained by gr	,			
Garbage disposal? N Whirlpool bath?	N			
More than one system (laundry, etc.)? N				
Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N				
Are there any additional systems on this property serving other buildings? N				
Location of septic system on lot? West Side				
	well a deep well? Y			
Have you ever experienced any problems with the system such as:				
surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain:				
When was the system last pumped? 2018 Name of pump	per: Smilie's Sewer Service			
	on a monitoring plan? N			
Have you received notices from any government agency concerning				
Is your property located in a shoreland management area? N				
Do you have any additional information that should be given to the	e new owner? N			

I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing.

Owner/Occupant: Lillian Johnson's Signature On File Date: 4/15/2019



DISCLAIMER

Brian L. Humpal, Inc. dba. Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems

Non-transferable

Business License

Inspect Minnesota, Midwest Soil Testing

License # L2896

License Expires: 12/22/2019

Issued: 11/20/2018

Specialty Area(s):

Installer
Maintainer
Service Provider
Advanced Designer
Advanced Inspector

Designated Certified Individual(s):

Cert #	Name	Certification Expires:
C9633	Anthony P Scully	3/5/2020
	Installer, Designer (Apprentice)	
C5342	Brian L Humpal	10/15/2023
	Installer, Maintainer, Serv Prov, Adv	Designer, Adv Inspector
C9852	Christopher R Uebe	3/4/2021
	Designer, Inspector	



520 Lafayette Road North St. Paul, Minnesota 55155-4194 Nich Haig

Nick Haig, Supervisor Certification and Training Unit