



GÖVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed

	Ince: 6-14-19 Rea	son for Maintenance	Routin	e	
rroperty Address	: 10705 Kimbro Av	4	Property Owner's	Name: Keith	Mueller
Municipality:	tillwater ZIP:5	5082 Property Id	entification Number	er:	
Maintenance Pen	mit No: 96920 \$15501	Maintainer Name	and License No. Ol	son's Sewer Service/	L216
A See See See See See See See See See Se	· · · · · · · · · · · · · · · · · · ·	- A - V			
	CHathatics Valudojentas	Total dis	araksistan salah Maraman (marya	н сыкынаса Т сыу	e Net ounterd
Tánkijs) Rumip	ea	Isining teveror		. 4. 3	
I Sludge and so	um meacured	Studge Levet in	Tank ir	Scum Level in Tan	k, in
vo tanks nee	d to be pumped?		/ Liquid	Level X 10	0
Yes I No	o (if no provide measurement	(z) Strange et 20	(III) Y	anks must be pumper	d if 25% or greate
. Access used to	remove septage: Mainte	manco Holo 🗍 Osbani			
		== - ;			
. Were all cover	's securely replaced? 🗖 Ye	s 🗆 No	*		4
. Is there evider	's securely replaced? 🗖. Yence of tank leakage from a s	eptic, holding, pret	reatment or pump	tank below the one	erating denth or
I. Is there evider	's securely replaced? A Yence of tank leakage from a slamaged, cracked, or struct	eptic, holding, pret	reatment or pump Itenance hole cove	tank below the opeers? 🔲 Yes 🖾 No	erating depth or
. Is there evider	nce of tank leakage from a s	eptic, holding, pret	reatment or pump Itenance hole covi Leaking in	tank below the ope ers? Yes No Cover Damage	erating depth or
. Is there evider	nce of tank leakage from a s lamaged, cracked, or struct	eptic, holding, pret urally unsound mair	itenance hole cov	ers? Yes No	erating depth or
. Is there evider	nce of tank leakage from a s lamaged, cracked, or struct Tank	eptic, holding, pret urally unsound mair Leaking Out	tenance hole covi	Cover Damage	erating depth or
. Is there evider	rce of tank leakage from a s lamaged, cracked, or struct Tank Septic/Holding Tank #1	eptic, holding, pret urally unsound mair Leaking Out Yes 🗵 No	Leaking In Ves X No	Cover Damage Yes No	erating depth or
. Is there evider	Tank Septic/Holding Tank #2	eptic, holding, preturally unsound mair Leaking Out Yes No	Leaking in Ves No Yes No Yes No	Cover Damage Yes No Yes No Yes No	erating depth or
. Is there evider evidence of d	Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank	eptic, holding, preturally unsound main Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking in Ves No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	erating depth or
. Is there evider evidence of d	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	eptic, holding, preturally unsound main Leaking Out Yes Mo Yes No Yes No Yes No Yes No	Leaking In Ves No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	
How many galle	Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank pump Tank pump Tank #2 pump Tank pump Tank	Leaking Out Leaking Out Yes No	Leaking in Leaking in Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	
How many galle	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Leaking Out Yes No	Leaking in Leaking in Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	
How many gallo	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank Ons of septage were removed gal Tank #2 ion: List any troubleshooting	Leaking Out Leaking Out Yes No	Leaking in Leaking in Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082