

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a v	alid maintenance	permit. This permit	must be completed
prior to performing maintenance activity Date of Maintenance: 5-13-19 Reason	for Maintenance:	n-site for the dura	tion of the maintena	nce activity.
Property Address: 16 Quamwell	Aue S	Property Owner's I	Name: Obby Scl	nleromer
Municipality: Lakeland ZIP: 5500	Property Id	entification Number	r:	
Maintenance Permit No: 57309a15124 M				wer Service/ L1673
Maintenance Performed	Tank Mea	asurement (must be	e completed if tanks	NOT numped)
Tank(s) Pumped	Liquid Level of			.ver pumpeu)
☐ Sludge and scum measured	Sludge Level in	Tank ——— in	Scum Level in Tank	in
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)	= % Sludge & So	cum Ta	anks must be pumped	if 25% or greater
 Access used to remove septage: Maintenance Were all covers securely replaced? Yes Is there evidence of tank leakage from a septage 	☐ No cic, holding, pret	reatment or pump	tank below the oper	ating depth or
	☐ No cic, holding, pret	reatment or pump	tank below the oper	ating depth or
 Were all covers securely replaced? Yes Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structural 	□ No cic, holding, pret Ily unsound mair	reatment or pump ntenance hole cove	tank below the oper ers? Yes No	ating depth or
 Were all covers securely replaced? Yes Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structura Tank	No cic, holding, pret lly unsound main Leaking Out	reatment or pump ntenance hole cove Leaking In	tank below the operers? Yes No Cover Damage	ating depth or
2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structura Tank Septic/Holding Tank #1	No cic, holding, pret lly unsound main Leaking Out	reatment or pump ntenance hole cove Leaking In Yes No	tank below the operers? Yes No Cover Damage Yes No	ating depth or
2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structural Tank Septic/Holding Tank #1 Septic/Holding Tank #2	No cic, holding, pret lly unsound main Leaking Out Yes No Yes No	reatment or pump ntenance hole cove Leaking In Yes No Yes No	tank below the operers? Yes No Cover Damage Yes No Yes No	ating depth or
2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structural Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed?	No cic, holding, pret Ily unsound main Leaking Out Yes No Yes No Yes No Yes No	reatment or pump ntenance hole cover Leaking In Yes No Yes No Yes No Yes No	tank below the operers? Yes No Cover Damage Yes No Yes No Yes No Yes No	
2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structural Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed?	No cic, holding, pret Ily unsound main Leaking Out Yes No Yes No Yes No Yes No Yes No	reatment or pump ntenance hole cove Leaking In Yes No Yes No Yes No Yes No	tank below the operers? Yes No Cover Damage Yes No Yes No Yes No Yes No	gal

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673