

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

	System	Location			CE14200000
Address 6875 170th st n			Telephone		6514296996
City Hugo	State mn	ZIP 55038	Property ID No./	GEO Code	
Owner Edward Ridler	Pumping Da	Pumping Date 9/6/19			
	Cont	tractor			
Maintainer Row Sewer Service	MPCA Licens	se No (L3309	Telephone	Number	6514655505
What was done to the system			Report Liquid Ca	pacity in G	allons
X Tank(s) Pumped		Tank 1: 1000	X Pumped	Tank 2:	Pumped
Sludge and scum measured.		Tank 3:	Pumped	Tank 4:	Pumped
Do tanks need to be pumped?			 Pumped: 1000		
Yes No (If no provide measure	ments below)				
Visual Inspection (note any problems w	ith the system):	NOTE: Th	is does not serv	e as a com	pliance inspection.
Tank Length in. X Tank Width Tank Radius in. X Tank Radius	in. X Tan in. X 3.1 in. X 3.1	k Depth I 4 = Tank Volum	SEP Pumped in. = Tank Volum		ETH
Sludge Level in. X Gallons Per Ir	nch = Sludg	je Volume	Gallons		
Scum Level in. X Gallons Per Ir Sludge Volume + Scum Volume Total Sludge and Scum Volume		Sludge and Scum	Gallons Volume ercent Sludge and	Gallons —— Scum in Tai	nk%
Scum Layer Effluent Sludge Layer		Tank Depth measu from invert of outl pipe to bottom of	followin 1. The to 12 inche baffle; o 2. Total et than 25	g conditions op of the sluces from the b r sludge and s percent of t	nped if either of the s exist: dge layer is less than pottom of the outlet scum volume is great he tank's liquid
Signature	D	ate	09/06/2019		Reset Form