| Pro | pèrty | address: 8251 River Acres Road | South Cot | tage Grove, MN | Inspector initials/Date: ss 05/02/2019 (mm/dd/yyyy) | |
|-------------------|-----------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| (Illin Dad yyyyy) | | | | | | |
| 1. | lm | pact on Public Health – C | act on Public Health – Compliance component #1 of 5 | | | |
| | Co | ompliance criteria: | | | Verification method(s): | |
| | 985 | stem discharges sewage to the | ☐ Yes | ⊠ No | Searched for surface outlet | |
| | | ound surface. | | M NO | Searched for seeping in yard/backup in home | |
| | Sv | stem discharges sewage to drain | ☐ Yes | ⊠ No | ☐ Excessive ponding in soil system/D-boxes | |
| | | or surface waters. | 103 | ⊠ 140 | | |
| | Sv | stem causes sewage backup into | ☐ Yes | ⊠ No | Homeowner testimony (See Comments/Explanation) | |
| | | elling or establishment. | | 23 110 | "Black soil" above soil dispersal system | |
| | Δ | Any "yes" answer above indicates the system is an imminent threat to public health and safety. Comments/Explanation: | | | ☐ System requires "emergency" pumping | |
| | | | | | ☐ Performed dye test ☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation) | |
| | | | | | | |
| 2 | | | | | | |
| | Co | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| 2. | Tank Integrity – Compliance component #2 of 5 | | | | | |
| | 2000000 | Compliance criteria: | | | Vorification mathed/s | |
| 6 | | | Ι | | Verification method(s): | |
| | | stem consists of a seepage pit, spool, drywell, or leaching pit. | ⊠ Yes | ∐ No | ☐ Probed tank(s) bottom | |
| | | | | | ☐ Examined construction records | |
| | | epage pits meeting 7080.2550 may be apliant if allowed in local ordinance. | | | ☐ Examined Tank Integrity Form (Attach) | |
| - | 9.4-4.4-07 | | | | ☐ Observed liquid level below operating depth | |
| | | wage tank(s) leak below their | ☐ Yes | ⊠ No | | |
| | | signed operating depth. | | | Probed outside tank(s) for "black soil" | |
| ÷ | ir y | es, which sewage tank(s) leaks: | | - | | |
| | Any "yes" answer above indicates the system is failing to protect groundwater. | | | е | Unable to verify (See Comments/Explanation) | |
| | | | | ter. | ☐ Other methods not listed (See Comments/Explanation) | |
| | Comments/Explanation: | | | | | |
| | Pumped 1000 gallons through 4" pipe. Tank not water tight. Sytem needs to be updated. 5-2-19. | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| 3. | Other Compliance Conditions - Compliance component #3 of 5 | | | | | |
| | a. | a. Maintenance hole covers are damaged, cracked, unsecured, or appear to be structurally unsound. ☐ Yes* ☒ No ☐ Unknow | | | | |
| | b. | | | | | |
| | | | | | | |
| Explain: | | | | | | |
| | c. System is non-protective of ground water for other conditions as determined by inspector . ☐ Yes* ☒ No | | | | | |
| | | | | | | |
| | *System is failing to protect groundwater. | | | | 400 | |
| | Explain: | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31b • 6/4/14