Country

## SSTS MAINTENANCE REPORT

	System Location
Address 13833 OLDFIELD RD	N. Telephone Number <u>651-351-7684</u>
City STILLWATER	43, 331 (40)
OWNER DAWN ODLE	Pumping Date
	Contractor
Maintainer	MPCA License No. Telephone Number
What was done to the system?	Report Liquid Capacity in Gallons
Tank(s) Pumped  Sludge and scum measured. Do tanks need to be pumped?  Yes No (If no provide measurements below)	Tank 1: Pumped Tank 2: Pumped  Tank 3: Pumped Tank 4: Pumped  Total Gallons Pumped:
Visual Inspection (note any problems with the	system): NOTE: This does not serve as a compliance inspection.
*Tank Measurer	ments-Use Only If Tank(s) Were NOT Pumped
Scum Layer  Liquid Effluent  Siudge Layer	*Tanks must be pumped if either of the following conditions exist:  1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or  2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity.
ignature Pawin Wala	Date: 8/24/2019

2016

\$17.00 Processing Fee
Make Checks payables and remit to:
Washington County Public Health and Environment 14949 62nd St N Stillwater, MN 55082

RECEIVED

AUG 28 2019

**PUBLIC HEALTH**