DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 10/10/19 Reason for		STATE NEP	UKI	V
10/10/19 Reason f	or Maintenance:	92530 r17	1272	
Property Address: 19320 News atc	Au 11	Property Owned at	5/9	
Property Address: 19320 Newgate Municipality: Scandia	State MAS Zin	Code 5	Suc & Dennis Len	Z
What was done to the system?		75073	GEO Code/Property I.D. #:	
Tank(s) Pumped	lank	Measurements (must	be completed if tanks NOT pu	impod)
Sludge and scum measured	Liquid Level o	(Tarel		
Do tanks need to be pumped?	11	-	udge Level in. Scum Le	vel in.
Yes No (If no provide measurements)	Total (Sludge +	+ Scum) / Liqui	id Level = % Sludge &	
1. Access used to remove septage: Maintenan	sollet ==			
2. If maintenance hole was used, were all covers see Explanation:	ce note JOth	er (Go to #3 below)	* Tank must be pumpe	d if this value
Explanation:	curely replaced?	Yes No please	is greater than 25%.	
5. It owner refuses to allow a Subsurface Sewage	Treatment Syst	tom (SSTC) 4 - 4		
 If owner refuses to allow a Subsurface Sewage them complete and sign the following stateme 	nt:	com (3313) to be pump	ed through the maintenance l	hole, have
hole. I understand that removal of solids and liqui 4. Is the tank designed as a leaky tank? example: seep.	ds through other	laccess points is a se	solids and liquids through the m	naintenance
as a leaky tank? example: seep	age nit ressonat	drivell leaching is not cor	nsidered maintenance.	
Tank#1 Tyes KNo Verificatio Method Used	h 4	arywen, reaching pit		
Tank#2 Tyon Time	Visual			•
Tank#2 Yes No Verificatio Method Used	Visua			
5. Is there evidence of tank leakage from a septic, I damaged, cracked, or structurally unsound main	olding, pretrea	Itment or muse		
Tank and the structurally unsound main	tenance hole co	overs?	elow the operating depth or e	vidence of
Sometic (1) Live	aking Out	Leaking In	31	
Septic/Holding Tank #1	Yes TANO	Yes No	Cover Damage	
Septic/Holding Tank #2	les DNo	T Yes ANO	Yes KMo	
Pretreatment Tank	es TiNo	Yes No	T Yes I No	
Pump Tank Y	es [No	Yes No	T. Yes T. No	
6. How many gallons of septage were removed?		E 1 103 [_:NO	Yes No	
Tank#1 1,000 Tank#2 1,000 P	Protrona			
7. Other information: List any troub to	Pretreatment Tan	ıkPu	ımp Tank	
7. Other information: List any troubleshooting, mino	r repairs conduc	cted, tank safety conce	rns, or other con	
8. Certification: The series		•	concerns.	
8. Certification: I hereby certify as a State of Minnesota and made the observations, or directly	certified SSTS Ma	aintainer that I personal		
and made the observations, or directly Maintainer's Name:	supervised other	rs in the performance of	y conducted the work this job.	
1255 1	Maine		,	
Maintainer's License #: 2 (4 Maintainer's Phor	ne#: /s/-/.	Address: 17638	Lyans St NE	
Maintainer's Signature	671 4			
7		Date: 10/	110/7019	
<i>*</i>			1-7001	