Midwest Sewer Services

P.O. Box 10853 White Bear Lake, MN 55110 651-492-7550/Brian@Midwestsoiltesting.com

Brian Humpal

MPCA Licensed Advanced Inspector

SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

Inspection Address: 10077 Julep Trl N, Forest Lake, MN 55073

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system, have reviewed the history of the system with the owner, Jodi Stuber, and have reviewed the original design/permit records on file at Washington County. This older system (installed in 1994) consists of two precast septic tanks, a pre-cast lift tank, and a mound.

Predicated on my inspection of the system, my review of the history of the system with the owner, and my review of the original design/permit records, it is my opinion that this system presently meets MPCA minimum compliance inspection requirements.

Midwest Sewer Services have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Midwest Sewer Services disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal



Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspection results based on Minnesota Pollution Control Agency requirements and attached forms – additional local requirements may also apply	
Submit completed form to Local Unit of Government (LUG) and system of within 15 days	owner
System Status	
System status on date (mm/dd/yyyy):12/10/2019	
	Ioncompliant – Notice of Noncompliand See Upgrade Requirements on page 3)
Reason(s) for noncompliance (check all applicable) Impact on Public Health (Compliance Component #1) – Imminent Other Compliance Conditions (Compliance Component #3) – Imminent Tank Integrity (Compliance Component #2) – Failing to protect gr Other Compliance Conditions (Compliance Component #3) – Failing Soil Separation (Compliance Component #4) – Failing to protect gr Operating permit/monitoring plan requirements (Compliance Comp	ninent threat to public health and safety roundwater ing to protect groundwater groundwater
Property Information Parcel ID# or Sec/T	-wp/Range:
Property address: 10077 Julep Trl N, Forest Lake, MN 55073 F	wp/Range: Reason for inspection: Dwner's phone: 651-433-2536
Property address: 10077 Julep Trl N, Forest Lake, MN 55073 F Property owner: Jodi Stuber Cor	Reason for inspection: Property Transfer Dwner's phone: 651-433-2536
Property address: 10077 Julep Trl N, Forest Lake, MN 55073 F Property owner: Jodi Stuber Cor Owner's representative: F	Reason for inspection: Property Transfer Dwner's phone: 651-433-2536 Representative phone: 651-430-6655
Property address:10077 Julep Trl N, Forest Lake, MN 55073 F Property owner:	Reason for inspection: Property Transfer Dwner's phone: 651-433-2536 Representative phone: 651-430-6655
Property address:	Reason for inspection: Property Transfer Dwner's phone: 651-433-2536 Representative phone: 651-430-6655 I a mound.
Property address:	Reason for inspection: Property Transfer Dwner's phone: 651-433-2536 Representative phone: 651-430-6655 I a mound. Dinne the compliance status of this system. No a unknown conditions during system construction,
Property address:	Reason for inspection: Property Transfer Dwner's phone: 651-433-2536 Representative phone: 651-430-6655 I a mound. Dinne the compliance status of this system. No a unknown conditions during system construction,
Property address:	Reason for inspection: Property Transfer Dwner's phone: 651-433-2536 Representative phone: 651-430-6655 It a mound. Dinne the compliance status of this system. No punknown conditions during system construction,
Property address:	Reason for inspection: Property Transfer Dwner's phone: 651-433-2536 Representative phone: 651-430-6655 If a mound. Denote the compliance status of this system. No a unknown conditions during system construction, and the compliance construction construction construction in the compliance construction construction construction in the compliance construction construction construction in the compliance construction constructi
Property address:	Reason for inspection: Property Transfer Dwner's phone: 651-433-2536 Representative phone: 651-430-6655 If a mound. Description of the compliance status of this system. No a unknown conditions during system construction, and the compliance of the construction of the compliance status of the construction, and the compliance status of the construction, and the compliance status of the construction, and the construction of the compliance status of the construction, and the construction of the constru
Property address: 10077 Julep Trl N, Forest Lake, MN 55073 Property owner: Jodi Stuber Or Owner's representative: Washington County Brief system description: Two pre-cast septic tanks, a pre-cast lift tank, and Comments or recommendations: Certification I hereby certify that all the necessary information has been gathered to determ determination of future system performance has been nor can be made due to possible abuse of the system, inadequate maintenance, or future water usage Inspector name: Brian Humpal/Christopher Uebe Business name: Midwest Sewer Services Inspector signature: Mecessary or Locally Required Attachments	Reason for inspection: Property Transfer Dwner's phone: 651-433-2536 Representative phone: 651-430-6655 If a mound. Description of the compliance status of this system. No a unknown conditions during system construction, and the compliance of the construction of the compliance status of the construction, and the compliance status of the construction, and the compliance status of the construction, and the construction of the compliance status of the construction, and the construction of the constru

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 1 of 3

Property address: _ 10077 Julep Trl N, Forest Lake, MN 55073

Inspector initials/Date: 12/10/2019 **24**

1.	In	npact on Public Health – Con	npliance	component #1 of	of 5	
	Sy gro Sy or Sy dw An	estem discharge sewage to the bund surface. Its tem discharge sewage to drain tile surface waters. Its tem cause sewage backup into velling or establishment. In y "yes" answer above indicates in Imminent Threat to Public Heal comments/Explanation: In the control of the above found.	the sys	⊠ No ⊠ No etem is	Verification method(s): Searched for surface outlet Searched for seeping in yard/backup in home Excessive ponding in soil system/D-boxes Homeowner testimony (See Comments/Explanation "Black soil" above soil dispersal system System requires "emergency" pumping Performed dye test Unable to verify (See Comments/Explanation) Other methods not listed (See Comments/Explanation)	
2.		ank Integrity — Compliance com	ponent #	‡2 of 5	Verification method(s):	
	Syce Secon Secon Manual Sy Coc Loc Liff	rstem consists of a seepage pit, sspool, drywell, or leaching pit. repage pits meeting 7080.2550 may be impliant if allowed in local ordinance. rewage tank(s) leak below their signed operating depth. res, which sewage tank(s) leaks: ry "yes" answer above indicates and its Failing to Protect Green comments/Explanation: wered underwater camera into tanks - t pump and alarm were operational at the service of the service	baffles ar	No ter. Ind tank walls OK. If the inspection.	 ☑ Probed tank(s) bottom ☑ Examined construction records ☐ Examined Tank Integrity Form (Attach) ☐ Observed liquid level below operating depth ☐ Examined empty (pumped) tanks(s) ☐ Probed outside tank(s) for "black soil" ☐ Unable to verify (See Comments/Explanation) ☑ Other methods not listed (See Comments/Explanation) 	tion)
3.	a. b.	b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety. ☐ Yes* ☒ No ☐ Unknown *System is an imminent threat to public health and safety Explain:				

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

Inspector initials/Date: 12/10/2019 **B**#

4.	Soil Separation – Compliance compor	nent #4 of 5			
	Date of installation: 1994	Unknown	Verification method(s):		
	Shoreland/Wellhead protection/Food Beverage Lodging?	☐ Yes ⊠ No	Soil observation does not expire. Pr		
	Compliance criteria:	observations by two independent parties are sufficient unless site conditions have been altered or local			
	For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: Drainfield has at least a two-foot vertical	☐ Yes ☐ No	requirements differ. Conducted soil observation(s) (Attach boring lower to the conducted soil observation) (Attach boring lower to the conducted boring low		
	separation distance from periodically saturated soil or bedrock.		Other (See Comments/Explanation	·	
	Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	⊠ Yes □ No	Comments/Explanation: Reviewed design and permit records	S.	
	Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*				
	"Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)	☐ Yes ☐ No	Indicate depths of elevations		
			A. Bottom of distribution media	See Attached Boring Log(s)	
	Drainfield meets the designed vertical		B. Periodically saturated soil/bedrock		
	separation distance from periodically saturated soil or bedrock.		C. System separation		
			D. Required compliance separation*		
	Any "no" answer above indicates the system is Failing to Protect Groundwater. *May be reduced up to 15 percent if allowed by Loc Ordinance.			allowed by Local	
5.	Operating Permit and Nitrogen B	MP* – Compliance of	component #5 of 5 Not appl	licable	
	Is the system operated under an Operating Per	mit?	No If "yes", A below is required		
	Is the system required to employ a Nitrogen BM		No If "yes", B below is required		
	BMP=Best Management Practice(s) specific				
	If the answer to both questions is "no",	this section does n	ot need to be completed.		
	Compliance criteria				
	a. Operating Permit number:		☐ Yes ☐ No		
	Have the Operating Permit requirements to	peen met?			
	b. Is the required nitrogen BMP in place and	properly functioning?	☐ Yes ☐ No		
	Any "no" answer indicates Noncom	nliance			

Property address: 10077 Julep Trl N, Forest Lake, MN 55073

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 TTY 651-282-5332 or 800-657-3864 • Available in alternative formats Page 3 of 3


<u>Midwest Sewer Testing</u> Subsurface Sewage Treatment System Owner/Property Information

This information will be used for the purpose of conducting an MPCA Compliance Inspection

Property Address: 10077 Julep Trl N, Forest Lake, MN	D + CI + D 1 10 2010	T: 0.20 ANA		
Property Owner: Jodi Stuber	Date of Inspection: December 10, 2019	Time: 9:30 AM		
Tank(s) Tank(s)Material Soil Treatment System Other Septic 2 Fiberglass Rock trench Rarobic Plastic Gravelless trench Experimental system Lift Metal Chamber trench Experimental system Other Mound Other system Other sy	Property Address: 10077 Julep Trl N, Forest Lake, MN	Zip: 55073		
Septic 2	Property Owner: Jodi Stuber	Phone: 651-433-2536		
performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system. Year house built: 1994 Year septic installed: 1994 Tank size (gals.): 2-1000 How long has seller owned the property? 2011 Number of residents in home? 3 Number of bedrooms? 3 Are all floors drained by gravity? Y Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? East Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in approximately 2015. When was the system last pumped? 9/26/2019 Name of pumper: Smilie's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N	Septic 2 □Fiberglass □Rock trench □Aerobic □Plastic □Gravelless trench □Lift □Metal □Chamber trench □Holding □Concrete □Seepage bed □Other: □Block □Mound □Other □At-grade	Alternative system Experimental system Cesspool system Other system		
the ground surface to facilitate access and proper maintenance of the system. Year house built: 1994 Year septic installed: 1994 Tank size (gals.): 2-1000 How long has seller owned the property? 2011 Number of residents in home? 3 Number of bedrooms? 3 Are all floors drained by gravity? Y Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? East Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in approximately 2015. When was the system last pumped? 9/26/2019 Name of pumper: Smilie's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N				
How long has seller owned the property? 2011 Number of residents in home? 3 Number of bedrooms? 3 Are all floors drained by gravity? Y Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? East Side Location of water well on lot? South Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in approximately 2015. When was the system last pumped? 9/26/2019 Name of pumper: Smilie's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N				
Number of bedrooms? 3	1			
Garbage disposal? N				
More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? East Side Location of water well on lot? South Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in approximately 2015. When was the system last pumped? 9/26/2019 Name of pumper: Smilie's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N				
Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? East Side Location of water well on lot? South Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in approximately 2015. When was the system last pumped? 9/26/2019 Name of pumper: Smilie's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N		N		
Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? East Side Location of water well on lot? South Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in approximately 2015. When was the system last pumped? 9/26/2019 Name of pumper: Smilie's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N				
Are there any additional systems on this property serving other buildings? N Location of septic system on lot? East Side Location of water well on lot? South Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in approximately 2015. When was the system last pumped? 9/26/2019 Name of pumper: Smilie's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	Does this property have any footing drain tiles connected to the septic system? N			
Location of septic system on lot? East Side Location of water well on lot? South Side Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in approximately 2015. When was the system last pumped? 9/26/2019 Name of pumper: Smilie's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	Are any buildings on this property such as garages or out-buildings connected to this system? N			
Location of water well on lot? South Side Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in approximately 2015. When was the system last pumped? 9/26/2019 Name of pumper: Smilie's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	Are there any additional systems on this property serving other buildings? N			
Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in approximately 2015. When was the system last pumped? 9/26/2019 Name of pumper: Smilie's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	Location of septic system on lot? East Side			
surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in approximately 2015. When was the system last pumped? 9/26/2019 Name of pumper: Smilie's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	<u> </u>	<u> </u>		
How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Y If yes, explain: Replaced lift pump and pipe between house and tank in			
Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	v i i	1		
Is your property located in a shoreland management area? N				
Do you have any additional information that should be given to the new owner? N				
	Do you have any additional information that should be given to the new owner? N			

I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing

Owner/Occupant: Jodi Stuber's Signature On File Date: 12/10/2019



Soil Observations Log

Location of Project: 10077 Julep Trl N, Forest Lake, MN 55073						
Observations Made By: Midwest Sewer Ser				,	Date:	12/10/19
Classifi	cation System:	USDA				
So	il Observation:	1		Soil O	bservation:	
Surface Elevation of Observation S3" below top of mound on original contour			face tion of vation			
Depth In Inches Rock %	Soils E	ncountered	Depth In Inches	Rock %	Soils	Encountered
0-12 12-18	10YR 4/4	Fine Sandy Loam Clay Loam With & 10YR 6/2 Redox				
12" Depth To End Of Soil Observation Or Redox			Depth T	o End Of Soil	Observation Or Redox	
+53" Elevation Of Observation Below Top Of Mound					tion Relative To System	
-28" Depth To Bottom Of Distribution Media					Distribution Media	
=37" Of Separation				Of Sepa	ration	
Fnd Of Soil	Observation At:	18"	Fnd Of	Soil Oh	servation At:	
	edox Present At:	12"	2.10 01		x Present At:	
	ater Present At:	None	Standi		r Present At:	
Tanana						

Bottom Of Distribution Medium At: 28 Inches			
Signature:	Offer Ula		



EARTH SCIENCE TESTINGTM SOILS INFORMATION COMPANY:

SOIL BORINGS

BORING NO.1

0" - 5" DRK. BRN. FINE SANDY LOAM 5' - 30"BRN. FINE SANDY CLAY LOAM 30"- 64" BRN. FINE SANDY CLAY LOAM (STIFF - MOTTLED) END BORING - 64"

BORING NO.2

0" - 5" DRK. BRN. FINE SANDY LOAM 5" - 24" BRN. FINE SANDY CLAY LOAM 24"- 64" BRN.FINE SANDY CLAY LOAM (STIFF - MOTTLED) END BORING - 64"

BORING NO.3

0" - 6" DRK. BRN. FINE SANDY LOAM
6" - 40" BRN. FINE SANDY CLAY LOAM
40" - 64" BRN. FINE SANDY CLAY LOAM (STIFF - MOTTLED)
END BORING - 64"

BORING NO. 4

0"- 5" DRK. BRN. FINE SANDY LOAM
5" - 36" BRN. FINE SANDY CLAY LOAM
36" - 64" BRN. FINE SANDY CLAY LOAM (STIFF - MOTTLED)
END BORING - 64"

DISCLAIMER

Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include only verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems

Non-transferable

Business License

Midwest Sewer Services

License # L2896

License Expires: 12/22/2020

Issued: 11/26/2019

Specialty Area(s):

Installer
Maintainer
Service Provider
Advanced Designer
Advanced Inspector

Designated Certified Individual(s):

Cert # Na

Name

Certification Expires:

C5342

Brian L Humpal

10/15/2023

Installer, Maintainer, Serv Prov, Adv Designer, Adv Inspector

C9852 4

Christopher R Uebe

3/4/2021

Designer, Inspector



520 Lafayette Road North St. Paul, Minnesota 55155-4194 Mich Haig

Nick Haig, Supervisor Certification and Training Unit