Midwest Sewer Services

P.O. Box 10853 White Bear Lake, MN 55110 Brian Humpal						
651-492-7550/Brian@Midwestsoiltesting.com MPCA Licensed Advanced Inspector						
SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT						
Date: March 16, 2020Time: 11:30 AMOwner: Craig & Lisa Johnson						
Inspection Address: 5 Baillon Ln, St. Mary's Point, MN 55043						

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the original design/permit records on file at Washington County. This system consists of two pre-cast septic tanks and a gravelless trench drainfield.

Although not a compliance criteria, it should be noted that gravelless pipe is no longer approved for installation in the State of Minnesota and we have had experience with this product having significantly reduced performance and/or life expectancy. We cannot guarantee the performance of this system beyond the compliance date (3/16/2020).

Predicated on my inspection of the system and my review of the original design/permit records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Midwest Sewer Services have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Midwest Sewer Services disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal

Minnesota Pollution	Co
Control Agency	
	Exist

520 Lafayette Road North St. Paul, MN 55155-4194

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspection results based on Minnesota Pollution Control Agency (MPCA)	
requirements and attached forms – additional local requirements may also apply.	

For local tracking purposes:

Submit completed form to Local Unit of Government (LUG) and system owner within 15 days

System Status

System status on date (mm/dd/yyyy): _____3/16/2020

Compliant – Certificate of Compliance

(Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)

Noncompliant – Notice of Noncompliance

(See Upgrade Requirements on page 3)

Reason(s) for noncompliance (check all applicable)

Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety

Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety

Tank Integrity (Compliance Component #2) – Failing to protect groundwater

Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater

Soil Separation (Compliance Component #4) – Failing to protect groundwater

Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant

Property Information

Parcel ID# or Sec/Twp/Range:

Baillon Ln, St. Mary's Point, MN 55043	Reason for inspection: Property Transfer
ig & Lisa Johnson	Owner's phone:651-436-6174
::	Representative phone:
ity: Washington County	Regulatory authority phone: 651-430-6655
n: Two pre-cast septic tanks and a gravelle	ess trench drainfield.
r	

Comments or recommendations:

Although not a compliance criteria, it should be noted that gravelless pipe is no longer approved for installation in the State of Minnesota and we have had experience with this product having significantly reduced performance and/or life expectancy. We cannot guarantee the performance of this system beyond the compliance date (3/16/2020).

Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.

Inspector name:	Brian Humpal/Christopher Uebe	Certification number:	C5342/C9852
Business name:	Midwest Sewer Services	License number:	L2896
Inspector signatur	e: Brian Humpal Afric Uh	Phone number:	651-492-7550
Necessary or	Locally Required Attachments		
🛛 Soil boring lo	ogs 🛛 System/As-built drawing	Forms per local ordinan	се
Other inform	ation (list). Report Summary Property Information	Disclaimer License	

2 of 9

1. Impact on Public Health – Compliance component #1 of 5

ystem discharge sewage to the round surface.	🗌 Yes 🖾 No
ystem discharge sewage to drain tile r surface waters.	🗌 Yes 🖾 No
ystem cause sewage backup into welling or establishment.	🗌 Yes 🖾 No

an Imminent Threat to Public Health and Safety.

Comments/Explanation:

None of the above found.

Verification method(s):

- Searched for surface outlet
- Searched for seeping in yard/backup in home
- Excessive ponding in soil system/D-boxes
- Homeowner testimony (See Comments/Explanation)
- "Black soil" above soil dispersal system
- System requires "emergency" pumping
- Performed dye test
- Unable to verify (See Comments/Explanation)
- Other methods not listed (See Comments/Explanation)

2. Tank Integrity - Compliance component #2 of 5

Compliance criteria:		Verification method(s):
System consists of a seepage pit, cesspool, drywell, or leaching pit.□ Yes ⊠ NoSeepage pits meeting 7080.2550 may be		 Probed tank(s) bottom Examined construction records Examined Tank Integrity Form (Attach)
<i>compliant if allowed in local ordinance.</i> Sewage tank(s) leak below their designed operating depth.	☐ Yes ⊠ No	 Observed liquid level below operating depth Examined empty (pumped) tanks(s)
If yes, which sewage tank(s) leaks:		Probed outside tank(s) for "black soil"
Any "yes" answer above indic system is Failing to Protect G		 Unable to verify (See Comments/Explanation) Other methods not listed (See Comments/Explanation)

Comments/Explanation:

Lowered underwater camera into tanks - baffles and tank walls OK.

3. Other Compliance Conditions – Compliance component #3 of 5

a.	Maintenance hole covers are damaged	 cracked, unsecured, 	or appear to structurally unsound.	□ Yes*	🖾 No	Unknown

b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety. \Box Yes* \boxtimes No \Box Unknown *System is an imminent threat to public health and safety

Explain:

c. System is non-protective of ground water for other conditions as determined by inspector □ Yes* ⊠ No *System is failing to protect groundwater

Explain:

Inspector initials/Date: 3/16/2020

4. Soil Separation – Compliance component #4 of 5

Date of installation: 1999	Unknown	Verification method(s):				
Shoreland/Wellhead protection/Food Beverage Lodging?	🗌 Yes 🛛 No	Soil observation does not expire. Previous soil observations by two independent parties are sufficient,				
Compliance criteria:		unless site conditions have been alt				
For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.	☐ Yes ☐ No	 requirements differ. Conducted soil observation(s) (Attach boring logs) Two previous verifications (Attach boring logs) Not applicable (Holding tank(s), no drainfield) Unable to verify (See Comments/Explanation) Other (See Comments/Explanation) 				
Non-performance systems built April 1,	🛛 Yes 🔲 No	Comments/Explanation:				
1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:		Reviewed design and permit record	S.			
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*						
"Experimental", "Other", or "Performance"	□ Yes □ No	Indicate depths of elevations				
systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)		A. Bottom of distribution media	See Attached Boring Log(s)			
Drainfield meets the designed vertical		B. Periodically saturated soil/bedrock				
separation distance from periodically saturated soil or bedrock.		C. System separation				
		D. Required compliance separation*				
Any "no" answer above indicates t Failing to Protect Groundwater.	he system is	*May be reduced up to 15 percent if Ordinance.	allowed by Local			
Operating Permit and Nitrogen B	MP* – Compliance	component #5 of 5 🛛 🛛 Not appl	icable			
Is the system operated under an Operating Per	mit?	No If "yes", A below is required				
Is the system required to employ a Nitrogen BM	IP? □Yes □	No If "yes", B below is required				
BMP=Best Management Practice(s) specif	fied in the system desig	gn				

If the answer to both questions is "no", this section does not need to be completed.

Compliance criteria

5.

a.	Operating Permit number: Have the Operating Permit requirements been met?	🗌 Yes 🗌 No
b.	Is the required nitrogen BMP in place and properly functioning?	Yes No

Any "no" answer indicates Noncompliance.


Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

<u>Midwest Sewer Testing</u> Subsurface Sewage Treatment System Owner/Property Information

Date of Inspection: March 16, 2020 Time: 11:30 AM Property Address: 5 Baillon Ln, St. Mary's Point, MN Zip: 55043 Property Owner: Craig & Lisa Johnson Phone: 651-436-6174 Tank(s) Tank(s) Tank(s)Material Soil Treatment System Other Aerobic Plastic Gravelless trench Experimental system	This information will be used for the purpose of conducting an MPCA Compliance Inspection.				
Property Owner: Craig & Lisa Johnson Phone: 651-436-6174 Tank(s) Tank(s)Material Soil Treatment System Other Septic 2 Fiberglass Rock trench Alternative system Alternative system Lift Metal Chamber trench Cesspool system Cesspool system Other: Block Mound Other system Other system Very house built: 1999 Yes No *If no, proper maintenance must be performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system. Year house built: 1999 Year septic installed: 1999 Tank size (gals.): 2-1000 How long has seller owned the property? 1999 Number of residents in home? 2-7 Number of bedrooms? 4 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have	Date of Inspection: March 16, 2020	Time: 11:30 AM			
Tank(s) Tank(s)Material Soil Treatment System Other Septic 2 Fiberglass Rock trench Alternative system Lift Metal Chamber trench Experimental system Other: Block Other Other: Block Other system Other: Block Other Part he tank maintenance covers accessible? Y es No Year house built: 1999 Year septic installed: 1999 Tank size (gals.): 2-1000 How long has seller owned the property? 1999 Number of residents in home? 2-7 Number of bedrooms? 4 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are there any additional systems on this property serv	Property Address: 5 Baillon Ln, St. Mary's Point, MN	1			
Septic 2 Fiberglass Rock trench Alternative system Aerobic Plastic Gravelless trench Experimental system Holding Concrete Seepage bed Other system Other: Block Mound Other system Other: Block Mound Other system Other: Block Mound Other system Year house built: 1999 Yes No Year house built: 1999 Year septic installed: 1999 Year house built: 1999 Year septic installed: 1999 Number of bedrooms? 4 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,					
performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system.Year house built: 1999Year septic installed: 1999Tank size (gals.): 2-1000How long has seller owned the property? 1999Number of residents in home? 2-7Number of bedrooms? 4Are all floors drained by gravity? Lower PumpedGarbage disposal? NWhirlpool bath? NMore than one system (laundry, etc.)? NDoes this property have any footing drain tiles connected to the septic system? NAre any buildings on this property such as garages or out-buildings connected to this system? NAre there any additional systems on this property serving other buildings? NLocation of septic system on lot? South SideLocation of water well on lot? North SideIs the well a deep well? YHave you ever experienced any problems with the system such as: tree roots, sewage back-ups,	Septic 2FiberglassRock trenchAerobicPlasticGravelless trenchLiftMetalChamber trenchHoldingConcreteSeepage bedOther:BlockMound	Alternative system Experimental system Cesspool system			
the ground surface to facilitate access and proper maintenance of the system. Year house built: 1999 Year septic installed: 1999 Tank size (gals.): 2-1000 How long has seller owned the property? 1999 Number of residents in home? 2-7 Number of bedrooms? 4 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? North Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,	Are the tank maintenance covers accessible? \square Yes \square No *If r	no, proper maintenance must be			
How long has seller owned the property? 1999 Number of residents in home? 2-7 Number of bedrooms? 4 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? North Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,					
Number of bedrooms? 4 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? North Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,	Year house built: 1999Year septic installed: 1999T	Tank size (gals.): 2-1000			
Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? North Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,	How long has seller owned the property? 1999 Number of res	sidents in home? 2-7			
More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? North Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,	Number of bedrooms? 4Are all floors drained by gr	avity? Lower Pumped			
Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? North Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,	Garbage disposal? N Whirlpool bath?	N			
Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? North Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,					
Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? North Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,	Does this property have any footing drain tiles connected to the sep	ptic system? N			
Location of septic system on lot? South Side Location of water well on lot? North Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,	Are any buildings on this property such as garages or out-buildings	s connected to this system? N			
Location of water well on lot? North SideIs the well a deep well? YHave you ever experienced any problems with the system such as: tree roots, sewage back-ups,	Are there any additional systems on this property serving other built	ldings? N			
Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,	Location of septic system on lot? South Side				
	Location of water well on lot? North Side Is the	well a deep well? Y			
surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain:					
When was the system last pumped? 2018Name of pumper: Pinky's Sewer Service					
How often pumped in previous years? Every 2-3Is system on a monitoring plan? N	How often pumped in previous years? Every 2-3 Is system				
Have you received notices from any government agency concerning this system? N	Have you received notices from any government agency concernin	ig this system? N			
Is your property located in a shoreland management area? N					
Do you have any additional information that should be given to the new owner? N	Do you have any additional information that should be given to the	e new owner? N			

I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing

Owner/Occupant:



Soil Observations Log

	Location of Project: 5 Baillon Ln, St. Mary's Point, MN 55043						
	oservati	ons Made By:	Midwest Sewer Ser				3/16/2020
C	Classific	ation System:	USDA				
	Soil	Observation:	ST-1		Soil O	bservation:	
	face tion of vation	-	nd surface as last Tield trench	Elevat	face tion of vation		
Depth In Inches	Rock %	<u>Soils E</u>	ncountered	Depth In Inches	Rock %	<u>Soils</u>	Encountered
0-7 7-33 33-48 48-80		7.5YR 2.5, 7.5YR 4/3 10YR 4/4	7/2 Loamy Sand 73 Medium Sand 8 Medium Sand 9 Medium Sand				
80"	Depth T	o End Of Soil O	bservation Or Redox		Depth T	o End Of Soil	Observation Or Redox
Same	Elevatio	on Of Observatio	n Relative To System	m Elevation Of Observation Relative To System			ion Relative To System
-25"	Depth T	o Bottom Of Dis	Depth To Bottom Of Distribution Media			Distribution Media	
≥55"	Of Sepa				Of Sepa		
			00"				
End		Observation At:	80"	End Of		servation At:	
Cherr		dox Present At:	None	Redox Present At:			
Stan	iung wa	ater Present At:	None	Standing Water Present At:			

Bottom Of Distribution Medium At: 25 Inches

Signature:

After the

DISCLAIMER

Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems Non-transferable Business License

Midwest Sewer Services

License # L2896

License Expires: 12/22/2020

Issued: 11/26/2019

Specialty Area(s):

Installer Maintainer Service Provider Advanced Designer Advanced Inspector

Designated Certified Individual(s):

Cert #	Name	Certification Expires:
C5342	Brian L Humpal	10/15/2023
	Installer, Maintainer, Serv Prov, Adv Designer, Adv Inspector	
C9852 <	Christopher R Uebe	3/4/2021
	Designer, Inspector	

MINNESOTA POLLUTION CONTROL AGENCY

520 Lafayette Road North St. Paul, Minnesota 55155-4194

Haig

Nick Haig, Supervisor Certification and Training Unit