DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Mainter	nance Ullubaco Reason fo	r Maintenance:	V #	3916+ 18773	
Property Address: 23219 87-Counting Property Owner's Name: Sus an Miles					
Municipality: Scardia State NV Zip Code 85073 GEO Code/Property I.D. #:					
What was done to the system?		Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Ta	nk in Student	Level in Several and in	
	Sludge and scum measured.		nk in. Sludge I	Level in Scum Level in.	in.
Do tanks need to be pumped? Yes No (If no provide measurements)		Total (Sludge + Sc	tum) / Liquid Lev	/ Liquid Level = % Sludge & Scum	
		JL			
1. Access used to remove septage: Maintenance Hole Cother (Go to #3 below) * Tank must be pumped if this value is greater than 25%.					
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain					
Explanation:					
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:					
(owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
Tank#1 Yes No Verificatio Method Used:					
Tanker F : Tes F No Verificatio Method Osed.					
Tank#2 Ye	es No Verificatio Method U	sed:			
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	Yes KNo	Yes A No	
	Septic/Holding Tank #2	Yes No	Yes A No	Yes A No	
	Pretreatment Tank	Yes No	Yes No	☐ Yes ☐ No	
	Pump Tank	Yes No	Yes No	☐ Yes ☐ No	
6. How many galions of septage were removed?					
Tank #1 1000 Tank #2 1000 Pretreatment Tank Pump Tank					
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
, out morning	icioni. List arry troublesilooting,	minor repairs cond	ucted, tank safety conce	rns, or other concerns.	
9 Cortifications	I havabu annifu an a Canta - £88in.	and the bear			
8. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.					
Maintainer's Name: OSSI Maintainer's Address: 17638 Lyons St NE, Forest Lake of					
Maintainer's License #: All Maintainer's Phone #:					
Maintainer's Si	gnatureOSSI		Date: 4/	16/2020	