Midwest Sewer Services

P.O. Box 10853 White Bear Lake, MN 55110 651-492-7550/Brian@Midwestsoiltesting.com

Brian Humpal MPCA Licensed Advanced Inspector

SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

Inspection Address: 2440 Periwinkle Ave N, West Lakeland, MN 55082

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the original design/permit records on file at Washington County. This system consists of two pre-cast septic tanks, a pre-cast lift tank, and a chamber trench drainfield.

It should be noted that the chamber drainfield trenches are nearly filled or completely filled with soil. This is most likely the result of animal activity and/or soil infiltration into the chambers. The total capacity of the drainfield has been significantly reduced and could surface onto the ground and/or back-up into the house at anytime in the near future and/or when the system is placed back in service. If this occurs, this system would be considered an imminent threat to public health and safety.

My inspection indicates that this system is presently "non-compliant" and is an imminent threat to public health and safety in accordance with MPCA rules 7080.1500 Subp.4(A) because of the potential for sewage to back-up into the house or discharge onto the ground.

In accordance with MPCA rules, I am sending a copy of this complete report to Washington County. I cannot officially speak on behalf of the County relative to the upgrade requirements of these non-compliant systems. Please contact the Washington County Department of Public Health & Environment (651-430-6655) to verify the County's position.

Please advise buyer, agents, lender, etc. to contact me should they have any questions regarding this system.

Christopher Uebe

Brian Humpal

Brian Humpal



Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspection results based on Minnesota Pollution Control Agency (MP requirements and attached forms – additional local requirements may also apply.	CA) For local tracking purposes:
Submit completed form to Local Unit of Government (LUG) and system own within 15 days	er
System Status	
System status on date (mm/dd/yyyy):6/15/2020	
<u> </u>	compliant – Notice of Noncompliance Upgrade Requirements on page 3)
Reason(s) for noncompliance (check all applicable) □ Impact on Public Health (Compliance Component #1) – Imminent thre □ Other Compliance Conditions (Compliance Component #3) – Imminent □ Tank Integrity (Compliance Component #2) – Failing to protect grount □ Other Compliance Conditions (Compliance Component #3) – Failing to protect grount □ Soil Separation (Compliance Component #4) – Failing to protect grount □ Operating permit/monitoring plan requirements (Compliance Component	nt threat to public health and safety dwater to protect groundwater undwater
Property Information Parcel ID# or Sec/Twp/	Range:
	son for inspection: Property Transfer
· · ·	er's phone:
or	•
Owner's representative: Repr	resentative phone:
Local regulatory authority: Washington County Regu	ulatory authority phone: 651-430-6655
Brief system description: _ Two pre-cast septic tanks, a pre-cast lift tank, and a c	hamber trench drainfield.
Comments or recommendations: The chamber drainfield trenches are nearly filled or completely filled with soil. This soil infiltration into the chambers. The total capacity of the drainfield has been sign ground and/or back-up into the house at anytime in the near future and/or when the this system would be considered an imminent threat to public health and safety.	ificantly reduced and could surface onto the
Certification	
I hereby certify that all the necessary information has been gathered to determine determination of future system performance has been nor can be made due to unipossible abuse of the system, inadequate maintenance, or future water usage.	· · · · · · · · · · · · · · · · · · ·
Inspector name: Brian Humpal/Christopher Uebe Certi	ification number: C5342/C9852
	License number: L2896
Inspector signature: Brian Thumpal form the	Phone number: 651-492-7550
Necessary or Locally Required Attachments	
•	per local ordinance
☑ Other information (list): Report Summary, Property Information, Disclaime	
, ,	

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 1 of 3

Property address: 2440 Periwinkle Ave N, West Lakeland, MN 55082

Inspector initials/Date: _6/15/2020 **BA**

1.	lm	npact on Public Health – Cor	npliance compone	nt #1 of 5				
	Co	ompliance criteria:		Verification method(s):				
		stem discharge sewage to the bund surface.	⊠ Yes □ No	✓ Searched for surface outlet✓ Searched for seeping in yard/backup in home				
		stem discharge sewage to drain tile surface waters.	☐ Yes ⊠ No	 Excessive ponding in soil system/D-boxes Homeowner testimony (See Comments/Explanation) "Black soil" above soil dispersal system 				
		stem cause sewage backup into velling or establishment.	⊠ Yes □ No	System requires "emergency" pumping Performed dye test				
		ny "yes" answer above indicates Imminent Threat to Public Heal		☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)				
	Сс	mments/Explanation:						
2	an on If t	d/or soil infiltration into the chambers. to the ground and/or back-up into the l his occurs, this system would be cons	The total capacity of house at anytime in idered an imminent f	ely filled with soil. This is most likely the result of animal activity if the drainfield has been significantly reduced and could surface the near future and/or when the system is placed back in service. Threat to public health and safety.				
2.		ank Integrity – Compliance com	iponent #2 of 5	Verification method(s):				
		•	☐ Yes ⊠ No	☑ Probed tank(s) bottom				
		stem consists of a seepage pit, sspool, drywell, or leaching pit.	☐ Tes ☐ No	 ☑ Examined construction records 				
		epage pits meeting 7080.2550 may be mpliant if allowed in local ordinance.		Examined Tank Integrity Form (Attach)Observed liquid level below operating depth				
	de	wage tank(s) leak below their signed operating depth.	☐ Yes ⊠ No	Examined empty (pumped) tanks(s)Probed outside tank(s) for "black soil"				
	A	ves, which sewage tank(s) leaks: ny "yes" answer above indicates vistem is Failing to Protect Gro		☐ Unable to verify (See Comments/Explanation)☐ Other methods not listed (See Comments/Explanation)				
3.	Co Lo Lif	omments/Explanation: wered underwater camera into tanks - t pump and alarm were operational at ther Compliance Conditions	baffles and tank wa	ection.				
	a.	. Maintenance hole covers are damaged, cracked, unsecured, or appear to structurally unsound. ☐ Yes* ☒ No ☐ Unknown						
	b.	Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety. \square Yes* \square No \square Unknown *System is an imminent threat to public health and safety						
		Explain:						
	C.	System is non-protective of ground wa *System is failing to protect ground Explain:		ns as determined by inspector ☐ Yes* ☒ No				

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

Inspector initials/Date: 6/15/2020 **BA** Property address: 2440 Periwinkle Ave N, West Lakeland, MN 55082 **Soil Separation** – Compliance component #4 of 5 Date of installation: 1996/2007 Unknown Verification method(s): Shoreland/Wellhead protection/Food Beverage ☐ Yes ⊠ No Soil observation does not expire. Previous soil Lodging? observations by two independent parties are sufficient, unless site conditions have been altered or local Compliance criteria: requirements differ. For systems built prior to April 1, 1996, and ☐ Yes ☐ No not located in Shoreland or Wellhead ☐ Conducted soil observation(s) (Attach boring logs) Protection Area or not serving a food. ☐ Two previous verifications (Attach boring logs) beverage or lodging establishment: Not applicable (Holding tank(s), no drainfield) Drainfield has at least a two-foot vertical ☐ Unable to verify (See Comments/Explanation) separation distance from periodically ○ Other (See Comments/Explanation) saturated soil or bedrock. ☐ Yes ☐ No Non-performance systems built April 1, Comments/Explanation: 1996, or later or for non-performance Chamber Trenches Are Full Of Soil systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.* "Experimental", "Other", or "Performance" ☐ Yes ☐ No Indicate depths of elevations systems built under pre-2008 Rules; Type IV See Attached or V systems built under 2008 Rules (7080. Boring Log(s) A. Bottom of distribution media 2350 or 7080.2400 (Advanced Inspector License required) B. Periodically saturated soil/bedrock Drainfield meets the designed vertical separation distance from periodically C. System separation saturated soil or bedrock. D. Required compliance separation* Any "no" answer above indicates the system is *May be reduced up to 15 percent if allowed by Local Failing to Protect Groundwater. Ordinance. 5. Operating Permit and Nitrogen BMP* – Compliance component #5 of 5 Not applicable ☐ Yes ☐ No If "yes", A below is required Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP? ☐ Yes ☐ No If "yes", B below is required BMP=Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria a. Operating Permit number: ☐ Yes ☐ No Have the Operating Permit requirements been met?

Any "no" answer indicates Noncompliance.

b. Is the required nitrogen BMP in place and properly functioning?

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

☐ Yes ☐ No


www.pca.state.mn.us • 651-296-6300 • 800-657-3864 TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 3 of 3

Midwest Sewer Testing Subsurface Sewage Treatment System Owner/Property Information This information will be used for the purpose of conducting an MPCA Compliance Inspection.

This information will be used for the purpose of conducting an MPCA	Compilance inspection.					
Date of Inspection: 6/10/2020 & 6/15/2020	Time: 9:45 AM & 12:15 PM					
Property Address: 2440 Periwinkle Ave N, West Lakeland, MN	Zip: 55082					
Property Owner: Dave Hughes	Phone:					
Tank(s) Tank(s)Material Soil Treatment System Septic 2 Fiberglass Rock trench Aerobic Plastic Gravelless trench Lift Metal Chamber trench Holding Concrete Seepage bed Other: Block Mound Other At-grade	Other Alternative system Experimental system Cesspool system Other system					
Are the tank maintenance covers accessible? Yes No *If i performed through the maintenance holes. Maintenance hole cover the ground surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and proper maintenance of the second surface to facilitate access and the sec	ers should be made accessible to					
Year house built: 1996 Year septic installed: 1996/2007						
	sidents in home?					
Number of bedrooms? 4 Are all floors drained by gr	3					
Garbage disposal? Whirlpool bath?						
More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the se	ntia gyatam?					
Are any buildings on this property such as garages or out-building	-					
Are there any additional systems on this property serving other but	ildings?					
Location of septic system on lot? Tanks - Northwest Side, Drainfie	eld - Southeast Side					
	well a deep well? Y					
Have you ever experienced any problems with the system such as: surfacing of sewage onto the ground, septic tank overflowing, etc. to the system? If yes, explain:						
	per: Meyer Sewer Service					
	on a monitoring plan?					
Have you received notices from any government agency concerning	ng this system?					
Is your property located in a shoreland management area? N						
Do you have any additional information that should be given to the	e new owner?					
I hereby certify that the above information is correct to the best of my knowledge considered "non-compliant/failing" per MPCA rules, that the inspector must by local government unit within 15 days of the date of inspection completion. I also this report, that I/we are ultimately responsible for payment of all fees for all wor by Inspect Minnesota and Midwest Soil Testing	law submit a copy of this report to the so agree that unless otherwise noted in					

Date:


Owner/Occupant:



e: 06-20-07	No 44° 59.039 Wo 92° 47.296	N 44° 59. C 13 w 92° 92. 315	N 59.008 No 42.325	N 440 59.014 WU 92° 47.331
Depth in Feet	B1	B2		Black Loan
	Black sild Loom mix (4.11)		Black silthan Topsoil	Topsoil
	1 mediun prop	Topsoul		
	13 y 413		e	
	2 h.x d. 45 1 1 1000	Cark brown fine		
	ficary michalle	10 y 2/3	Red brown	30
	28" b	Acdium brown	5,1+ Luan	Red brown
		Loam	571413	fru SANDY
	Hark brown : 14. 22	10 gr 4/3	16. Red browns	54×5/3 44
	4	medium brown	5yr 5/3	Red brown
1	This are has bee	134×4/3	- 0	Fin 5AND 54x 5/3
	graded X	1990 713	60	39, 3/3
	В	Red bown free	6	2
		3 AND 5 8 5/3	Red bown from	72
	8	* Light redox	1	
		@ 68.1	clamp'	
		The second secon		
		- 1		

/		EARTH SCIENCE SOIL TESTING
	000000000000000000000000000000000000000	
	7	A SOILS INFORMATION COMPANY:
		}
	40	LA CON DODINGS
		SOIL BORINGS
	18	W.L.L. TOWNSHIP
	Commence.	W.L.L. TOWNSHIP
		LOT 2 BLOCK 1 PHASE 2
	BORING N	O.1 DARK BROWN FINE SILTY LOAM
	0"-17" 17"-32"	LIGHT RROWN FINE SILTY LOAM
	32"-50"	LIGHT BROWN FINE TO MEDIUM LOAMY SAND, ROCKS
	50"-7'0"	LIGHT TAN FINE SAND
	7'0"-8'0"	BROWN COARSE SAND AND GRAVEL
	8'0"	END BORING
	• •	
	BORING N	0.2
	0"-12"	DARK BROWN FINE SILTY LOAM
	12"-26"	LIGHT BROWN FINE SILTY LOAM
	26"-46"	LIGHT BROWN FINE LOAMY SAND, ROCKS
	46"-8'0"	LIGHT BROWN MEDIUM TO COARSE SAND AND GRAVEL
	8'0"	END BORING .
	BORING N	0.1
	0"-16"	DARK BROWN FINE SILTY LOAM
	16"-27"	LIGHT BROWN FINE SILTY LOAM
	27"-60"	LIGHT BROWN FINE LOAMY SAND, ROCKS
	60"-8'0"	LIGHT TAN MEDIUM TO COARSE SAND AND GRAVEL
	8'0"	END BORING
	BORING N	
	0"-15"	DARK BROWN FINE SILTY LOAM LIGHT BROWN FINE SILTY LOAM
	15"-31" 31"-40"	LIGHT BROWN FINE SILTY LOAM LIGHT BROWN FINE LOAMY SAND, ROCKS
	40"-66"	LIGHT BROWN FINE TO MEDIUM LOAMY SAND
	66"-8'0"	LIGHT BROWN MEDIUM SAND AND ROCKS
	8'0"	END BORING
	2.4	

SITE EVALUATION		COUNTY	USE ONLY	□ NEW		CLASS V	-	
VALUATOR:			☐ EXISTING ☐ DWELLING		☐ COMMERCIAL ESTABLISHMENT ☐ FBL ESTABLISHMENT			
EVALUATOR: (14215 LE CHAIT- PROPERTY ADDRESS: 2440 PERININKE AVE DATE: TIME: 1			× 1	GEOCODE:			IOTECTION AREA	
ATE: 5 SEP 7007	TIME:	:45						
Jer wer	70		L REVIEW					
OIL CLASSIFICATION:			PARENT MAT	ERIAL:				
SOIL BOR	R.	/ B2		SOIL BORING 2				
LEVATION OF BORING:	LOCATION:		ELEVATION			LOCATION:		
SPS COORDINATES: LAT:	LON:	□ PROBE		NATES: LAT: BORING	- 0	LON:	□ PROBE	
SOIL HORIZON DEPTH (IN) TEXTURE COLOR	STRUCTURE	REDOXIMORPH			COLOR	STRUCTURE	REDOXIMORPHIC FEATURES	
0"- 11" SANDA 107R	SBK	No						
111-32" SINT 104F	SBK							
32'-50" sano 107t	SBK							
50-52 5ANO 12/4	56							
52" 0357 FUELION				-				
				L				
			EW CONCLU	IONS	SOIL.	rexture:	_	
pa⊈-SITE SUITABLE □ UNSUITABLE SOIL STA	NDING WATER:		PTH INFORMATION:			SOIL SIZING FACTOR:		
☐ DISTURBED SOIL	OCK: MAXIMUM DEPTH			PTH OF SYSTEM: LINEAR LOADING RATE:				
- COMPACTED SOIL		Jo		24				
CHECK ALL THAT A	ebi Y		TE REVIEW ASEMENTS ON LO	T:		SETBACKS		
□ WETLAND OR WETLAND VEGET			D UTILITY	BLUF	LINE			
☐ POND, LAKE, STREAM, RIVER ☐ FLOODPLAIN						RIVER		
☐ 10 YEAR FLOOD ELEVATION			PON		POND, LAKE, STREAM, WETLAND			
☐ BLUFFLINE ☐ WELL WELL CASING DEPTH:			- Onex		WELL			
COMMENTS/NOTES:								
		-						



DISCLAIMER

Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems

Non-transferable

Business License

Midwest Sewer Services

License # L2896

License Expires: 12/22/2020

Issued: 11/26/2019

Specialty Area(s):

Installer
Maintainer
Service Provider
Advanced Designer
Advanced Inspector

Designated Certified Individual(s):

Cert # Na

Name

Certification Expires:

C5342

Brian L Humpal

10/15/2023

Installer, Maintainer, Serv Prov, Adv Designer, Adv Inspector

C9852 4

Christopher R Uebe

3/4/2021

Designer, Inspector



520 Lafayette Road North St. Paul, Minnesota 55155-4194 Mich Haig

Nick Haig, Supervisor Certification and Training Unit