OUTENIMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

		Creston I	ocation			
Address 1/0// 2	9 1 / /	System L	ocation	Telephone Number		
Address 1042		He. S				
city Hasth	95		2003	roperty ID No./GEO Code		
Owner Char	lie Swanson	Pumping Date	9/24/15		······································	
		Contro	actór /			
Naintainer MEY	ER SEWER	MPCA License	No. 915	Telephone Number 6	51-459-016	
What wa	as done to the system?			port Liquid Capacity in G		
Tank(s) Pumped		Tank 1: 1000 Pumped Tank 2: 1000 Pumped				
Sludge and scum measured.			Tank 3:	Pumped Tank 4:	Pumped	
Do tanks need to be pumped? Yes No (If no provide measurements below)			Total Gallons Pumped: 2000			
					aliance inspection	
Visual Inspection	(note any problems with	the system):	NOTE: INIS	does not serve as a com	priarice inspections	
	*Tank Meas	urements-Use Onl	y If Tank(s) Were N	IOT Pumped		
Tank Length	in. 🗶 Tank Width	in. X Tank (Depth in.	= Tank Volume (cubic in	ches)	
Tank Radius	in. X Tank Radius	in. X 3.14	= Tank Volume (cubic inches)	····	
Tank Volume (cu. in		= Liquid Capacity	Gallon	s/ Tank Depth in. =	Gallons/Inch	
Sludge Level	in. X Gallons Per Inch	= Sludge	Volume G	allons		
Scum Level	in. X Gallons Per Inch	= Scum V	olume G	allons		
Sludge Volume	+ Scum Volume	= Total Si	udge and Scum Vol	ume Gallons		
·	-		-		ak %	
Total Sludge and So	cum Volume	Liquid Capacity	= Perce	ent Sludge and Scum in Tar	nk	
		₩		*Tanks must be pum		
				following conditions 1. The top of the sluce	s exist: dge layer is less than	
Scum Layer				12 inches from the b	oottom of the outlet	
Effluent			ink Depth measured	2. Total sludge and s	scum volume is great	
		and the second of the second o	om invert of outlet pe to bottom of tar	than 25 percent of t	he tank's liquid	
Sludge Layer				capacity.		
Signature		Date	9/04/1	5	Reset Form	