Midwest Sewer Services

P.O. Box 10853 White	Bear Lake, MN 55110	Brian Humpal
651-492-7550/Brian@N	fidwestsoiltesting.com	MPCA Licensed Advanced Inspector
SUBSURFACE SEWAG	GE TREATMENT SYS	TEM (SSTS) COMPLIANCE REPORT
Date: July 29, 2020	Time: 12:30 PM	Owner: Mark & Ginger Bollinger
Inspection Address: 7034	Goodview Ave S, Cottag	ge Grove, MN 55016

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system, have reviewed the history of the system with the owner, Mark Bollinger, and have reviewed the original design/permit records, along with a previous compliance inspection from 2010, which were on file at Washington County. This system consists of two pre-cast septic tanks and a rock trench drainfield.

Predicated on my inspection of the system, my review of the history of the system with the owner, and my review of the records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Midwest Sewer Services have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Midwest Sewer Services disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal

Minnesota Pollution Control Agency 520 Lafayette Road North St. Paul, MN 55155-4194

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspection results based on Minnesota Pollution Control Agency (MPCA)
requirements and attached forms – additional local requirements may also apply.

For local tracking purposes:

Submit completed form to Local Unit of Government (LUG) and system owner within 15 days

System Status

System status on date (mm/dd/yyyy): 7/29/2020

Compliant – Certificate of Compliance

(Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)

Noncompliant – Notice of Noncompliance

(See Upgrade Requirements on page 3)

Reason(s) for noncompliance (check all applicable)

Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety

Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety

Tank Integrity (Compliance Component #2) – Failing to protect groundwater

Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater

Soil Separation (Compliance Component #4) – Failing to protect groundwater

Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant

Property Information

Parcel ID# or Sec/Twp/Range:

Property address:	7034 Goodview Ave S, Cottage Grove, MN 55016	Reason for inspection: Property Transfer
Property owner:	Mark & Ginger Bollinger	Owner's phone: 303-589-7289
or		
Owner's represen	tative:	Representative phone:
Local regulatory a	uthority: Washington Counyt	Regulatory authority phone: 651-430-6655
Brief system desc	ription: <u>Two pre-cast septic tanks and a rock trench de</u>	rainfield.
Comments or reco	mmendations:	

Comments or recommendations:

Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.

Inspector name:	Brian Hump	al/Christopher Uebe	Certification number:	C5342/C9852
Business name:	Midwest Se	wer Services	License number:	L2896
Inspector signatur	те: Z	vian Humpal After the	Phone number	651-492-7550
Necessary or	Locally R	equired Attachments		
🛛 Soil boring lo	ogs	System/As-built drawing	Forms per local ordina	nce
🛛 Other inform	ation (list):	Report Summary, Property Informa	ation, Disclaimer, License	

2 of 10

1. Impact on Public Health – Compliance component #1 of 5

Property address: <u>7034 Goodview Ave S, Cottage Grove, MN 55016</u>

Compliance criteria:		Verification method(s):
System discharge sewage to the ground surface.	🗌 Yes 🛛 No	Searched for surface outletSearched for seeping in yard/backup in home
System discharge sewage to drain tile or surface waters.	🗌 Yes 🖾 No	 Excessive ponding in soil system/D-boxes Homeowner testimony (See Comments/Explanation) "Disal asil" share asil dimensional system
System cause sewage backup into dwelling or establishment.	🗌 Yes 🛛 No	 "Black soil" above soil dispersal system System requires "emergency" pumping Performed dye test
Any "yes" answer above indicates an Imminent Threat to Public Heal		 Unable to verify (See Comments/Explanation) Other methods not listed (See Comments/Explanation)
Comments/Explanation:		

2. Tank Integrity – Compliance component #2 of 5

Compliance criteria:		Verification method(s):
System consists of a seepage pit,	🗌 Yes 🛛 No	Probed tank(s) bottom
cesspool, drywell, or leaching pit.		Examined construction records
Seepage pits meeting 7080.2550 may be		Examined Tank Integrity Form (Attach)
compliant if allowed in local ordinance.		Observed liquid level below operating depth
Sewage tank(s) leak below their designed operating depth.	🗌 Yes 🛛 No	Examined empty (pumped) tanks(s)
If yes, which sewage tank(s) leaks:		Probed outside tank(s) for "black soil"
-		Unable to verify (See Comments/Explanation)
Any "yes" answer above indic system is Failing to Protect G		Other methods not listed (See Comments/Explanation)

Comments/Explanation:

None of the above found.

Lowered underwater camera into tanks - baffles and tank walls OK.

3. Other Compliance Conditions – Compliance component #3 of 5

a.	Maintenance hole covers are damaged, cracked, unsecured, or appear to structurally unsound.	☐ Yes*	🛛 No	🗌 Unknown

b. Other issues *(electrical hazards, etc.)* to immediately and adversely impact public health or safety. \Box Yes* \boxtimes No \Box Unknown *System is an imminent threat to public health and safety

Explain:

c. System is non-protective of ground water for other conditions as determined by inspector □ Yes* ⊠ No *System is failing to protect groundwater

Explain:

4. Soil Separation – Compliance component #4 of 5

Date of installation: 2003	Unknown	Verification method(s):	
Shoreland/Wellhead protection/Food Beverage Lodging?	🗌 Yes 🛛 No	Soil observation does not expire. Pre	
Compliance criteria:		observations by two independent pa unless site conditions have been alte	
For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.	☐ Yes ☐ No	 requirements differ. Conducted soil observation(s) (Attach boring logs) Two previous verifications (Attach boring logs) Not applicable (Holding tank(s), no drainfield) Unable to verify (See Comments/Explanation) Other (See Comments/Explanation) 	
Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	🛛 Yes 🔲 No	Comments/Explanation: Reviewed previous compliance insp Reviewed deisgn and permit records	
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*			
"Experimental", "Other", or "Performance"	🗌 Yes 🔲 No	Indicate depths of elevations	
systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)		A. Bottom of distribution media	See Attached Boring Log(s)
Drainfield meets the designed vertical		B. Periodically saturated soil/bedrock	
separation distance from periodically saturated soil or bedrock.		C. System separation	
		D. Required compliance separation*	
Any "no" answer above indicates t Failing to Protect Groundwater.	he system is	*May be reduced up to 15 percent if Ordinance.	allowed by Local
Operating Permit and Nitrogen B	MP* – Compliance of	component #5 of 5 🛛 🛛 Not appl	icable
Is the system operated under an Operating Per	mit? 🗌 Yes 🗌	No If "yes", A below is required	
Is the system required to employ a Nitrogen BM	1P? 🗌 Yes 🗌	No If "yes", B below is required	
BMP=Best Management Practice(s) specif	ïed in the system desig	n	
If the answer to both questions is "no",	this section does n	ot need to be completed.	

Compliance criteria

5.

a.	Operating Permit number: Have the Operating Permit requirements been met?	Yes No
b.	Is the required nitrogen BMP in place and properly functioning?	Yes No

Any "no" answer indicates Noncompliance.


Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

<u>Midwest Sewer Testing</u> Subsurface Sewage Treatment System Owner/Property Information

This information will be used for the purpose of conducting an MPCA	
Date of Inspection: July 29, 2020	Time: 12:30 PM
Property Address: 7034 Goodview Ave S, Cottage Grove, MN	Zip: 55016
Property Owner: Mark & Ginger Bollinger	Phone: 303-589-7289
$Tank(s)$ $Tank(s)Material$ Soil Treatment System \square Septic 2 \square Fiberglass \square Rock trench	Other Alternative system
AerobicPlasticGravelless trenchLiftMetalChamber trench	Experimental system Cesspool system
Holding Concrete Seepage bed	Other system
Other: Block Mound	
Other At-grade	
Are the tank maintenance covers accessible? Xes INO *If:	
performed through the maintenance holes. Maintenance hole cover	ers should be made accessible to
the ground surface to facilitate access and proper maintenance of t	he system.
Year house built: 2003 Year septic installed: 2003	Tank size (gals.): 1-1500, 1-1000
	sidents in home? 2
Number of bedrooms?5Are all floors drained by g	ravity? Y
Garbage disposal? Y Whirlpool bath?	Y
More than one system (laundry, etc.)? N	
Does this property have any footing drain tiles connected to the se	ptic system? N
Are any buildings on this property such as garages or out-building	s connected to this system? N
Are there any additional systems on this property serving other bu	ildings? N
	C
Location of septic system on lot? West Side	
	e well a deep well? Y
Have you ever experienced any problems with the system such as	1
surfacing of sewage onto the ground, septic tank overflowing, etc.	
to the system? N If yes, explain:	
	0.11.1.1
	per: Schlomka's
	n on a monitoring plan? N
Have you received notices from any government agency concerning Is your property located in a shoreland management area? N	
Do you have any additional information that should be given to th	a now owner? N
Do you have any additional information that should be given to th	e new owner? IN

I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing

6 of 10



.,

a

Log Of Soil Borings

Locat	ion of Project:	7034 Goodview Ave S,	Cottage Gr	ove, MN	
	ings Made By:	Inspect Minnesota		Date:	2/23/10
	Auger Used:	Hand/Bucket	Class	ification System:	USDA
Bo	oring Number:	1		Boring Number:	
Surface Elevation of Boring		l surface at last drop spection pipe	Surface Elevation Boring		
Depth In Inches	<u>Soils E</u>	ncountered	Depth In Inches	<u>Soils Er</u>	ncountered
0-18 18-44 44-54 54-70	7.5YR 4 7.5YR 4/4 F	5/2 Silt Loam 1/4 Silt Loam Tine Sandy Loam amy Sand & Gravel			
70" De	pth To End Of B	oring Or Mottled Soils		Depth To End Of B	oring Or Mottled Soils
Same Ele	vation Of Boring	g Relative To System		Elevation Of Boring	Relative To System
-34" De	pth To Bottom (Separation			Depth To Bottom C Of Separation	
En	d Of Boring At:	70"	,	End Of Boring At:	
	Soil Present At:	None	Mottle	ed Soil Present At:	· · · · · · · · · · · · · · · · · · ·
Standing Wa	ter Present At:	None		Water Present At:	

Bottom Of Distribution Medium At: _____34 ___ Inches

LOB OF BOIL BORNIOS

Depth Feet	#1	82			
		n loan medium bra sind wash	10 - 1 10 yr 30	11 10yr3	
		10 loan 10yr3/3	Red brown	silt learn	
· · · · · ·	Red browns		20 ' Byr 40	Red bravn Syr 41.	\$(1†:120 }
	5yr43			34	
	A Red brown 1	5yr 4/3	sult 1000 ped brawn Sand and Syr 4/3	loarny State	J
	sandand Syr4 3	Georef	Red brow sand an	ncoarse 1 much meaning	mbale
		GE Sandy SI mottede	rougific gravel	silt loam loyr 72	
-	7				
	E		·	• •	

Jobs Lot 2 Acom Ridge Cottage Grove

8 of 10

ţ

DISCLAIMER

Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems Non-transferable Business License

Midwest Sewer Services

License # L2896

License Expires: 12/22/2020

Issued: 11/26/2019

Specialty Area(s):

Installer Maintainer Service Provider Advanced Designer Advanced Inspector

Designated Certified Individual(s):

Cert #	Name	Certification Expires:
C5342	Brian L Humpal	10/15/2023
	Installer, Maintainer, Serv Prov, Adv Designer, Adv Inspector	
C9852 <	Christopher R Uebe	3/4/2021
	Designer, Inspector	

MINNESOTA POLLUTION CONTROL AGENCY

520 Lafayette Road North St. Paul, Minnesota 55155-4194

Haig

Nick Haig, Supervisor Certification and Training Unit