Midwest Sewer Services

P.O. Box 10853 White Bear Lake, MN 55110 651-492-7550/Brian@Midwestsoiltesting.com

Brian Humpal

MPCA Licensed Advanced Inspector

SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

Inspection Address: 9121 96th Street N, Grant, MN 55115 (House)

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the original design/permit records, along with a previous compliance inspection from 2012, which were on file at Washington County. This very old system (installed in 1991) consists of a pre-cast septic tank, a pre-cast lift tank, and a rock trench drainfield. It should be noted that the average life expectancy of a septic system is approximately 30 years.

There is a separate system for the barn, which was found non-complaint in 2012. A separate inspection on this system was not performed at this time.

Predicated on my inspection of the system and my review of the records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Midwest Sewer Services have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Midwest Sewer Services disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal



Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

| Instructions: Inspection results based on Minnesota Pollution Control Agency (MPCA) requirements and attached forms – additional local requirements may also apply. | For local tracking purposes: |
|--|--|
| Submit completed form to Local Unit of Government (LUG) and system owner within 15 days | |
| System Status | |
| System status on date (mm/dd/yyyy): 8/6/2020 | |
| · · · · · · · · · · · · · · · · · · · | npliant – Notice of Noncompliance grade Requirements on page 3) |
| Reason(s) for noncompliance (check all applicable) Impact on Public Health (Compliance Component #1) – Imminent threat to Other Compliance Conditions (Compliance Component #3) – Imminent threat to Tank Integrity (Compliance Component #2) – Failing to protect groundwate Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwate Soil Separation (Compliance Component #4) – Failing to protect groundwate Operating permit/monitoring plan requirements (Compliance Component #4) | reat to public health and safety ter otect groundwater rater |
| | |
| | |
| Property Information Parcel ID# or Sec/Twp/Rand | ae: |
| | ge: or inspection: Property Transfer |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Reason for | or inspection: Property Transfer |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's property owner: 121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's property owner: 121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's property owner: 121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's property owner: 121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's property owner: 121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's property owner: 121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's property owner: 121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's property owner: 121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's property owner: 121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's property owner: 121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's property owner. | or inspection: Property Transfer phone: |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Property owner: Kay Winchell Owner's por Owner's representative: Representative: | or inspection: Property Transfer phone: ntative phone: |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Property owner: Kay Winchell Owner's por Owner's representative: Representative: Regulatory authority: Washington County | or inspection: Property Transfer phone: ntative phone: ry authority phone: 651-430-6655 |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's representative: Represer Local regulatory authority: Washington County Regulator Brief system description: A pre-cast septic tank, a pre-cast lift tank, and a rock trend | or inspection: Property Transfer phone: ntative phone: ry authority phone: 651-430-6655 |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Property owner: Kay Winchell Owner's por Owner's representative: Representative: Regulatory authority: Washington County | or inspection: Property Transfer phone: |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's por Owner's representative: Representative: Regulatory authority: Washington County Regulatory Brief system description: A pre-cast septic tank, a pre-cast lift tank, and a rock trend Comments or recommendations: There is a separate system for the barn, which was found non-complaint in 2012. A seperformed at this time. | or inspection: Property Transfer phone: |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Property owner: Kay Winchell Owner's por Owner's representative: Represer Local regulatory authority: Washington County Brief system description: A pre-cast septic tank, a pre-cast lift tank, and a rock trend Comments or recommendations: There is a separate system for the barn, which was found non-complaint in 2012. A seperformed at this time. Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknown. | or inspection: Property Transfer phone: Intative phone: 651-430-6655 In drainfield. Parate inspection on this system was not Compliance status of this system. No |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Property owner: Kay Winchell Owner's por Owner's representative: Represer Local regulatory authority: Washington County Brief system description: A pre-cast septic tank, a pre-cast lift tank, and a rock trend Comments or recommendations: There is a separate system for the barn, which was found non-complaint in 2012. A seperformed at this time. Certification I hereby certify that all the necessary information has been gathered to determine the of determination of future system performance has been nor can be made due to unknow possible abuse of the system, inadequate maintenance, or future water usage. | or inspection: Property Transfer phone: Intative phone: 651-430-6655 In drainfield. Parate inspection on this system was not Compliance status of this system. No |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's representative: Representative: Regulator authority: Washington County Regulator are system description: A pre-cast septic tank, a pre-cast lift tank, and a rock trend Comments or recommendations: There is a separate system for the barn, which was found non-complaint in 2012. A seperformed at this time. Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknow possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certification | or inspection: Property Transfer phone: Intative phone: 651-430-6655 In drainfield. Paparate inspection on this system was not Compliance status of this system. No year conditions during system construction, |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's representative: Representative: Regulatory authority: Washington County Regulatory Brief system description: A pre-cast septic tank, a pre-cast lift tank, and a rock trend Comments or recommendations: There is a separate system for the barn, which was found non-complaint in 2012. A seperformed at this time. Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknow possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certificate Widwest Sewer Services Licer | or inspection: Property Transfer phone: Intative phone: 651-430-6655 In drainfield. Property Transfer phone: 651-430-6 |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's representative: Representative: Regulatory authority: Washington County Regulatory Brief system description: A pre-cast septic tank, a pre-cast lift tank, and a rock trend Comments or recommendations: There is a separate system for the barn, which was found non-complaint in 2012. A seperformed at this time. Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknow possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certificate Business name: Midwest Sewer Services Licen | or inspection: Property Transfer phone: |
| Property address: 9121 96 th Street N, Grant, MN 55115 (House) Reason for Owner's representative: Representative: Regulator authority: Washington County Regulator System description: A pre-cast septic tank, a pre-cast lift tank, and a rock trend Comments or recommendations: There is a separate system for the barn, which was found non-complaint in 2012. A seperformed at this time. Certification I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknown possible abuse of the system, inadequate maintenance, or future water usage. Inspector name: Brian Humpal/Christopher Uebe Certification Business name: Midwest Sewer Services Licer Photonessary or Locally Required Attachments | or inspection: Property Transfer phone: |

Property address: 9121 96th Street N, Grant, MN 55115 (House)

Inspector initials/Date: 8/6/2020

Impact on Public Health – Compliance component #1 of 5 Compliance criteria: Verification method(s): Searched for surface outlet ☐ Yes ☐ No System discharge sewage to the Searched for seeping in yard/backup in home ground surface. System discharge sewage to drain tile ☐ Yes ☐ No ☐ Homeowner testimony (See Comments/Explanation) or surface waters. ☐ "Black soil" above soil dispersal system ☐ Yes ☐ No System cause sewage backup into ☐ System requires "emergency" pumping dwelling or establishment. ☐ Performed dye test Any "yes" answer above indicates the system is Unable to verify (See Comments/Explanation) an Imminent Threat to Public Health and Safety. Other methods not listed (See Comments/Explanation) Comments/Explanation: None of the above found. 2. Tank Integrity – Compliance component #2 of 5 Verification method(s): Compliance criteria: Probed tank(s) bottom System consists of a seepage pit, ☐ Yes ☐ No cesspool, drywell, or leaching pit. Seepage pits meeting 7080.2550 may be ☐ Examined Tank Integrity Form (Attach) compliant if allowed in local ordinance. ☐ Observed liquid level below operating depth ☐ Yes ☒ No Sewage tank(s) leak below their ☐ Examined empty (pumped) tanks(s) designed operating depth. ☐ Probed outside tank(s) for "black soil" If yes, which sewage tank(s) leaks: ☐ Unable to verify (See Comments/Explanation) Any "ves" answer above indicates the ☑ Other methods not listed (See Comments/Explanation) system is Failing to Protect Groundwater. Comments/Explanation: Lowered underwater camera into tanks - baffles and tank walls OK. Lift pump and alarm were operational at the time of the inspection. 3. Other Compliance Conditions – Compliance component #3 of 5 Maintenance hole covers are damaged, cracked, unsecured, or appear to structurally unsound. ☐ Yes* ⊠ No ☐ Unknown a. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety.

Yes* No ☐ Unknown *System is an imminent threat to public health and safety Explain: System is non-protective of ground water for other conditions as determined by inspector ☑ No *System is failing to protect groundwater Explain:

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3 Property address: 9121 96th Street N, Grant, MN 55115 (House)

Inspector initials/Date: 8/6/2020


| 4. | Soil Separation – Compliance compor | nent #4 of | 5 | | | |
|----|---|-----------------|---------------------------------------|--|-------------------------------|--|
| | Date of installation: 1991 | Unknow | wn | Verification method(s): | | |
| | Shoreland/Wellhead protection/Food Beverage Lodging? | | | Soil observation does not expire. Previous soil observations by two independent parties are sufficient, | | |
| | Compliance criteria: | | | unless site conditions have been altered or local requirements differ. ☐ Conducted soil observation(s) (Attach boring logs) ☐ Two previous verifications (Attach boring logs) ☐ Not applicable (Holding tank(s), no drainfield) | | |
| | For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: | ⊠ Yes [| □ No | | | |
| | Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock. | | | ☐ Unable to verify (See Comments.☐ Other (See Comments/Explanation | (Explanation) | |
| | Non-performance systems built April 1, | ☐ Yes ☐ | □ No | Comments/Explanation: | | |
| | 1996, or later or for non-performance systems located in Shoreland or Wellhead | | | Reviewed previous compliance ins | pection from 2012. | |
| | Protection Areas or serving a food, beverage, or lodging establishment: | | | Reviewed design and permit record | ds. | |
| | Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.* | | | | | |
| | "Experimental", "Other", or "Performance" | ☐ Yes ☐ | No | Indicate depths of elevations | | |
| | systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required) | | | A. Bottom of distribution media | See Attached Boring Log(s) | |
| | Drainfield meets the designed vertical | | | B. Periodically saturated soil/bedrock | | |
| | separation distance from periodically saturated soil or bedrock. | | | C. System separation | | |
| | | | | D. Required compliance separation* | | |
| | Any "no" answer above indicates the system is Failing to Protect Groundwater. | | n is | *May be reduced up to 15 percent if allowed by Local Ordinance. | | |
| | - aming to 1 lotoot Groundwater | | | Ordinarios. | | |
| 5. | Operating Permit and Nitrogen B | MP* – Co | mpliance o | component #5 of 5 Not app | licable | |
| | Is the system operated under an Operating Per | | | No If "yes", A below is required | | |
| | Is the system required to employ a Nitrogen BM | 1P? | ☐ Yes ☐ | No If "yes", B below is required | | |
| | BMP=Best Management Practice(s) specifi | ïed in the sy | stem desig | n | | |
| | If the answer to both questions is "no", | this section | on does n | not need to be completed. | | |
| | Compliance criteria | | | | | |
| | a. Operating Permit number: | | | | | |
| | Have the Operating Permit requirements I | been met? | | ☐ Yes ☐ No | | |
| | b. Is the required nitrogen BMP in place and | | nctionina? | ☐ Yes ☐ No | | |
| | Any "no" answer indicates Noncom | | · · · · · · · · · · · · · · · · · · · | | | |

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 3 of 3

Midwest Sewer Testing Subsurface Sewage Treatment System Owner/Property Information This information will be used for the purpose of conducting an MPCA Compliance Inspection.

| This information will be used for the purpose of conducting an MFCA | Comphance inspection. | | | | |
|--|--|--|--|--|--|
| Date of Inspection: August 6, 2020 | Time: 1:45 PM | | | | |
| Property Address: 9121 96 th Street N, Grant, MN (House) | Zip: 55115 | | | | |
| Property Owner: Kay Winchell | Phone: | | | | |
| Tank(s) Tank(s)Material Soil Treatment System Septic 1 Fiberglass Rock trench Aerobic Plastic Gravelless trench Lift Metal Chamber trench Holding Concrete Seepage bed Other: Block Mound Other At-grade | Other Alternative system Experimental system Cesspool system Other system | | | | |
| Are the tank maintenance covers accessible? ⊠ Yes ☐ No *If | no, proper maintenance must be | | | | |
| performed through the maintenance holes. Maintenance hole cov | ers should be made accessible to | | | | |
| the ground surface to facilitate access and proper maintenance of | | | | | |
| 1 | Tank size (gals.): 1250 | | | | |
| | esidents in home? | | | | |
| Number of bedrooms? 4 Are all floors drained by g | | | | | |
| Garbage disposal? Y Whirlpool bath | ? Y | | | | |
| More than one system (laundry, etc.)? N | | | | | |
| Does this property have any footing drain tiles connected to the se | eptic system? N | | | | |
| Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? Separate system for the | | | | | |
| barn. | | | | | |
| Location of septic system on lot? Southwest | 11 1 110 17 | | | | |
| | e well a deep well? Y | | | | |
| Have you ever experienced any problems with the system such as surfacing of sewage onto the ground, septic tank overflowing, etc to the system? If yes, explain: | | | | | |
| V 1 1 | nper: Pinky's Sewer Service | | | | |
| | n on a monitoring plan? N | | | | |
| Have you received notices from any government agency concerni | ng this system? N | | | | |
| Is your property located in a shoreland management area? N | | | | | |
| Do you have any additional information that should be given to the | ne new owner? N | | | | |
| I hereby certify that the above information is correct to the best of my knowledge considered "non-compliant/failing" per MPCA rules, that the inspector must by local government unit within 15 days of the date of inspection completion. I a this report, that I/we are ultimately responsible for payment of all fees for all we by Inspect Minnesota and Midwest Soil Testing | law submit a copy of this report to the lso agree that unless otherwise noted in | | | | |
| Owner/Occupant: | Date: | | | | |



Soil Observations Log

| Location of Project: 9121 96th Street N, Grant, MN 55115 (House) | | | | | | | |
|--|--------|--|---|-----------------------------------|----------------------|-------------|-----|
| Observations Made By: Midwest Sewer Serv | | | | , | Date: | 8/6/2020 | |
| | | ation System: | USDA | i viecs | | | , , |
| Soil Observation: ST-1 | | | Soil C | bservation: | | | |
| | | nd surface as last Tield trench | Surface Elevation of Observation | | ' | | |
| Depth In Inches | Rock % | Soils E | ncountered | Depth In Inches Soils Encountered | | Encountered | |
| 0-16 16-24 24-36 36-60 60-80 | ≈10 | 10YR 3/4 L 7.5YR 3/ 7.5YR 4/4 Sand | Loamy Fine Sand Loamy Fine Sand Loamy Fine Sand Loam Gandy Loam Loam With Gravel Loam Sandy Clay Loam | | | | |
| 80" Depth To End Of Soil Observation Or Redox | | | Depth T | o End Of Soil | Observation Or Redox | | |
| Same Elevation Of Observation Relative To System | | • | Elevation Of Observation Relative To System | | | | |
| -48" Depth To Bottom Of Distribution Media | | Depth To Bottom Of Distribution Media | | Distribution Media | | | |
| ≥32" Of Separation | | | Of Sepa | ration | | | |
| End Of Soil Observation At: 80" | | End Of | Soil Oh | servation At: | | | |
| Redox Present At: None | | 2.10 01 | | x Present At: | | | |
| Standing Water Present At: None | | | Standi | | r Present At: | | |
| | | | | | | | |

| Bottom Of Distribution Medium At: 48 Inches | | | |
|---|-----------|--|--|
| | | | |
| Signature: | Offer Ole | | |

Log Of Soil Borings

| Location of Project: 9121 96th Street N, Grant, MN 55115 (House) | | | | | |
|--|---|--|--------------------|---------------------|--------------------|
| Borings Made By: Inspect Minnesota | | | | Date: | 3/16/12 |
| Auger Used: Hand/Bucket | | | Class | ification System: | USDA |
| Boring Number: 1 | | | | Boring Number: | |
| Surface Elevation of Boring 6" downslope of drainfield at middle of south drainfield trench | | Surface Elevation Boring | | | |
| Depth In Inches | Soils E | ncountered | Depth In Inches | · Sous Focoliniered | |
| 0-12 12-22 22-34 34-58 58-80 80-90 | 10YR 3/4 L 5YR 4/4 Sandy Cl 5YR 4/4 5YR 4/4 Sa | Loamy Fine Sand oamy Fine Sand lay Loam, Trace Gravel Sandy Loam andy Clay Loam Sandy Loam | | | |
| 90" | Depth To End Of Boring Or Redox | | | Depth To End Of Bo | ring Or Redox |
| +6" | Elevation Of Boring Relative To System | | | Elevation Of Boring | Relative To System |
| -48" Depth To Bottom Of System | | | Depth To Bottom O | f System | |
| ≥48" Of Separation | | | Of Separation | | |
| - 106P 1 22" | | | | E LOCE : 1. I | |
| End Of Boring At: 90" | | | | End Of Boring At: | |
| Redox Present At: None | | <u> </u> | Redox Present At: | | |
| Standing Water Present At: None | | Standing | Water Present At: | | |

| Bottom Of Distribution Medium At: 48 Inches | |
|---|--|
| | |

DISCLAIMER

Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include only verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems

Non-transferable

Business License

Midwest Sewer Services

License # L2896

License Expires: 12/22/2020

Issued: 11/26/2019

Specialty Area(s):

Installer
Maintainer
Service Provider
Advanced Designer
Advanced Inspector

Designated Certified Individual(s):

Cert # Na

Name

Certification Expires:

C5342

Brian L Humpal

10/15/2023

Installer, Maintainer, Serv Prov, Adv Designer, Adv Inspector

C9852 4

Christopher R Uebe

3/4/2021

Designer, Inspector



520 Lafayette Road North St. Paul, Minnesota 55155-4194 Mich Haig

Nick Haig, Supervisor Certification and Training Unit