Midwest Sewer Services

P.O. Box 10853 White Bear I	Brian Humpal				
651-492-7550/Brian@Midwes	MPCA Licensed Advanced Inspector				
SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT					
Date: September 21, 2020	Time: 2:45 PM	Owner: Karen Baltzer			
Inspection Address: 13232 20 th St Ct N, West Lakeland, MN 55082					

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system, have reviewed the history of the system with the owner, Karen Baltzer, and have reviewed the original design/permit records on file at Washington County. This system consists of two pre-cast septic tanks and a rock trench drainfield.

Predicated on my inspection of the system, my review of the history of the system with the owner, and my review of the original design/permit records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Midwest Sewer Services have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Midwest Sewer Services disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal

Minnesota Pollution Control Agency 520 Lafayette Road North St. Paul, MN 55155-4194

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspection results based on Minnesota Pollution Control Agency (MPCA)
requirements and attached forms – additional local requirements may also apply.

For local tracking purposes:

Submit completed form to Local Unit of Government (LUG) and system owner within 15 days

System Status

System status on date (mm/dd/yyyy): 9/21/2020

Compliant – Certificate of Compliance

(Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)

Noncompliant – Notice of Noncompliance

(See Upgrade Requirements on page 3)

Reason(s) for noncompliance (check all applicable)

□ Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety

Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety

Tank Integrity (Compliance Component #2) – Failing to protect groundwater

Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater

Soil Separation (Compliance Component #4) – Failing to protect groundwater

Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant

Property Information

Parcel ID# or Sec/Twp/Range:

Property address:	13232	20 th St Ct N,West Lakeland, MN 55082		Reason for inspec	ction: Pi	roperty Transfer	
Property owner:	ner: Karen Baltzer			Owner's phone: 952-484-5043			
or							
Owner's represent	ative:			Representative pl	hone:		
Local regulatory authority: Washington County			Regulatory author	rity phone:	651-430-6655		
Brief system description: Two pre-cast septic tanks and a rock trend		ench drair	nfield.				
Commonte or roco	mmonda	tions:					

Comments or recommendations:

Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.

Inspector name:	Brian Humpal/Christopher Uebe	Certification number:	C5342/C9852
Business name:	Midwest Sewer Services	License number:	L2896
Inspector signatur	e: Brian Humpal After Man	Phone number:	651-492-7550
Necessary or	Locally Required Attachments		
🛛 Soil boring lo	gs 🛛 System/As-built drawing] Forms per local ordinan	се
I Other information	ation (list): _ Report Summary, Property Information, D	isclaimer, License	

2 of 10

1. Impact on Public Health – Compliance component #1 of 5

System discharge sewage to the ground surface.	🗌 Yes 🛛 No
System discharge sewage to drain tile or surface waters.	🗌 Yes 🖾 No
System cause sewage backup into dwelling or establishment.	🗌 Yes 🖾 No

Comments/Explanation:

None of the above found.

Verification method(s):

- Searched for surface outlet
- Searched for seeping in yard/backup in home
- Excessive ponding in soil system/D-boxes
- Homeowner testimony (See Comments/Explanation)
- "Black soil" above soil dispersal system
- System requires "emergency" pumping
- Performed dye test
- Unable to verify (See Comments/Explanation)
- Other methods not listed (See Comments/Explanation)

2. Tank Integrity – Compliance component #2 of 5

Compliance criteria:	-	Verification method(s):
System consists of a seepage pit,	🗌 Yes 🛛 No	Probed tank(s) bottom
cesspool, drywell, or leaching pit.		Examined construction records
Seepage pits meeting 7080.2550 may be		Examined Tank Integrity Form (Attach)
compliant if allowed in local ordinance.		Observed liquid level below operating depth
Sewage tank(s) leak below their designed operating depth.	🗌 Yes 🖾 No	Examined empty (pumped) tanks(s)
If yes, which sewage tank(s) leaks:		Probed outside tank(s) for "black soil"
	ataa tha	Unable to verify (See Comments/Explanation)
Any "yes" answer above indic system is Failing to Protect G		Other methods not listed (See Comments/Explanation)

Comments/Explanation:

Lowered underwater camera into tanks - baffles and tank walls OK.

3. Other Compliance Conditions – Compliance component #3 of 5

a.	Maintenance hole covers are damaged,	cracked, unsecured,	or appear to structurally u	nsound. 🗌 Yes*	🛛 No	🗌 Unknown

b. Other issues (*electrical hazards, etc.*) to immediately and adversely impact public health or safety. \Box Yes* \boxtimes No \Box Unknown *System is an imminent threat to public health and safety

Explain:

c. System is non-protective of ground water for other conditions as determined by inspector □ Yes* ⊠ No *System is failing to protect groundwater

Explain:

4. Soil Separation – Compliance component #4 of 5

Date of installation: 2005	Unknown	Verification method(s):				
Shoreland/Wellhead protection/Food Beverage Lodging?	🗌 Yes 🛛 No	Soil observation does not expire. Pr				
Compliance criteria:	I		observations by two independent parties are sufficient, unless site conditions have been altered or local			
For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.	☐ Yes ☐ No	 Conducted soil observation(s) (A Two previous verifications (Attac Not applicable (Holding tank(s), not Unable to verify (See Comments/Explanation) Other (See Comments/Explanation) 	ch boring logs) o drainfield) Explanation)			
Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	🛛 Yes 🗌 No	Comments/Explanation: Reviewed design and permit records	S.			
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*						
"Experimental", "Other", or "Performance"	🗌 Yes 🗌 No	Indicate depths of elevations	-			
systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)		A. Bottom of distribution media	See Attached Boring Log(s)			
Drainfield meets the designed vertical		B. Periodically saturated soil/bedrock				
separation distance from periodically saturated soil or bedrock.		C. System separation				
		D. Required compliance separation*				
Any "no" answer above indicates the Failing to Protect Groundwater.	he system is	*May be reduced up to 15 percent if Ordinance.	allowed by Local			
Operating Permit and Nitrogen B	MP* – Compliand	ce component #5 of 5 🛛 🛛 Not appl	licable			
Is the system operated under an Operating Peri	mit? 🗌 Yes	□ No If "yes", A below is required				
Is the system required to employ a Nitrogen BM	IP? 🗌 Yes	□ No If "yes", B below is required				
BMP=Best Management Practice(s) specifi	ied in the system de	esign				
If the answer to both questions is "no",	this section doe	s not need to be completed.				

Compliance criteria

a.	Operating Permit number:	🗌 Yes 🗌 No
	Have the Operating Permit requirements been met?	
b.	Is the required nitrogen BMP in place and properly functioning?	🗌 Yes 🗌 No

Any "no" answer indicates Noncompliance.


Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

<u>Midwest Sewer Testing</u> Subsurface Sewage Treatment System Owner/Property Information

Date of Inspection: September 21, 2020 Time: 2:45 PM Property Address: 13232 20th St Ct N, West Lakeland, MN Zip: 55072 Property Owner: Karen Baltzer Phone: 952-484-5043 Tank(s) Tank(shaterial Soil Treatment System Other Areobic Plastic Gravelless trench Alternative system Other Lift Metal Chamber trench Experimental system Other Other: Block Mound Other system Other system Other Block Mound Other system. Other system. Year house built: 2005 Yeas septic installed: 2005 Tank size (gals.): 1-1500, 1-1000 How long has seller owned the property? 2005 Number of residents in home? 1-3 Number of bedrooms? 3 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? Y More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? Northeast Side Docation of sewage onto the g	This information will be used for the purpose of conducting an MPCA	Compliance Inspection.				
Property Owner: Karen Baltzer Phone: 952-484-5043 Tank(s) Tank(s)Material Soil Treatment System Other Aerobic Fiberglass Rock trench Alternative system Lift Metal Chamber trench Experimental system Other: Block Mound Other system Other: Block Mound Other system Other dtrough the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system. Year house built: 2005 Year septic installed: 2005 Tank size (gals.): 1-1500, 1-1000 How long has seller owned the property? 2005 Number of residents in home? 1-3 Number of bedrooms? 3 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? Y More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are any sequenced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain: When was the system last pumped? 2019 Na	Date of Inspection: September 21, 2020	Time: 2:45 PM				
Tank(s) Tank(s)Material Soil Treatment System Other Septic 2 Fiberglass ⊠Rock trench □Alternative system □ Lift □Metal □Chamber trench □Experimental system □ Other □Block □Mound □Cother system □ □ Other □Block □Mound □Cother system □ □ Other □Block □Mound □Cother system □ □ Other □Block □Mound □ □ Are the tank maintenance covers accessible? ∑Yes No *If no, proper maintenance must be performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system.	Property Address: 13232 20 th St Ct N, West Lakeland, MN	Zip: 55072				
Septic 2 Fiberglass Sck trench Charabet rench Experimental system Lift Metal Charabet rench Experimental system Holding Concrete Septic 2 Yes Other: Block Mound Other system Other: Block Mound Concrete Mound Other system Septic 2 Yes Yes No *If no, proper maintenance must be performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system. Year house built: 2005 Year septic installed: 2005 Tank size (gals.): 1-1500, 1-1000 How long has seller owned the property? 2005 Number of residents in home? 1-3 Number of bedrooms? Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? Y More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflow	1 5	Phone: 952-484-5043				
performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system. Year house built: 2005 Year septic installed: 2005 Tank size (gals.): 1-1500, 1-1000 How long has seller owned the property? 2005 Number of residents in home? 1-3 Number of bedrooms? 3 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? Y More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? Northeast Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain: When was the system last pumped? 2019 Name of pumper: Meyer Sewer Services How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	Septic 2FiberglassRock trenchAerobicPlasticGravelless trenchLiftMetalChamber trenchHoldingConcreteSeepage bedOther:BlockMound	Alternative system Experimental system Cesspool system				
How long has seller owned the property? 2005 Number of residents in home? 1-3 Number of bedrooms? 3 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? Y More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? Northeast Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain: When was the system last pumped? 2019 Name of pumper: Meyer Sewer Services How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	performed through the maintenance holes. Maintenance hole cover	ers should be made accessible to				
How long has seller owned the property? 2005 Number of residents in home? 1-3 Number of bedrooms? 3 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? Y More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? Northeast Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain: When was the system last pumped? 2019 Name of pumper: Meyer Sewer Services How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	Year house built: 2005 Year septic installed: 2005	Tank size (gals.): 1-1500, 1-1000				
Number of bedrooms? 3 Are all floors drained by gravity? Lower Pumped Garbage disposal? N Whirlpool bath? Y More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? Northeast Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain: When was the system last pumped? 2019 Name of pumper: Meyer Sewer Services How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is system? N						
Garbage disposal? N Whirlpool bath? Y More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? Northeast Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain: When was the system last pumped? 2019 Name of pumper: Meyer Sewer Services How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is system? N						
Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? Northeast Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain: When was the system last pumped? 2019 Name of pumper: Meyer Sewer Services How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	Garbage disposal? N Whirlpool bath?	Y				
Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? Northeast Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain: When was the system last pumped? 2019 Name of pumper: Meyer Sewer Services How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is system? N						
Are there any additional systems on this property serving other buildings? N Location of septic system on lot? Northeast Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain: When was the system last pumped? 2019 Name of pumper: Meyer Sewer Services How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is system? N	Does this property have any footing drain tiles connected to the se	ptic system? N				
Location of septic system on lot? Northeast SideLocation of water well on lot?Is the well a deep well? YHave you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain:When was the system last pumped? 2019Name of pumper: Meyer Sewer ServicesHow often pumped in previous years? Every 3Is system on a monitoring plan? NHave you received notices from any government agency concerning this system? NIs your property located in a shoreland management area? N	Are any buildings on this property such as garages or out-buildings connected to this system? N					
Location of water well on lot?Is the well a deep well? YHave you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain:When was the system last pumped? 2019Name of pumper: Meyer Sewer ServicesHow often pumped in previous years? Every 3Is system on a monitoring plan? NHave you received notices from any government agency concerning this system? NIs system? N	Are there any additional systems on this property serving other bu	ildings? N				
Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain: When was the system last pumped? 2019 Name of pumper: Meyer Sewer Services How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	Location of septic system on lot? Northeast Side					
surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N If yes, explain: When was the system last pumped? 2019 Name of pumper: Meyer Sewer Services How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	Location of water well on lot? Is the	e well a deep well? Y				
How often pumped in previous years? Every 3Is system on a monitoring plan? NHave you received notices from any government agency concerning this system? NIs your property located in a shoreland management area? N	surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made					
Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N						
Have you received notices from any government agency concerning this system? N Is your property located in a shoreland management area? N	How often pumped in previous years? Every 3 Is system	n on a monitoring plan? N				
	Have you received notices from any government agency concerning	ng this system? N				
Do you have any additional information that should be given to the new owner? N						
	Do you have any additional information that should be given to the	e new owner? N				

I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing

Owner/Occupant:



7 of 10

Soil Observations Log

	Location of Project: 13232 20th St Ct N, West Lakeland, MN 55082						
Ot			Midwest Sewer Ser			Date:	9/21/2020
0	Classific	ation System:	USDA				
	Soil	Observation:	ST-1		Soil C	bservation:	
	face tion of vation	-	nd surface as last field trench	Elevat	face tion of vation		
Depth In Inches	Rock %	<u>Soils E</u>	ncountered	Depth In Inches	Rock %	<u>Soils</u>	Encountered
0-17 17-36 36-49 49-80		10YR 3/4 10YR 3/4 M Sandy 10YR 4/4 M Trace C 7.5YR 4/4 I	2 Medium Sand edium Sand With Loam Layers edium Sand With Of Gravel And Lamellae Banding				
80"	Depth To End Of Soil Observation Or Redox				Depth T	o End Of Soil	Observation Or Redox
Same	Same Elevation Of Observation Relative To System				Elevatio	n Of Observat	tion Relative To System
	-48" Depth To Bottom Of Distribution Media				Depth T	o Bottom Of I	Distribution Media
	Of Sepa				Of Sepa	aration	
End		Theory office At-	80"			convotion AL.	
End		Observation At: dox Present At:		End Of		servation At:	
Ctor			None	Standi		x Present At: r Present At:	
Standing Water Present At: None			Stanul	ng wale	a riesent Ali		


Bottom Of Distribution Medium At: 48 Inches

Signature:

Other Va

ATE 3-28+29-05

8 of 10



DISCLAIMER

Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems Non-transferable Business License

Midwest Sewer Services

License # L2896

License Expires: 12/22/2020

Issued: 11/26/2019

Specialty Area(s):

Installer Maintainer Service Provider Advanced Designer Advanced Inspector

Designated Certified Individual(s):

Cert #	Name	Certification Expires:		
C5342	Brian L Humpal	10/15/2023		
	Installer, Maintainer, Serv Prov, Adv Designer, Adv Inspector			
C9852 ·	Christopher R Uebe	3/4/2021		
	Designer, Inspector			

MINNESOTA POLLUTION CONTROL AGENCY

520 Lafayette Road North St. Paul, Minnesota 55155-4194

Haig

Nick Haig, Supervisor Certification and Training Unit