Midwest Sewer Services

P.O. Box 10853 White Bear	Lake, MN 55110	Brian Humpal					
651-492-7550/Brian@Midw	MPCA Licensed Advanced Inspector						
SUBSURFACE SEWAGE T	FREATMENT SYSTEM	1 (SSTS) COMPLIANCE REPORT					
Date: October 1, 2020	Time: 11:30 AM	Owner: Jim Cox					
Inspection Address: 12941 22	nd St S, Afton, MN 55001	Inspection Address: 12941 22 nd St S, Afton, MN 55001					

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system, have reviewed the history of the system with the owner, Jim Cox. I have contacted Washington County and was advised that there are no records for this system. This older system (installed in 1997) consists of two pre-cast septic tanks and a gravelless trench drainfield.

Although not a compliance criteria, it should be noted that gravelless pipe is no longer approved for installation in the State of Minnesota and we have had experience with this product having significantly reduced performance and/or life expectancy. We cannot guarantee the performance of this system beyond the compliance date (10/1/2020).

Predicated on my inspection of the system and my review of the history of the system with the owner, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Midwest Sewer Services have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Midwest Sewer Services disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal

Minnesota Pollution Control Agency	Comp
520 Lafayette Road North St. Paul, MN 55155-4194	Existing Su

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspection results based on Minnesota Pollution Control Agency (MPCA)
requirements and attached forms – additional local requirements may also apply.

For local tracking purposes:

Submit completed form to Local Unit of Government (LUG) and system owner within 15 days

System Status

System status on date (mm/dd/yyyy): 10/1/2020

Compliant – Certificate of Compliance

(Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)

Noncompliant – Notice of Noncompliance

(See Upgrade Requirements on page 3)

Reason(s) for noncompliance (check all applicable)

Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety

Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety

Tank Integrity (Compliance Component #2) – Failing to protect groundwater

Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater

Soil Separation (Compliance Component #4) – Failing to protect groundwater

Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant

Property Information

Parcel ID# or Sec/Twp/Range:

Property address:	12941 22 ¹¹⁰ St S, Afton, MN 55001	Reason for inspection: Property Transfer
Property owner:	Jim Cox	Owner's phone:
or		
Owner's represent	ative:	Representative phone:
Local regulatory a	uthority: Washington County	Regulatory authority phone: _651-430-6655
Brief system desci	ription: Two pre-cast septic tanks and a gr	avelless trench drainfield.

Comments or recommendations:

Although not a compliance criteria, it should be noted that gravelless pipe is no longer approved for installation in the State of Minnesota and we have had experience with this product having significantly reduced performance and/or life expectancy. We cannot guarantee the performance of this system beyond the compliance date (10/1/2020).

Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.

Inspector name:	Brian Humpal/Christopher Uebe	Certification number:	C5342/C9852
Business name:	Midwest Sewer Services	License number:	L2896
Inspector signatur	e: Brian Humpal Afren Uh	Phone number:	651-492-7550
Necessary or	Locally Required Attachments		
🛛 Soil boring lo	ogs 🛛 System/As-built drawing	Forms per local ordinan	се
🖾 Other inform	ation (list): Report Summary Property Information	Disclaimer License	

2 of 9

1. Impact on Public Health – Compliance component #1 of 5

Compliance criteria:		Verification method(s):
System discharge sewage to the ground surface.	🗌 Yes 🖾 No	Searched for surface outletSearched for seeping in yard/backup in home
System discharge sewage to drain tile or surface waters.	🗌 Yes 🖾 No	 Excessive ponding in soil system/D-boxes Homeowner testimony (See Comments/Explanation) "Black soil" above soil dispersal system
System cause sewage backup into dwelling or establishment.	🗌 Yes 🛛 No	 Black soil above soil dispersal system System requires "emergency" pumping Performed dye test
Any "yes" answer above indicates an Imminent Threat to Public Heal	•	 Unable to verify (See Comments/Explanation) Other methods not listed (See Comments/Explanation)
Comments/Explanation:		

2. Tank Integrity - Compliance component #2 of 5

Compliance criteria:		Verification method(s):		
System consists of a seepage pit, cesspool, drywell, or leaching pit.	🗌 Yes 🛛 No	 Probed tank(s) bottom Examined construction records 		
Seepage pits meeting 7080.2550 may be compliant if allowed in local ordinance.		Examined Tank Integrity Form (Attach)		
Sewage tank(s) leak below their designed operating depth.	🗌 Yes 🖾 No	 Observed liquid level below operating depth Examined empty (pumped) tanks(s) 		
If yes, which sewage tank(s) leaks:		Probed outside tank(s) for "black soil"		
Any "yes" answer above indicates the system is Failing to Protect Groundwater.		 Unable to verify (See Comments/Explanation) Other methods not listed (See Comments/Explanation) 		

Comments/Explanation:

None of the above found.

Lowered underwater camera into tanks - baffles and tank walls OK.

3. Other Compliance Conditions - Compliance component #3 of 5

a.	Maintenance hole covers are damaged, crac	cked, unsecured,	or appear to structurally unsound.	□ Yes*	🛛 No	🗌 Unknown
----	---	------------------	------------------------------------	--------	------	-----------

b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety. \Box Yes* \boxtimes No \Box Unknown *System is an imminent threat to public health and safety

Explain:

c. System is non-protective of ground water for other conditions as determined by inspector □ Yes* ⊠ No *System is failing to protect groundwater

Explain:

4. Soil Separation – Compliance component #4 of 5

Date of installation: 1997	Unknown	Verification method(s):			
Shoreland/Wellhead protection/Food Beverage Lodging?	🗌 Yes 🛛 No	Soil observation does not expire. Previous soil observations by two independent parties are so			
Compliance criteria:		unless site conditions have been alt			
For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: Drainfield has at least a two-foot vertical	□ Yes □ No	 requirements differ. Conducted soil observation(s) (Attach boring logs) Two previous verifications (Attach boring logs) Not applicable (Holding tank(s), no drainfield) 			
separation distance from periodically saturated soil or bedrock.			. ,		
Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	🖾 Yes 🔲 No	Comments/Explanation:			
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*					
"Experimental", "Other", or "Performance"	🗌 Yes 🔲 No	□ Conducted soil observation(s) (Attach boring logs) □ Two previous verifications (Attach boring logs) □ Not applicable (Holding tank(s), no drainfield) □ Unable to verify (See Comments/Explanation) □ Other (See Comments/Explanation) □ Other (See Comments/Explanation) Comments/Explanation: Comments/Explanation) Comments/Explanation: Comments/Explanation: Indicate depths of elevations See Attached Boring Log(s) B. Periodically saturated soil/bedrock E. C. System separation D. D. Required compliance separation* *May be reduced up to 15 percent if allowed by Local Ordinance. component #5 of 5 ☑ Not applicable			
systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)		See Attached			
Drainfield meets the designed vertical		B. Periodically saturated soil/bedrock			
separation distance from periodically saturated soil or bedrock.		C. System separation			
		D. Required compliance separation*			
Any "no" answer above indicates t Failing to Protect Groundwater.	he system is		allowed by Local		
Operating Permit and Nitrogen BMP* – Compliance component #5 of 5 Not applicable					
Is the system operated under an Operating Per	mit? 🗌 Yes [No If "yes", A below is required			
Is the system required to employ a Nitrogen BM	IP? □Yes [No If "yes", B below is required			
BMP=Best Management Practice(s) specif	fied in the system desi	gn			

If the answer to both questions is "no", this section does not need to be completed.

Compliance criteria

5.

a.	Operating Permit number:	🗌 Yes 🔲 No
	Have the Operating Permit requirements been met?	
b.	Is the required nitrogen BMP in place and properly functioning?	🗌 Yes 🗌 No


Any "no" answer indicates Noncompliance.

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

Subsurface Sewage Treatment System Owner/Property Information This information will be used for the purpose of conducting an MPCA Compliance Inspection. Date of Inspection: October 1, 2020 Time: 11:30 AM Property Address: 12941 22 nd St S, Afton, MN Zip: 55001 Property Owner: Jank(s)Material Soil Treatment System Other □ Arerobic □ Fiberglass ©Rock trench □ Reperimental system □ Arerobic □ Block □ Chamber trench □ Cesspool system □ Other system □ Other: □ Block □ Other system □ Other system □ Other system □ Other: □ Block □ Mound □ Other system □ Other system □ Other: □ Block □ Mound □ Other system □ Other system □ Other: □ Block Mound □ Other system □ Other system □ Other: □ Block Mound □ Other system □ Other system □ Other: □ Block Mound □ Other system □ Other system Year house built: 1954 Year septic installed: 1997 <	<u>Midwest Sewer Testing</u>				
Date of Inspection: October 1, 2020 Time: 11:30 AM Property Address: 12941 22 nd St S, Afton, MN Zip: 55001 Property Owner: Jim Cox Phone: Tank(s) Tank(s)/Material Soil Treatment System Other Aerobic Plastic Giravelless trench Experimental system I.ift Metal Chamber trench Experimental system Other: Block Mound Other system Other: Block Mound Other system Other: Block Mound Other system Property Audress: 1294 / Year septic installed: 1997 Tank size (gals.): How long has seller owned the property? 1997 Number of residents in home? 1-2 Number of bedrooms? 2 Are all floors drained by gravity? Y Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are there any additional systems on this property serving other buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water	Subsurface Sewage Treatment System Owner/Property Information				
Property Address: 12941 22 nd St S, Afton, MN Zip: 55001 Property Owner: Jim Cox Phone: Tank(s) Tank(s)Material Soil Treatment System Other Acrobic Plastic Gravelless trench Experimental system Experimental system Lift Metal Chamber trench Cesspool system Cesspool system Other: Block Mound Cesspool system Cesspool system Other: Block Mound Concrete Cesspool system Performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system. Year house built: 1954 Year septic installed: 1997 Tank size (gals.): How long has seller owned the property? 1997 Number of residents in home? 1-2 Number of bedrooms? 2 Are all floors drained by gravity? Y Garbage disposal? N Whirtpool bath? N More than one system (laundry, etc.)? N Otes this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Location of septic system on lot? South S					
Property Owner: Jim Cox Phone: Tank(s) Tank(s)Material Soil Treatment System Other Aerobic Plastic Rock trench Atternative system Experimental system Holding Concrete Seepage bed Experimental system Experimental system Other: Block Mound Other system Experimental system Other of the maintenance covers accessible? Yes No *If no, proper maintenance must be performed through the maintenance holes. Maintenance of the system. Year house built: 1954 Year septic installed: 1997 Tank size (gals.): How long has seller owned the property? 1997 Number of residents in home? 1-2 Number of bedrooms? 2 Number of bedrooms? 2 Are all floors drained by gravity? Y Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of septic system on lot? South Side Is the well a deep well? Y	Date of Inspection: October 1, 2020	Time: T1:30 AM			
Tank(s) Tank(s)Material Soil Treatment System Other Septic 2 Fiberglass Rock trench Alternative system Lift Metal Chamber trench Experimental system Holding Concrete Seepage bed Other system Block Mound Other system Other system Ver the tank maintenance covers accessible? Yes No *If no, proper maintenance must be performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system. Year house built: 1954 Year septic installed: 1997 Tank size (gals.): How long has seller owned the property? 1997 Number of residents in home? 1-2 Number of bedrooms? 2 Are all floors drained by gravity? Y Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of septic of swage onto the ground, se		1			
Septic 2 Fiberglass Rock trench Alternative system Actobic Plastic Gravelless trench Experimental system Holding Concrete Seepage bed Other system Other Block Mound Other system Other Block Other system Other system Year house built: 1954 Year septic installed: 1997 Tank size (gals.): How long has seller owned the property? 1997 Number of residents in home? 1-2 Number of bedrooms? 2 Are all floors drained by gravity? Y Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are there any additional systems on this property serving other buildings? N Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? N When was the system last pumped? 2018 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N					
performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system. Year house built: 1954 Year septic installed: 1997 Tank size (gals.): How long has seller owned the property? 1997 Number of residents in home? 1-2 Number of bedrooms? 2 Are all floors drained by gravity? Y Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain: When was the system last pumped? 2018 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N	Septic 2 Fiberglass Rock trench Aerobic Plastic Gravelless trench Lift Metal Chamber trench Holding Concrete Seepage bed Other: Block Mound Other At-grade	Alternative system Experimental system Cesspool system Other system			
Year house built: 1954 Year septic installed: 1997 Tank size (gals.): How long has seller owned the property? 1997 Number of residents in home? 1-2 Number of bedrooms? 2 Are all floors drained by gravity? Y Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain: When was the system last pumped? 2018 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N	performed through the maintenance holes. Maintenance hole cover	ers should be made accessible to			
How long has seller owned the property? 1997 Number of residents in home? 1-2 Number of bedrooms? 2 Are all floors drained by gravity? Y Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain: When was the system last pumped? 2018 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N					
Number of bedrooms? 2 Are all floors drained by gravity? Y Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain: When was the system last pumped? 2018 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N					
Garbage disposal? N Whirlpool bath? N More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain: When was the system last pumped? 2018 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N					
More than one system (laundry, etc.)? N Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain: When was the system last pumped? 2018 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N	58				
Does this property have any footing drain tiles connected to the septic system? N Are any buildings on this property such as garages or out-buildings connected to this system? N Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain: When was the system last pumped? 2018 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N		1			
Are there any additional systems on this property serving other buildings? N Location of septic system on lot? South Side Location of water well on lot? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain: When was the system last pumped? 2018 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N		ptic system? N			
Location of septic system on lot? South SideLocation of water well on lot?Is the well a deep well? YHave you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain:When was the system last pumped? 2018Name of pumper: Pinky's Sewer ServiceHow often pumped in previous years? Every 3Is system on a monitoring plan? NHave you received notices from any government agency concerning this system? N	Are any buildings on this property such as garages or out-building	s connected to this system? N			
Location of water well on lot?Is the well a deep well? YHave you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain:When was the system last pumped? 2018Name of pumper: Pinky's Sewer ServiceHow often pumped in previous years? Every 3Is system on a monitoring plan? NHave you received notices from any government agency concerning this system? N	Are there any additional systems on this property serving other bu	ildings? N			
Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain: When was the system last pumped? 2018 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N					
surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? M If yes, explain: When was the system last pumped? 2018 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Every 3 Is system on a monitoring plan? N Have you received notices from any government agency concerning this system? N	Location of water well on lot? Is the well a deep well? Y				
How often pumped in previous years? Every 3Is system on a monitoring plan? NHave you received notices from any government agency concerning this system? N	surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made				
Have you received notices from any government agency concerning this system? N		per: Pinky's Sewer Service			
Have you received notices from any government agency concerning this system? N	How often pumped in previous years? Every 3 Is system				
Is your property located in a shoreland management area? N	Have you received notices from any government agency concerning	ng this system? N			
	Is your property located in a shoreland management area? N				
Do you have any additional information that should be given to the new owner? N	Do you have any additional information that should be given to the	e new owner? N			

I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing

Owner/Occupant:



Soil Observations Log

Location of Project: 12941 22nd St S, Afton, MN 55001							
Ob			Midwest Sewer Ser				
C	lassific	ation System:	USDA				
	Soil	Observation:	ST-1		Soil C	bservation:	
Surf Elevat Observ	ion of	-	nd surface as last Tield trench	Surface Elevation of Observation			
Depth In Inches	Rock %	<u>Soils E</u>	ncountered	Depth In Inches	Rock %	<u>Soils</u>	Encountered
0-4 4-19 19-40 40-62		10YR 3/3 L 10YR 4/4 10YR 5/4 M	oamy Sand (Dry) oamy Sand (Dry) Hedium Sand edium Sand With Sand Layers				
62"	Depth T	o End Of Soil O	bservation Or Redox		Depth T	o End Of Soil	Observation Or Redox
Same	Elevatio	n Of Observatio	n Relative To System	m Elevation Of Observation Relative To System			tion Relative To System
-25"	Depth T	o Bottom Of Dis	stribution Media Depth To Bottom Of Distribution Media			Distribution Media	
	Of Sepa				Of Sepa		
			60 H			1	
End		Observation At:	62"	End Of		servation At:	
		dox Present At:	None				
Stan	Standing Water Present At: None			Standing Water Present At:			

Bottom Of Distribution Medium At: 25 Inches

Signature:

After the

DISCLAIMER

Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems Non-transferable Business License

Midwest Sewer Services

License # L2896

License Expires: 12/22/2020

Issued: 11/26/2019

Specialty Area(s):

Installer Maintainer Service Provider Advanced Designer Advanced Inspector

Designated Certified Individual(s):

Cert #	Name	Certification Expires:
C5342	Brian L Humpal	10/15/2023
	Installer, Maintainer, Serv Prov, Adv Designer, Adv Inspector	
C9852 <	Christopher R Uebe	3/4/2021
	Designer, Inspector	

MINNESOTA POLLUTION CONTROL AGENCY

520 Lafayette Road North St. Paul, Minnesota 55155-4194

Haig

Nick Haig, Supervisor Certification and Training Unit