#### **Midwest Sewer Services**

P.O. Box 10853 White Bear Lake, MN 55110

Brian Humpal

651-492-7550/Brian@Midwestsoiltesting.com

MPCA Licensed Advanced Inspector

#### SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

**Inspection Address:** 3977 Oakgreen Ave N, Baytown Twp, MN 55082

#### **REPORT SUMMARY**

I have performed an "MPCA Compliance Inspection" on this system, have reviewed the history of the system with the owner, Debbie Anez, and have reviewed the original design/permit records on file at Washington County. This very old system (installed in 1987) consists of a precast septic tank, a pre-cast lift tank, and a rock trench drainfield. It should be noted that the average life expectancy of a septic system is approximately 30 years.

Predicated on my inspection of the system, my review of the history of the system with the owner, and my review of the original design/permit records, it is my opinion that this system presently meets MPCA minimum compliance inspection requirements.

Midwest Sewer Services have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Midwest Sewer Services disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal



### **Compliance Inspection Form**

# Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

<b>Instructions:</b> Inspection results based on Minnesota Pollution Control Agency (M requirements and attached forms – additional local requirements may also apply.	PCA) For local tracking purposes:
Submit completed form to Local Unit of Government (LUG) and system ow within 15 days	ner
System Status	
System status on date (mm/dd/yyyy):11/2/2020	
	ncompliant – Notice of Noncompliance ee Upgrade Requirements on page 3)
Reason(s) for noncompliance (check all applicable)  Impact on Public Health (Compliance Component #1) – Imminent the Other Compliance Conditions (Compliance Component #3) – Immine Tank Integrity (Compliance Component #2) – Failing to protect group Other Compliance Conditions (Compliance Component #3) – Failing Soil Separation (Compliance Component #4) – Failing to protect group Operating permit/monitoring plan requirements (Compliance Component	ent threat to public health and safety undwater g to protect groundwater oundwater
Property Information Parcel ID# or Sec/Tw	p/Range:
	ason for inspection: Property Transfer
Property owner: Kevin & Debbie Anez Ow	ner's phone: 651-439-5833
or	
•	presentative phone:
Local regulatory authority: Washington County Re  Brief system description: A pre-cast septic tank, a pre-cast lift tank, and a roc	gulatory authority phone: 651-430-6655
Comments or recommendations:	k trench dialimetu.
201 System.	
Certification	
I hereby certify that all the necessary information has been gathered to determin determination of future system performance has been nor can be made due to u possible abuse of the system, inadequate maintenance, or future water usage.	
	rtification number: C5342/C9852
Business name: Midwest Sewer Services	License number: L2896
Inspector signature: Brian Thompal for the	Phone number: 651-492-7550
Nococcamu or Locally Poquired Attachments	
Necessary or Locally Required Attachments	an man la cal cardinana
_	ns per local ordinance
☐ Other information (list): Report Summary, Property Information, Disclaim	ner, License

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 1 of 3

Property address: 3977 Oakgreen Ave N, Baytown Twp, MN 55082

Inspector initials/Date: 11/2/2020 **24** 

1.	Impact on Public Health – Compliance component #1 of 5					
	C	ompliance criteria:		Verification method(s):		
		stem discharge sewage to the ound surface.	☐ Yes ⊠ No	<ul><li>Searched for surface outlet</li><li>Searched for seeping in yard/backup in home</li></ul>		
		stem discharge sewage to drain tile surface waters.	☐ Yes ⊠ No	<ul> <li>☑ Excessive ponding in soil system/D-boxes</li> <li>☑ Homeowner testimony (See Comments/Explanation)</li> <li>☐ "Plack soil" above soil dispersal system</li> </ul>		
		vstem cause sewage backup into velling or establishment.	☐ Yes ⊠ No	<ul> <li>"Black soil" above soil dispersal system</li> <li>System requires "emergency" pumping</li> <li>Performed dye test</li> </ul>		
		ny "yes" answer above indicates n Imminent Threat to Public Heal		☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)		
		omments/Explanation: one of the above found.				
2.	Ta	ank Integrity — Compliance com	nponent #2 of 5			
	C	ompliance criteria:		Verification method(s):		
		stem consists of a seepage pit, sspool, drywell, or leaching pit.	☐ Yes ⊠ No	<ul><li>☑ Probed tank(s) bottom</li><li>☑ Examined construction records</li></ul>		
		epage pits meeting 7080.2550 may be mpliant if allowed in local ordinance.		<ul><li>Examined Tank Integrity Form (Attach)</li><li>Observed liquid level below operating depth</li></ul>		
		ewage tank(s) leak below their signed operating depth.	☐ Yes  ☐ No	Examined empty (pumped) tanks(s)		
	lf y	yes, which sewage tank(s) leaks:		Probed outside tank(s) for "black soil"		
		ny "yes" answer above indica /stem is Failing to Protect Gro		<ul> <li>☐ Unable to verify (See Comments/Explanation)</li> <li>☑ Other methods not listed (See Comments/Explanation)</li> </ul>		
3.	Lo Lif	omments/Explanation: owered underwater camera into tanks - it pump and alarm were operational at ther Compliance Conditions	the time of the inspe	ction.		
<u> </u>	<u>а</u> .	-		d, or appear to structurally unsound. ☐ Yes* ☒ No ☐ Unknown		
	b.	•	mmediately and adve	ersely impact public health or safety.   Yes*  No Unknown		
		Explain:				
	C.	System is non-protective of ground wa *System is failing to protect ground		as as determined by inspector ☐ Yes* ☒ No		
		Explain:				

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

Property address: 3977 Oakgreen Ave N, Baytown Twp, MN 55082

Inspector initials/Date: 11/2/2020 **B#** 


1.	Soil Separation – Compliance compor	nent #4 c	of 5					
	Date of installation: 1987	Unkr	nown	٧	erification method(s):			
	Shoreland/Wellhead protection/Food Beverage Lodging?	☐ Yes	⊠ No		oil observation does not expire. Pi			
	Compliance criteria:				observations by two independent parties are sufficient unless site conditions have been altered or local			
	For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	⊠ Yes	No No	requirements differ.  ☐ Conducted soil observation(s) (Attach boring logs) ☐ Two previous verifications (Attach boring logs) ☐ Not applicable (Holding tank(s), no drainfield)				
	Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.				☐ Unable to verify (See Comments/Explanation) ☐ Other (See Comments/Explanation)			
	Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	☐ Yes	□No		Comments/Explanation: Reviewed design and permit record	s.		
	Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*							
	"Experimental", "Other", or "Performance"	☐ Yes	□No	Ir	ndicate depths of elevations			
	systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)			_A.	. Bottom of distribution media	See Attached Boring Log(s)		
	Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.			-	Periodically saturated soil/bedrock  System separation			
		_		<u>D</u>	. Required compliance separation*			
	Any "no" answer above indicates to Failing to Protect Groundwater.	he syst	em is		May be reduced up to 15 percent i Ordinance.	f allowed by Local		
5.	Operating Permit and Nitrogen B	<b>MP*</b> – 0	Complianc	e com	ponent #5 of 5 🛮 🗵 <b>Not app</b>	licable		
	Is the system operated under an Operating Per	mit?	☐ Yes	☐ No	If "yes", A below is required			
	Is the system required to employ a Nitrogen BM	1P?	☐ Yes	☐ No	If "yes", B below is required			
	BMP=Best Management Practice(s) specif	ied in the	system de	sign				
	If the answer to both questions is "no",	this sec	tion doe	s not i	need to be completed.			
	Compliance criteria							
	a. Operating Permit number:				DVaa DNa			
	Have the Operating Permit requirements I	been met	?		☐ Yes ☐ No			
b. Is the required nitrogen BMP in place and properly functioning?					☐ Yes ☐ No			
	Any "no" answer indicates Noncom	pliance	•					

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 3 of 3

# Midwest Sewer Testing Subsurface Sewage Treatment System Owner/Property Information This information will be used for the purpose of conducting an MPCA Compliance Inspection.

This information will be used for the purpose of conducting all MFCF	Comphance inspection.				
Date of Inspection: November 2, 2020	Time: 2:00 PM				
Property Address: 3977 Oakgreen Ave N, Baytown Twp, MN	Zip: 55082				
Property Owner: Kevin & Debbie Anez	Phone: 651-439-5833				
Tank(s)       Tank(s)Material       Soil Treatment System         Septic 1       Fiberglass       Soil Treatment System         Aerobic       Plastic       Gravelless trench         Lift       Metal       Chamber trench         Holding       Concrete       Seepage bed         Other:       Block       Mound         Other       At-grade	Other  Alternative system  Experimental system  Cesspool system  Other system				
Are the tank maintenance covers accessible? ⊠ Yes □ No *If	no, proper maintenance must be				
performed through the maintenance holes. Maintenance hole cov	vers should be made accessible to				
the ground surface to facilitate access and proper maintenance of	the system.				
Year house built: 1880 Year septic installed: 1987	Tank size (gals.): 1500				
How long has seller owned the property? 1984 Number of re	esidents in home? 2-6				
Number of bedrooms? 4 Are all floors drained by §	gravity? Y				
Garbage disposal? N Whirlpool bath	? N				
More than one system (laundry, etc.)? N					
Does this property have any footing drain tiles connected to the s	eptic system? N				
Are any buildings on this property such as garages or out-building					
Are there any additional systems on this property serving other be	aildings? N				
Location of septic system on lot? Tanks - South Side, Drainfield	- Southeast Side				
Location of water well on lot? East Side Is the	e well a deep well? Y				
Have you ever experienced any problems with the system such as surfacing of sewage onto the ground, septic tank overflowing, etc to the system? Y If yes, explain:Replaced pump.					
, , , , , , , , , , , , , , , , , , , ,	nper: Pinky's Sewer Service				
How often pumped in previous years? Every 3					
Have you received notices from any government agency concerning this system? N					
Is your property located in a shoreland management area? N					
Do you have any additional information that should be given to the	ne new owner? N				
I hereby certify that the above information is correct to the best of my knowledge considered "non-compliant/failing" per MPCA rules, that the inspector must by local government unit within 15 days of the date of inspection completion. I at this report, that I/we are ultimately responsible for payment of all fees for all we by Inspect Minnesota and Midwest Soil Testing	law submit a copy of this report to the lso agree that unless otherwise noted in				
Owner/Occupant:	Date:				



#### **Soil Observations Log**

Location of Project: 3977 Oakgreen Ave N, Baytown Twp, MN 55082							
Observations Made By: Midwest Sewer Ser						Date:	11/2/2020
Classification System: USDA							
	Soil	Observation:	ST-1		Soil C	bservation:	
Surface Elevation of Observation			Elevat	Surface Elevation of Observation			
Depth In Inches	Rock %	Soils E	ncountered	Depth In Inches	Rock %	Soils Encountered	
0-13 13-28 28-40 40-56		7.5YR 2.5 7.5YR 4/3 Med	2.5/2 Loam 5/3 Loamy Sand ium Sand (Very Dry) ium Sand (Very Dry)				
56"	56" Depth To End Of Soil Observation Or Redox				Depth T	o End Of Soil	Observation Or Redox
Same Elevation Of Observation Relative To System				Elevatio	n Of Observat	tion Relative To System	
-25" Depth To Bottom Of Distribution Media			Depth To Bottom Of Distribution Media				
≥31" Of Separation				Of Sepa	ration		
End Of Soil Observation At: 56"					Soil Oh	servation At:	
Redox Present At: None				2.10 01		x Present At:	
Star	Standing Water Present At: None			Standi		r Present At:	

Bottom Of Distribution Medium At: 25 Inches				
Signature:	Office 16			

## LOG OF SOIL BORINGS

BOR	ING NO. /	BOR	ING NO J	BORI	NO NO. 3	BORI	NG NO. 4
OEPTH IN PERT	DESCRIPTION	DEPTH IN PERT	DESCRIPTION	DEPTH IN PERT	SOIL DESCRIPTION	DEPTH IN FEET	SOIL DESCRIPTION
0	DAEK BOWN	0	DAKK BOWE	0	DAKE SHWH	0	DAKE BLOWE
	PINE SHUY		sciss long		FINE SALLY		A IAIC
	Lorus		5040		LUAM		sampleam
8-		19"		7"	-	9"	
					LT. 2.20		
	HALO Brown		مرزور بساورها		Brown Risis Lonmy		Browny Kines
	evan		commy Samo		571-10	ļ	50-0
<u> </u>					ı	24	
27"						24"	
	17-020						PRP 13,0 mi
	Browns						rise
	lonny	34"					Sharry
	5440		RLO BIOME				lonn
	JROCKS		Sawy Leann				
				575			
f1					REO BLOWN		1
	ł				RIÚC Saucy		
	· t				100 m		
	Ţ						I
	· •						I
	1						
							Ī
	ľ						1
							İ
	[		[				ļ
							1
			Į.				
	L		Į.				ĺ
	L		<u> </u>		ļ		i
	Ĺ		ļ		1		ł
	<u> </u>				Ļ		j
	<u> </u>				ļ		İ
	L-		<u> </u>				

#### **DISCLAIMER**

# Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include only verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1<sup>st</sup> through April 1<sup>st</sup>) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

# Subsurface Sewage Treatment Systems

Non-transferable

# Business License

### **Midwest Sewer Services**

License # L2896

License Expires: 12/22/2020

Issued: 11/26/2019

### Specialty Area(s):

Installer
Maintainer
Service Provider
Advanced Designer
Advanced Inspector

#### Designated Certified Individual(s):

Cert # Na

Name

**Certification Expires:** 

C5342

Brian L Humpal

10/15/2023

Installer, Maintainer, Serv Prov, Adv Designer, Adv Inspector

C9852 4

Christopher R Uebe

3/4/2021

Designer, Inspector



520 Lafayette Road North St. Paul, Minnesota 55155-4194 Mich Haig

Nick Haig, Supervisor Certification and Training Unit