ALIA SOILS FRUM DESIGNER

## Log Of Soil Borings

Location of Project: 7837 Jamaca Ave N, Grant, MN 55082						
Borings Made By: Midwest Soil Testing			Date:			4/5/12 & 4/11/12
Auger Used: Hand/Bucket		Classification System:		ation System:	USDA	
Boring Number: 1		Boring Number:		oring Number:	2	
Surface 97.80'		Surface				
Elevation	levation of		Elevation of 97.40'			
Boring			Boring			
Depth In			Depth In	Soils Encountered		
Inches 0-12	7.5YR 2.5/3 Loam		Inches 0-13	7.5YR 2.5/2 Loam		
12-20 20-32 32-38 38-78	7.5YR 4/4 Sandy 7.5YR 4/4 Loam 5YR 4/4 Sa	Loam, Trace Gravel y Sand, Trace Gravel andy Clay Loam 4/4 Loam	13-33 33-37 37-42 42-50		7.5YR 3/4 Sandy 5YR 4/4 Sal 5YR 4 5YR 4/4 Sandy turated 7.5YR 5/	Loam, Trace Gravel ndy Clay Loam /4 Loam y Clay Loam With /3 Loamy Sand Layers 5YR 5/8 Redox
End Of Boring At: 78"		End Of Boring At:		nd Of Boring At:	50"	
Redox Present At: None			Redox Present At:		42"	
Standing Water Present At: None			Standing Water Present At: None			
Boring Number: 3			Boring Number: 4			
Surface		Surface				
Elevation	Management of the control of the con		Elevation of 97.00'		97.00'	
Boring			Boring Depth In			
Inches			Inches		Soils Encountered	
0-14	7.5YR 2.5/3 Sandy Loam		0-14		7.5YR 2.5/3 Fine Sandy Loam	
14-22 22-30	7.5YR 3/4 Sandy Loam 7.5YR 4/4 Sandy Clay Loam (Saturated)		14-31 31-40			Sandy Loam
30-42	With 5YR 4/6 Redox			5YR 4/4 Sandy Loam (Saturated) With Few 5YR 4/6 Redox 5YR 4/4 Sandy Clay Loam With Saturated Sand Seams		
End Of Boring At: 42"					nd Of Boring At:	48"
Redox Present At: 22"					dox Present At:	31"
Standing Water Present At: None			Standing	LW	ater Present At:	None