4 of 11

Property Address:	9275 Lake Jane Trail N, Lake Elmo, MN 55042
Business Name:	Midwest Sewer Services

Date: 8/25/2021

3. Other compliance conditions – Compliance component #3 of 5

3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured?				
	🗆 Yes* 🕅 No 🔲 Unknown			
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety? 🗌 Yes* 🛛 No 🗋 Unknown			
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.			
	3c. System is non-protective of ground water for other co	nditions as determined by inspector? \Box Yes* \boxtimes No		
	3d. System not abandoned in accordance with Minn. R.	7080.2500? □ Yes* ⊠ No		
	*Yes to 3c or 3d - System is failing to protect gro	indwater.		
Describe verification methods and results:				
	Attached supporting documentation: 🖂 Not appli	cable 🗍		
4.	Operating permit and nitrogen BMP* –	Compliance component #4 of 5 🛛 Not applicable		
		· · ·		
Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? Yes No If "yes", A below in the system design? Yes No If "yes", B below in the system design?		□ Yes □ No If "yes", A below is required		
		d in the system design? □ Yes □ No If "yes", B below is required		
BMP = Best Management Practice(s) specified in the system design				
	If the answer to both questions is "no", this section does not need to be completed.			
	Compliance criteria:			
	a. Have the operating permit requirements been met?	Yes No		

b. Is the required nitrogen BMP in place and properly functioning?

Any "no" answer indicates noncompliance.

Describe verification methods and results:

Attached supporting documentation:
Operating permit (Attach)