## ZIERKE SOIL TESTING

John Mollner 23734 Itasca Ave N Forest Lake, MN 55025

11/2/2021

Dear John Moliner,

At your request, I have conducted a septic inspection to determine the compliance status of your septic system pursuant to Minnesota Rules Chapter 7080.1500.

The compliance test set out in 7080.1500 has three main inquiries: 1). Is the system functioning hydraulically (disposing of effluent in a manner that prevents it from coming in contact with people)? 2). Are the septic tanks water tight? 3). Does the system have sufficient vertical separation between the bottom of the septic system and restrictive layers (bedrock, standing water, seasonally wet layers, etc) to provide full treatment of effluent?

Based off of these criteria, your system is <u>compliant</u>. A certification of compliance is in effect for three years from the date it is issued. To be clear, this should not be construed as a guarantee of future system function – there are too many factors that influence the lifespan of a septic system for an inspector to predict or even guess how long a septic system will last. A copy of this report will be filed with your local unit of government for their records.

Sincerely,

Benjamin Zierke

MPCA Lic 119, Cert 9594

ADDRESS: 28587 Jeffrey Ave Chisago City, MN 55013

PHONE 651-249-1346

EMAIL benzierke@gmail.com



520 Lafayette Road North St. Paul, MN 55155-4194

## Compliance inspection report form

## **Existing Subsurface Sewage Treatment System (SSTS)**

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wg-wwists4-31a.pdf.

Property information	Local tracking	number:
Parcel ID# or Sec/Twp/Range: 0203221240003	Reason for Inspection	Sale
Local regulatory authority info: Washington County		
Property address: 23734 Itasca Ave N Forest Lake, MN 55025		
Owner/representative: John Mollner		Owner's phone: 651-464-8509
Brief system description: (2) 1000 gallon septic tanks, 1000 gallon	on lift tank, mound dispersal	system
System status		
System status on date (mm/dd/yyyy): 11/2/2021		
☐ Compliant – Certificate of compliance*	☐ Noncompliant – Notice	ce of noncompliance
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and	Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.	
abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)	An imminent threat to public	health and safety (ITPHS) must be
*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.	upgraded, replaced, or its us of this notice or within a shor under section 145A.04 subdi	se discontinued within ten months of receipt rter period if required by local ordinance or ivision 8.
Reason(s) for noncompliance (check all applicab	le)	
☐ Impact on public health (Compliance component #1)	- Imminent threat to public	health and safety
☐ Tank integrity (Compliance component #2) – Failing	to protect groundwater	
☐ Other Compliance Conditions (Compliance compone	ent #3) – Imminent threat to	public health and safety
☐ Other Compliance Conditions (Compliance compone		
System not abandoned according to Minn. R. 7080.2		nt #3) – Failing to protect groundwater
Soil separation (Compliance component #5) – Failing	E// 15/ 15/	
Operating permit/monitoring plan requirements (Con	npliance component #4) – N	oncompliant - local ordinance applies
Comments or recommendations		
Certification		
I hereby certify that all the necessary information has been gathered a future system performance has been nor can be made due to unknow inadequate maintenance, or future water usage.	to determine the compliance so wn conditions during system co	tatus of this system. No determination of onstruction, possible abuse of the system,
By typing my name below, I certify the above statements to be true used for the purpose of processing this form.	and correct, to the best of my	knowledge, and that this information can be
Business name: Zierke Soil Testing		Certification number: 9594
Inspector signature: BC		License number: 119
(This document has been electronically sign	ned)	Phone: 651-249-1346
Necessary or locally required supporting do	cumentation (must b	pe attached)
Soil observation logs System/As-Built □ Locally re	equired forms	grity Assessment
Other information (list):	90 MILLON S	AN 1500
https://www.peg.state.mp.usa6E1_206_6200a900_6E7_296	A Lice your professed rela	av conden . Available in alternative formats

Compliance criteria:		Attached supporting documentation:
System discharges sewage to the ground surface	☐ Yes* ⊠ No	☐ Other: ☐ Not applicable
System discharges sewage to drain ile or surface waters.	☐ Yes* ⊠ No	
System causes sewage backup into dwelling or establishment.	☐ Yes* ☒ No	_
Any "yes" answer above indicates imminent threat to public health an		_
Describe verification methods and	results:	
None of the above observed during s	ite visit 11/2/2021. Jo	ohn reported no issues with the system.
<b>nk integrity</b> – Compliance	component #2	2 of 5
nk integrity – Compliance Compliance criteria:	component #2	2 of 5 Attached supporting documentation:
Compliance criteria:	component #2  ☐ Yes* ☑ No	
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit,		Attached supporting documentation:
Compliance criteria: System consists of a seepage pit,		Attached supporting documentation:  Empty tank(s) viewed by inspector
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes* ⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	☐ Yes* ⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance  11/6/2020
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:	☐ Yes* ☑ No ☐ Yes* ☑ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance  (mm/dd/yyyy):  (must be within three year
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance  11/6/2020
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indic	☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance  (mm/dd/yyyy):  (See form instructions to ensure assessment complete.)

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021

Pr	operty Address: 23734 Itasca Ave N Forest Lake, MN 55025
В	siness Name: Zierke Soil Testing Date: 11/2/2021
3.	Other compliance conditions – Compliance component #3 of 5
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured?
	☐ Yes* ☑ No ☐ Unknown
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety? 🗌 Yes* 🖾 No 🗎 Unknown
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.
	3c. System is non-protective of ground water for other conditions as determined by inspector? ☐ Yes* ☒ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500? ☐ Yes* ☑ No
	*Yes to 3c or 3d - System is failing to protect groundwater.
	Describe verification methods and results:
	Attached supporting documentation:   Not applicable
_	
1.	Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⋈ Not applicable
	Is the system operated under an Operating Permit? ☐ Yes ☐ No ☐ If "yes", A below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? $\square$ Yes $\square$ No If "yes", B below is required
	BMP = Best Management Practice(s) specified in the system design
	If the answer to both questions is "no", this section does not need to be completed.
	Compliance criteria:
	a. Have the operating permit requirements been met? ☐ Yes ☐ No
	b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No
	Any "no" answer indicates noncompliance.
	Describe verification methods and results:
	Attached supporting documentation:   Operating permit (Attach)

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021

siness Name: Zierke Soil Testing		Date: <u>1</u>	1/2/2021	
Soil separation – Compliance con	nponent #5	of 5		
Date of installation 11/1/2002 (mm/dd/yyyy)	Unknown			
Shoreland/Wellhead protection/Food beverage lodging?	☐ Yes ⊠ No	Attached supporting documentation:  Soil observation logs completed for the	e renort	
Compliance criteria (select one):		Two previous verifications of required vertical separation		
5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	☐ Yes ☐ No*	☐ Not applicable (No soil treatment area		
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.				
5b. Non-performance systems built	⊠ Yes □ No*	Indicate depths or elevations		
April 1, 1996, or later or for non- performance systems located in Shoreland		A. Bottom of distribution media	101.7'	
or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:		B. Periodically saturated soil/bedrock	98.2'	
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*		C. System separation	3.5'	
		D. Required compliance separation*	3.0'	
		*May be reduced up to 15 percent if allo Ordinance.	wed by Local	
5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day)	Yes No*			
Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.				

**Upgrade requirements:** (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

800-657-3864 •

Describe verification methods and results:

Property address: 28734 Itasca August	Parcel ID:
City: forest (ake	State: VNV Zip code: 55035
Optional section: Sewage Tank Compliance C	Certification (Tank integrity assessment)
This form does not represent a complete system inspection r this form, completed, may serve as a tank integrity assessment.	eport and only certifies sewage tank compliance status. i.e.,
<b>Instructions:</b> This section of the form may be completed and sig Maintenance Business who personally conducts the necessary prothe system.	ned by a Designated Certified Individual (DCI) of a licensed SSTS occurres to assess the compliance status of each sewage tank in
When this section of the form is signed by a qualified certified prof Existing System Compliance Inspection Report: Compliance inspection on the MPCA website at https://www.pca.state.mn.us/water.	ection form - Existing system (wg-wwists4-31b). This form can be
The information and certified statement on this form is required windividual other than the SSTS Inspector that submits an inspection component compliance and is allowable under Minn. R. 7082.0700 three years beyond the signature date on this form unless a new of required according to local regulations. Additional Administrative F. 7082.0700, subp. 4 Items B, C, and D; 7083.0730 Item C.	on report. This form represents a third party assessment of SSTS 0, subp. 4 Item (B) subitem (1). This form is valid for a period of evaluation is requested by the owner or owner's agent or is
Certificate of sewage tank compliance	Notice of sewage tank non-compliance
Affirm all three statements:	Select all that apply:
The SSTS does not contain a seepage pit, cesspool, drywell, leaching pit, or other pit.  It does not contain a sewage tank that was designed to be watertight, but subsequently leaks below the designed operating depth.  It does not represent an imminent safety threat by reason of unsecured, damaged, or weak maintenance hole cover(s) or other unsafe condition.	☐ The SSTS has a seepage pit, cesspool, drywell, leaching pit, or other pit — "Failure to Protect Groundwater."  ☐ It has a sewage tank that was designed to be watertight, but subsequently leaks below the designed operating depth — "Failure to Protect Groundwater."  ☐ It presents a threat to public safety by reason of unsecured, damaged, or weak maintenance hole cover(s) or other unsafe condition — "Imminent Threat to Public Health or Safety."
Company information	Designated Certified Individual (DCI) information
Company name: Olson's Sewer Service, Inc.	Print name: Bran Wart
Business license number: 216	Certification number: C9646
I personally conducted the work described above as a Designated Business. I personally conducted the necessary procedures to ass	l Certified Individual of a Minnesota-licensed SSTS Maintenance sess the compliance status of each sewage tank in this SSTS.
By typing/signing my name below, I certify the above statement this information can be used for the purpose of processing this for Designated Certified Individual's signature:	ts to be true and correct, to the best of my knowledge, and that
pesignated pertilled individual's signature.	Date (mm/dd/yyyy): 4 20

## **Logs of Soil Borings**

Location of Project:

23734 Itasca Ave N Forest Lake, MN 55025

Borings Made by Ben Zierke

Date:

11/1/2021

Hand bucket auger used for borings; USDA - SCS Soil Classification used.

Depth, in Inches  O				
Inches  O	Depth, in	D. J. D. J. A	Depth, in	Daving Neverlan 2
O		Boring Number 1		Boring Number 2
0-13" 10YR 5/4 sandy loam  13-22" 10YR 5/4 sandy loam  22-28" 7.5YR 4/4 loam, 5YR 5/6 concentrations and 10YR 5/1 depletions below 22"   End of boring at 2.3 lose  Standing water table: Precent at S	lilicites			
22-28"  7.5YR 4/4 loam, 5YR 5/6 concentrations and 10YR 5/1 depletions below 22"  End of Doring at 2-3 leed Standing water table: Present at Standing water table: Pr	0		0	
22-28"  7.5YR 4/4 loam, 5YR 5/6 concentrations and 10YR 5/1 depletions below 22"  End of Doring at 2-3 leed Standing water table: Present at Standing water table: Pr	0-13"	10YR 3/3 sandy loam		
22-28"  7.5YR 4/4 loam, 5YR 5/6 concentrations and 10YR 5/1 depletions below 22"  End of boring at 2-3 Res  Standing water table: Present at  Standing water table: Observed at  Boring Number 3  Depth, in Inches  O  Boring Number 3  Depth, in Inches  O  Boring Number 4  Boring Number 4  O  Boring Number 4  Boring Number 4  O  Boring Number 4  Bo				
22-28"  7.5YR 4/4 loam, 5YR 5/6 concentrations and 10YR 5/1 depletions below 22"  End of boring at 2-3 Res  Standing water table: Present at  Standing water table: Observed at  Boring Number 3  Depth, in Inches  O  Boring Number 3  Depth, in Inches  O  Boring Number 4  Boring Number 4  O  Boring Number 4  Boring Number 4  O  Boring Number 4  Bo	).	annual and a second a second and a second and a second and a second and a second an		
and 10YR 5/1 depletions below 22"    End of boring at   2.3   Ret	13-22"	10YR 5/4 sandy loam		
and 10YR 5/1 depletions below 22"    End of boring at   2.3   Ret				
and 10YR 5/1 depletions below 22"    End of boring at   23   Rest   Standing water nature   Rest of depth   Hours after boring   Standing water nature   Rest of depth   Hours after boring   Standing water nature   Rest of depth   Hours after boring   Standing water nature   Rest of depth   Hours after boring   Standing water nature   Rest of depth   Hours after boring   Standing water nature   Rest of depth   Hours after boring   Rest   Rest of depth   Hours after boring   Rest	22 20"	7 EVP 4/4 loam EVP E/6 concentrations		
depletions below 22"  End of boring at	22-20	The state of the s		
End of boring at		and 10YR 5/1		
End of boring at		depletions below 22"		
Standing water table: Present at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Mottled Soil on present in bore hole				
Standing water table: Present at Feet of depth Hours after boring Standing water table: Present at Feet of depth Standing water not present in hole Mottled Soil: Observed at Feet of depth Mottled Soil: Feet of depth Mottled Soil: Observed at Feet of depth Mottled Soil: Feet of depth Mottled Soil: Observed at Feet of depth Mottled Soil: Feet of depth Mottled Soil on present in bore hole  Depth, in Inches O  Boring Number 4 Inches O  End of boring at Feet of depth Standing water table: Present at Feet of depth Mottled Soil: Observed at Feet of depth Mottled Soil on present in hole Mottled Soil: Observed at Feet of depth Mottled Soil on present in bore hole  Standing water not present in hole Mottled Soil: Observed at Feet of depth Mottled Soil on present in bore hole  Mottled Soil on present in bore hole  Standing water not present in bore hole  Mottled Soil on present in bore hole  Standing water not present in bore hole				
Standing water table: Present at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Mottled Soil on present in bore hole				
Standing water table: Present at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Mottled Soil on present in bore hole				
Standing water table: Present at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Mottled Soil on present in bore hole				
Standing water table: Present at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Mottled Soil on present in bore hole				
Standing water table: Present at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Hours after boring Standing water not present in hole Mottled Soil: Observed at Feet of depth Mottled Soil on present in bore hole				
Present at feet of depth Standing water not present in hole Mottled Soil: Observed at 1.8 feet of depth Mottled Soil: Observed at 1.8 feet of depth Mottled Soil: Observed at feet of depth Mottled Soil: Observed at feet of depth Mottled Soil not present in bore hole Comments.  Depth, in Inches O				
Standing water not present in hole    Standing water not present in hole   Mottled Soil:			0	
Observed at 1.8 feet of depth Mottled soil not present in bore hole Comments:    Depth, in Inches		Management of the Control of the Con		and the second s
Mottled soil not present in bore hole Comments:  Depth, in Inches O		10 Fact of Jacob		fact of don'th
Depth, in Inches O		AND THE PARTY OF T		the state of the s
Inches  O  End of boring at   teet   Standing water table:   Present at   feet of depth   Hours after boring   Standing water table:   Present at   feet of depth   Hours after boring   Standing water not present in hole   Mottled Soil:   Observed at   feet of depth   Mottled Soil:   Observed		Solit in bote note	200	
Inches  O  End of boring at   teet   Standing water table:   Present at   feet of depth   Hours after boring   Standing water table:   Present at   feet of depth   Hours after boring   Standing water not present in hole   Mottled Soil:   Observed at   feet of depth   Mottled Soil:   Observed		T	T=	r
End of boring at leet  Standing water table: Present at feet of depth Standing water not present in hole  Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole	Depth, in	Roring Number 3	Depth, in	Boring Number 4
End of boring at feet  Standing water table: Present at feet of depth Standing water not present in hole  Mottled Soil: Observed at feet of depth  Mottled soil not present in bore hole  End of boring at feet of depth Standing water table: Present at feet of depth Standing water not present in hole Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole	Inches	Dornig Humber 5	Inches	Doring realises 4
End of boring at  Standing water table: Present at Feet of depth Standing water table: Present at Feet of depth Standing water not present in hole Mottled Soil: Observed at Mottled Soil on tyresent in bore hole  End of boring at Standing water table: Present at Standing water table: Present at Standing water not present in hole Mottled Soil: Standing water not present in hole Mottled Soil: Observed at Mottled Soil on tyresent in bore hole  Mottled Soil on tyresent in bore hole	0		0	
Standing water table: Present at Standing water not present in hole Standing water not present in hole Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole	10		0	
Standing water table: Present at Standing water not present in hole Standing water not present in hole Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole				
Standing water table: Present at Standing water not present in hole Standing water not present in hole Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole				
Standing water table: Present at Standing water not present in hole Standing water not present in hole Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole				
Standing water table: Present at Standing water not present in hole Standing water not present in hole Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole				
Standing water table: Present at Standing water not present in hole Standing water not present in hole Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole				
Standing water table: Present at Standing water not present in hole Standing water not present in hole Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole				
Standing water table:  Present at Standing water not present in hole  Mottled Soil:  Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole				
Standing water table:  Present at Standing water not present in hole  Mottled Soil:  Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole				
Standing water table:  Present at Standing water not present in hole  Mottled Soil:  Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole				
Standing water table:  Present at Standing water not present in hole  Mottled Soil:  Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole		1		
Standing water table:  Present at Standing water not present in hole  Mottled Soil:  Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole				
Standing water table:  Present at Standing water not present in hole  Mottled Soil:  Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole				
Standing water table:  Present at Standing water not present in hole  Mottled Soil:  Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole			1	
Standing water table:  Present at Standing water not present in hole  Mottled Soil:  Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole				
Standing water table:  Present at Standing water not present in hole  Mottled Soil:  Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole				
Standing water table: Present at Standing water not present in hole Standing water not present in hole Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole				0.00
Present at feet of depth Hours after boring Standing water not present in hole  Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole	End of boring at	feet	End of boring at	feet
Standing water not present in hole  Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole				
Mottled Soil: Observed at feet of depth Mottled soil not present in bore hole  Mottled soil not present in bore hole  Mottled soil not present in bore hole		ble:	The second of the second second of	
Mottled soil not present in bore hole Mottled soil not present in bore hole	Present at	ble: feet of depth Hours after boring	Present at	feet of depth Hours after boring
	Present at Standing water not	ble: feet of depth Hours after boring present in hole	Present at Standing water not Mottled Soil:	feet of depth Hours after boring present in hole
	Present at Standing water not Mottled Soil: Observed at	ble: feet of depth present in hole feet of depth feet of depth	Present at Standing water not Mottled Soil: Observed at	feet of depth Hours after boring present in hole feet of depth

