

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	07/13/2021 Reason	for Maintenance: _	Routine	S 1000	2010
Property Address:15	790 S 15th St.	P	roperty Owner's Na	ame: Laura Runk	
Municipality:Afton	ZIP: 5500	1 Property Ider	ntification Number:		
		aintainer Name and License No. Schlomka Service LLC/L2989			
maniconarios i crime no		antanier ranie an	a Electibe 110.		
		Tank Mane	uramont (must be	completed if table	NOT numped)
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: ☐ Maintenance Hole ☑ Other (enter authorization code) Were all covers securely replaced? ☐ Yes ☐ No N/A Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? ☐ Unknown 					
	Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1		Yes No Yes No Yes No Some answers unknown. Pumped through inspection pipe.			
	Septic/Holding Tank #2		Yes No	1222	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
Some answers unknown. Pumped through inspection pipe.					
		<u> </u>		A STATE OF THE STA	
6. Location of septage disposal: Metro MCES WWTP					

Schlomka Services, LLC 1904 Vermillion St. Hastings, MN 55033 License# 2989 P: 651-459-3718