

13792 247<sup>th</sup> Avenue – Zimmerman, MN 55398 Phone (763) 274-0925 Fax (763) 274-0928

## **Septic Compliance**

June 29,2016

Renee Zugschwert 3737 Sun Terrace White Bear Lake, MN 55110

**Project:** 10191 110th St N, Stillwater

A septic compliance was completed at the above address and the system is according to the M.P.C.A codes for chapter 7080, and local codes for The system has the following attributes:

Non-Compliant Washington County

Date Built: 1972 Bedrooms: 3

Septic Tank: unknown size

Pump Tank: gravity

Soil Treatment: unknown type and dimensions. Soil separation is not adequate.

Steinbrecher Companies, Inc. has been hired to perform a compliance inspection of your ISTS for compliance with local ordinances pursuant to Minn. Stat. § 155.55 (2010). The compliance criteria required by Minn. Stat. § 155.55 Subd. 5a (2010) and Minn R 7080.1500 (2011). A compliance inspection is a snapshot in time of your septic system and does not warrant the condition or longevity of your septic system. Steinbrecher Companies, Inc. disclaims any use of the compliance inspection beyond determining ISTS compliance pursuant to Minn. Stat. § 155.55 (2010).

Sincerely,

Robert Polgreen

Steinbrecher Companies, Inc.

6619 Polyre



## Compliance Inspection Form Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

nstructions: Inspection results based on Minnesota Pollution Control Agency (MPCA)  For local tracking purposes: equirements and attached forms - additional local requirements may also apply.							
Submit completed form to within 15 days.	Local Unit of Government (LUG) ar	nd system owner					
System Status							
System status of	on date (mm/dd/yyyy):	June 29,2016					
(Valid for 3	t - Certificate of Complianc years from report date, unless ned in Local Ordinance)			<b>pliant - Notice of Noncompliance</b> de Requirements on page 3)			
☐ Impact☐ Other (☐ Tank In☐ Other (☐ Soil Se	ncompliance (check all applicable) on Public Health (Compliance Compliance Compliance Conditions (Compliategrity (Compliance Compenant Compliance Compliance Compliance Compliance Componeing permit/monitoring plan requirements	Component #1) - Immin ince Component #3) - I it #2) - Failing to protec ince Component #3) - I int #4) - Failing to prote	mminent threat to t groundwater failing to protect g ct groundwater	o public health and safety			
Property Information Property Address:	Parcel ID# 10191 110th St N, Stillwater	or Sec/Twp/Range: 1		Owner's Request			
Property Owner:	· · · · · · · · · · · · · · · · · · ·						
or			<u> </u>				
Owner's Representative:		0 Representa		- (CEA) 400 CEEE			
Local regulatory authority Brief system description:	y: Washington County septic tank to unkno		authority phone:	(651) 430-6655			
Comments or recomment replace system.  No construction informat	dations:	wii son tratifient.					
determination of future s	ecessary information has been g ystem performance has been n em, inadequate maintenance, o	or can be made due to	· · · · · · · · · · · · · · · · · · ·	tatus of this system. No ons during system construction,			
Inspector Name: Business Name:	Robert Polgreen Steinbrecher Companies, Inc.	Ceri	ification number: License number:				
Inspector Signature:	I but godgue		Phone number:	: (763) 274-0925			
Necessary or Locally F  Soil boring logs Other informat		System / As-built drav e, aerial photo	ving 🗆	Forms per local ordinance			

Property Address: 10191 110th St N, Stillwater			Inspector Initials / Date: RGP			June 29,2016				
1. I	mpact on Public Health - Compliance	e compo	onent #1 (	of 5						
	Compliance criteria: System discharge sewage to the	□Yes	√No		'erification method(s): Searched for surface outlet					
	ground surface.		Les Mino		<ul><li>Searched for surface outlet</li><li>Searched for seeping in yard/backup in home</li></ul>					
	System discharge sewage to drain tile	□Yes	√No		Excessive ponding in soil sy					
	or surface waters.		√No		Homeowner testimony (Se	/Explanation)				
	System cause sewage backup into	□Yes			"Black soil" above soil dispe					
	dwelling or establishment.  Any "yes" answer above indicates the	system :			System requires "emergend	ncy" pumping				
	· ·				Performed dye test	. /= .				
	an imminent Threat to Public Health a	iiu Sațet	<u>y.</u>		Unable to verify (See comn					
	Comments / Explanation:				☐ Other methods not listed (See comments/Explanation)					
2. 1	Fank Integrity - Compliance compone	ent #2 o	of 5							
	Compliance criteria:			V	erification method(s):					
	System consists of a seepage pit,	□Yes	√No		Probed tank(s) bottom					
	cesspool, drywell, or leaching pit.			<u></u>	, ,	ords				
					Examined Tank Integrity Fo	rm (Attach)				
	See page pits meeting 7080.2550 may be				Observed liquid level below	lepth				
	compliant if allowed in local ordinance.	-			Examined empty (pumped)					
	Sewage tank(s) leak below their	□Yes	√No		Probed outside tank(s) for Unable to verify (See Comm		nation)			
	designed operating depth.		<u>- 110</u>	H	Other methods not listed (S					
	If yes, which sewage tank(s) leaks:		_	_	,		, , ,			
	Any "yes" answer above indicates the									
	system is Failing to Protect Groundwat	ter.								
	Comments/Explanation: tank is very deep (effluent at 9.5' below grade no manhole.	e )								
3. Oth	her Compliance Conditions - Complia a. Maintenance hole covers are damaged, cra □Yes* ☑No □Unknown		•							
	b. Other issues (electrical hazards, etc.) to im  'Yes* 'No  Unknown  *System is an imminent threat to p  Explain:				oublic health or safety.					
	c. System is non-protective of ground water f *System is failing to protect groundwate Explain:		ons as deterr	nined by	inspector. □Yes*	: ☑No				


⊔Unkn □Ves □Yes		Soil obs observa unless s	tion method(s): ervation does not ex tions by two indepei ite conditions have b	-		
□Unkn □Yes	own ☑No	Soil obs observa unless s	ervation does not ex tions by two indepe	-		
 ∏Yes	√No	Soil obs observa unless s	ervation does not ex tions by two indepe	-		
 ∏Yes	√No	Soil obs observa unless s	ervation does not ex tions by two indepe	-		
		observa unless s	tions by two indepe	-		
Yes	√No	unless s	•		are sufficient	
∐Yes	√No			een altered o		
∐Yes	√No		ments differ.	, con unter cu c	,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
∐Yes	√No					
			uct soil observation(			
			<ul><li>☐ Two previous verifications (Attach boring logs)</li><li>☐ Not applicable (Holding tank(s), no drainfield)</li></ul>			
			le to verify (See Com		nation)	
		□ Othe	r (See Comments/Ex	pianation)		
		Comme	nts / Explanation:			
				be = 100'		
□Yes	□No	_				
		possible	cesspit, inaccessabl	e depths.		
		_ Indicate	depths of elevation	ıs		
∐Yes	□No	A. Botto	m of distribution me	edia	89.5'	
				/bedrock	91.79'	
					negative	
					24"	
				ercent if allov	ved by Local	
		Ordinari	cc.			
		_				
tem is						
	oliance c			applicable		
	∐Yes		•			
	_		B below is required			
ed in the	e system de	esign				
tion do	es not need	to be complete	d.			
		•				
	_	∐Yes	□ No			
	unctioning	rres	NO			
.e.						
immine	ent threat to	o public health ai	nd safetv (ITPHS) mu	st beuparader	d, replaced.	
		•				
-		•			-	
		· ·				
	□Yes  Complit?  of in the ion does  immine of this tem mu	Tyes No  The is  Compliance of the interest of this notice or the must be upgrown.	tank gramedia b B = redo possible    Midicate	Media bottom est from efflue   B = redox in DF area, grade =   possible cesspit, inaccessable   possible cesspit, inaccessable	tank grade at observation tube = 100' media bottom est from effluent level B = redox in DF area, grade = 93.79' possible cesspit, inaccessable depths.    Major   Major	

651.296.6300 800.657.3864 TTY 651.282.5332 or 800.657.3864


those used in connection with food, beverage, and lodging establishments as defined in law.

Boring 1	Elevation:	Location	ո։	
Soil Horiz	ons Depth (inches)	Texture	Color	Structure
0 -2"		loamy top soil	10yr 3/2	friable
2 - 14"		loose clay loam	10yr 7.54/4	loose
14 - 24"		clay	10yr 6/3	blocky
redox at 24"				
				·
Boring 2	Elevation:	Location		
Soil Horiz	ons Depth (inches)	Texture	Color	Structure
		_		
Boring 3	Elevation:	Location		
Soil Horiz	ons Depth (inches)	Texture	Color	Structure
Boring 4	Elevation:	Location		
Soil Horiz	ons Depth (inches)	Texture	Color	Structure
<del>-</del>				

## 10191 110th St N, Stillwater







Parcel ID: 1103021220001

**Parcel Address:** 

10191 110TH ST N, CITY OF GRANT

0 62.5 125 250 Feet

MAP FOR REFERENCE ONLY NOT A LEGAL DOCUMENT

This drawing is the result of the compilation and reproduction of land records as they appear in various Washington County offices. The drawing should be used for reference purposes only. Washington County is not responsible for any inaccuracies.