

Property Address: 14946 15<sup>th</sup> St S, Afton, MN 55001

Business Name: Midwest Sewer Services

Date: 2/1/2022

### 1. Impact on public health – Compliance component #1 of 5

**Compliance criteria:**

|   |  |
|---|--|
| System discharges sewage to the ground surface              | <input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No |
| System discharges sewage to drain tile or surface waters.   | <input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No |
| System causes sewage backup into dwelling or establishment. | <input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No |

**Attached supporting documentation:**

Other: \_\_\_\_\_  
 Not applicable

**Any “yes” answer above indicates the system is an imminent threat to public health and safety.**

**Describe verification methods and results:**

Although not a compliance criteria, it should be noted that the well is located approximately 42 feet from the septic system; the required setback between the septic system and the well is 50 feet.

### 2. Tank integrity – Compliance component #2 of 5

**Compliance criteria:**

|  |  |
|--|--|
| System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? | <input checked="" type="checkbox"/> Yes* <input type="checkbox"/> No |
| Sewage tank(s) leak below their designed operating depth?                        | <input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No |
| If yes, which sewage tank(s) leaks:  | Laundry/Basement   |

**Attached supporting documentation:**

Empty tank(s) viewed by inspector

Name of maintenance business: Pinky's Sewer Service

License number of maintenance business: L1673

Date of maintenance: 2/1/2022

Existing tank integrity assessment (Attach)

Date of maintenance (mm/dd/yyyy): \_\_\_\_\_ (must be within three years)

(See form instructions to ensure assessment complies with Minn. R. 7082.0700 subp. 4 B (1))

Tank is Noncompliant (pumping not necessary – explain below)

Other: \_\_\_\_\_

**Any “yes” answer above indicates the system is failing to protect groundwater.**

**Describe verification methods and results:**

At the time of our inspection, the manhole cover was broken. This manhole needs to be replaced as soon as possible. In addition, the manhole is buried. I recommend extending this cover to the ground surface to facilitate easier access and proper maintenance.