P	Property Address: 14393 42 nd Street South Afton	
В	Susiness Name: SS Septic Solutions, LLC.	Date: 0412/2022
3.	Other compliance conditions – Compliance component #3 of 5	· · · · · · · · · · · · · · · · · · ·
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured?	
	☐ Yes* ☒ No ☐ Unknown	
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety? ☐ Yes* ☒ No ☐ Unknown	
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ⊠ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* ☑ No
	*Yes to 3c or 3d - System is failing to protect groundwater.	4
	Describe verification methods and results:	
	Attached connecting decomentations [] Not applicable []	
	Attached supporting documentation: Not applicable	
м	Out and it and nitrogen DBAD's Conniliance commonent #4 of	6 F 57 N
4.	Operating permit and nitrogen BMP* – Compliance component #4 of	Not applicable
	Is the system operated under an Operating Permit?	f "yes", A below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? Yes No I	f "yes", B below is required
	BMP = Best Management Practice(s) specified in the system design	
	If the answer to both questions is "no", this section does not need to be completed	1.
	Compliance criteria:	
	a. Have the operating permit requirements been met?	
	b. Is the required nitrogen BMP in place and properly functioning? Yes No	
	Any "no" answer indicates noncompliance.	
	Describe verification methods and results:	
	¥	
	Attached supporting documentation: Operating permit (Attach)	