

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:		in the second se		S	Steve Miggler
Property Address: 9937				me:	
Municipality:					
Maintenance Permit No:_	N	laintainer Name an	d License No. Sch	lomka Service LLC	C/L2989
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:   Maintenance Hole  Other (enter authorization code)					
2. Were all covers securely replaced?					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Unknown					
	Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1		Yes No Yes No Yes No Some answers unknown. Pumped through inspection pipe.			
S	eptic/Holding Tank #2	─────────────────────────────────────	Yes No	☐ Yes ☐ No	
P	retreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
P	ump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4 How many callons of	sontago were removed	7			
4. How many gallons of septage were removed?  Tank #1 1200 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
				-,,	The second section of the section of
Some answers unknow	n. Pumped through inspec	uon pipe.	48)30.44		
6. Location of septage d	isposal: Metro MCES WV	VTP			

Schlomka Services, LLC 1904 Vermillion St. Hastings, MN 55033 License# 2989 P: 651-459-3718