ZIERKE SOIL TESTING

Kristine Lavine 14101 Oakhill Rd N Scandia, MN 55073

6/6/2022

Dear Kristine Lavine,

At your request, I have conducted a septic inspection to determine the compliance status of your septic system pursuant to Minnesota Rules Chapter 7080.1500.

The compliance test set out in 7080.1500 has three main inquiries: 1). Is the system functioning hydraulically (disposing of effluent in a manner that prevents it from coming in contact with people)? 2). Are the septic tanks water tight? 3). Does the system have sufficient vertical separation between the bottom of the septic system and restrictive layers (bedrock, standing water, seasonally wet layers, etc) to provide full treatment of effluent?

Based off of these criteria, your septic system is <u>compliant</u>. A certification of compliance is in effect for three years from the date it is issued. To be clear, this should not be construed as a guarantee of future system function – there are too many factors that influence the lifespan of a septic system for an inspector to predict or even guess how long a septic system will last. A copy of this report will be filed with your local unit of government for their records.

Sincerely,

Benjamin Zierke

MPCA Lic 119, Cert 9594

ADDRESS: 28587 Jeffrey Ave Chisago City, MN 55013

PHONE 651-249-1346

EMAIL benzierke@gmail.com



Compliance inspection report form

Existing Subsurface Sewage Treatment System (SSTS)

520 Lafayette Road North St. Paul, MN 55155-4194

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf.

Property information	Local tracking number:	
Parcel ID# or Sec/Twp/Range: 1503220140004	Reason for Inspection Sale	
Local regulatory authority info: Washington County		
Property address: 14101 Oakhill Rd N Scandia, MN 55073		
Owner/representative: Kristine Lavine	Owner's phone: 651-247-5631	
Brief system description: (2) 1000 gallon septic tanks, 1000 gall	lon lift tank, mound dispersal system	
System status		
System status on date (mm/dd/yyyy): _6/6/2022		
☐ Compliant – Certificate of compliance*	☐ Noncompliant – Notice of noncompliance	
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and	Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.	
abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.) *Note: Compliance indicates conformance with Minn.	An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt	
R. 7080.1500 as of system status date above and does not guarantee future performance.	of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.	
Reason(s) for noncompliance (check all applicate	ole)	
Impact on public health (Compliance component #1	,	
☐ Tank integrity (Compliance component #2) – Failing		
·	nent #3) – Imminent threat to public health and safety	
Other Compliance Conditions (Compliance compon		
-	2500 (Compliance component #3) – Failing to protect groundwater	
Soil separation (Compliance component #5) – Failin		
	mpliance component #4) – Noncompliant - local ordinance applies	
Comments or recommendations	and he remained. The electrical boy at the lift station is availed and	
	nould be repaired. The electrical box at the lift station is cracked and having a new weatherproof box installed at the lift station.	
g	g	
Certification		
	to determine the compliance status of this system. No determination of wn conditions during system construction, possible abuse of the system,	
,	e and correct, to the best of my knowledge, and that this information can be	
Business name: Zierke Soil Testing	Certification number: 9594	
Inspector signature:	License number: 119	
(This document has been electronically sig	nned) Phone: 651-249-1346	
Necessary or locally required supporting do	ocumentation (must be attached)	
☐ Soil observation logs ☐ System/As-Built ☐ Locally r	required forms	
Other information (list):		

Compliance criteria:		Attached supporting documentation:	
System discharges sewage to the ground surface	☐ Yes* ☒ No	☐ Other: ☑ Not applicable	
System discharges sewage to drain tile or surface waters.	☐ Yes* ☒ No		
System causes sewage backup into dwelling or establishment.	☐ Yes* ☒ No		
Any "yes" answer above indicates imminent threat to public health an			
Describe verification methods and	results:		
None of the above observed during si	ite visit 6/6/2022.		
nk integrity – Compliance	component #2	of 5	
nk integrity – Compliance	component #2	of 5	
nk integrity – Compliance Compliance criteria:	component #2	of 5 Attached supporting documentation:	
Compliance criteria:	·	Attached supporting documentation:	
Compliance criteria: System consists of a seepage pit,	component #2		
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	·	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector	Smilios
Compliance criteria: System consists of a seepage pit,	·	Attached supporting documentation:	Smilies
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	·	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector	
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ☑ No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business:	
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☑ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance:	6/6/2022
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☑ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attack	6/6/2022 n)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☑ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attack	6/6/2022 n)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within (See form instructions to ensure assessment)	6/6/2022 n) three years)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within	three years) ment complies with
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within (See form instructions to ensure assessment) Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necess	three years) ment complies with
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment) Minn. R. 7082.0700 subp. 4 B (1))	three years) ment complies with
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ ates the system er.	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within (See form instructions to ensure assessment) Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necess	three years) ment complies with

Pı	roperty Address: 14101 Oakhill Rd N Scandia, MN 55073	
	usiness Name: Zierke Soil Testing	Date: 6/6/2022
3.	Other compliance conditions – Compliance component #3 of 5	
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unse	ecured?
	☐ Yes* ☑ No ☐ Unknown	
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safet	y? ☐ Yes* ☒ No ☐ Unknown
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ☒ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* ☒ No
	*Yes to 3c or 3d - System is failing to protect groundwater.	
	Describe verification methods and results:	
	Attached supporting documentation: ⊠ Not applicable □	
4.	Operating permit and nitrogen BMP* – Compliance component #4 o	of 5 🛛 Not applicable
	Is the system operated under an Operating Permit? ☐ Yes ☐ No	If "yes", A below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No	
	BMP = Best Management Practice(s) specified in the system design	
	If the answer to both questions is "no", this section does not need to be completed	d.
	Compliance criteria:	
	a. Have the operating permit requirements been met? ☐ Yes ☐ No	
	b. Is the required nitrogen BMP in place and properly functioning? Yes No	
	Any "no" answer indicates noncompliance.	
	Describe verification methods and results:	
	Describe Verification methods and results.	
	Attached supporting documentation: Operating permit (Attach)	
	Coperating described and a coperating permit (Attach)	


https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021

usiness Name: Zierke Soil Testing			Date: _	6/6/2022
Soil separation	– Compliance cor	nponent #5 o	f 5	
Date of installation	12/4/2001 (mm/dd/yyyy)	Unknown		
Shoreland/Wellhead protection/Food		⊠ Yes □ No	Attached supporting documentation:	
beverage lodging?			oxtimes Soil observation logs completed for the report	
Compliance criteria (select one):			☐ Two previous verifications of required vertical	
5a. For systems built pro not located in Shore Protection Area or i beverage or lodging	not serving a food,	☐ Yes ☐ No*	☐ Not applicable (No soil treatment area)	
Drainfield has at lea separation distance saturated soil or be				
5b. Non-performance s		⊠ Yes □ No*	Indicate depths or elevations	
April 1, 1996, or later or for non- performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*		A. Bottom of distribution media	101.5'	
		B. Periodically saturated soil/bedrock	98.0'	
		C. System separation	3.5'	
		D. Required compliance separation*	3.0'	
		*May be reduced up to 15 percent if allowed by Local Ordinance.		
2,500 gallons per d	r pre-2008 Rules; ns built under 2008	☐ Yes ☐ No*		
Drainfield meets the separation distance saturated soil or be	from periodically			

Describe verification methods and results:

Upgrade requirements: (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

800-657-3864



Logs of Soil Borings

Location of Project: 14101 Oakhill Rd N Scandia, MN 55073 Borings Made by Ben Zierke 6/6/2022 Date: Hand bucket auger used for borings; USDA - SCS Soil Classification used. Depth, in Depth, in **Boring Number 1 Boring Number 2** Inches Inches 0-13" Sandy loam fill soil 13-19" 10YR 2/2 fine sandy loam 19-24" 10YR 5/3 fine sandy loam 24-30" 10YR 6/3 fine sandy loam, 7.5YR 5/6 and 10YR 6/1 redox End of boring at End of boring at Standing water table: Standing water table: feet of depth Hours after boring feet of depth Hours after boring Present at Present at Standing water not present in hole Standing water not present in hole Mottled Soil: Mottled Soil: feet of depth Observed at Observed at Mottled soil not present in bore hole Mottled soil not present in bore hole Comments: Comments: Depth, in Depth, in **Boring Number 3 Boring Number 4** Inches Inches End of boring at End of boring at Standing water table: Standing water table:

Present at

Mottled Soil:

Observed at

Comments:

Standing water not present in hole

Mottled soil not present in bore hole

Hours after boring

Hours after boring

Present at

Mottled Soil:

Observed at

Comments:

Standing water not present in hole

Mottled soil not present in bore hole