ZIERKE SOIL TESTING

Pat Collova 12555 Keller Ave N Hugo, MN 55038

7/6/2022

Dear Pat Collova,

At your request, I have conducted a septic inspection to determine the compliance status of your septic system pursuant to Minnesota Rules Chapter 7080.1500.

The compliance test set out in 7080.1500 has three main inquiries: 1). Is the system functioning hydraulically (disposing of effluent in a manner that prevents it from coming in contact with people)? 2). Are the septic tanks water tight? 3). Does the system have sufficient vertical separation between the bottom of the septic system and restrictive layers (bedrock, standing water, seasonally wet layers, etc) to provide full treatment of effluent?

Based off of these criteria, your septic system is <u>compliant</u>. A certification of compliance is in effect for three years from the date it is issued. To be clear, this should not be construed as a guarantee of future system function – there are too many factors that influence the lifespan of a septic system for an inspector to predict or even guess how long a septic system will last. A copy of this report will be filed with your local unit of government for their records.

Sincerely,

Benjamin Zierke

MPCA Lic 119, Cert 9594

Benjamin Zieske

ADDRESS: 28587 Jeffrey Ave Chisago City, MN 55013

PHONE 651-249-1346

EMAIL benzierke@gmail.com



Compliance inspection report form

520 Lafayette Road North St. Paul, MN 55155-4194

Existing Subsurface Sewage Treatment System (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf.

Property information	Local tracking number:
Parcel ID# or Sec/Twp/Range: 3103120230006	Reason for Inspection Sale
Local regulatory authority info: Washington County	
Property address: 12555 Keller Ave N Hugo, MN 55038	
Owner/representative: Pat Collova	Owner's phone: 612-685-0070
Brief system description: 1250 gallon pre-cast septic tank, gravit	ty rock trench drainfield
System status	
System status on date (mm/dd/yyyy): 7/6/2022	
	☐ Noncompliant – Notice of noncompliance
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and abatement under section 145A.04, subdivision 8 is discovered or	Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.
a shorter time frame exists in Local Ordinance.) *Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.	An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.
Reason(s) for noncompliance (check all applicab	ıle)
☐ Impact on public health (Compliance component #1)	– Imminent threat to public health and safety
☐ Tank integrity (Compliance component #2) – Failing	to protect groundwater
☐ Other Compliance Conditions (Compliance components)	ent #3) – Imminent threat to public health and safety
☐ Other Compliance Conditions (Compliance components)	ent #3) – Failing to protect groundwater
System not abandoned according to Minn. R. 7080.2	2500 (Compliance component #3) – Failing to protect groundwater
☐ Soil separation (Compliance component #5) – Failing	g to protect groundwater
☐ Operating permit/monitoring plan requirements (Con	npliance component #4) – Noncompliant - local ordinance applies
Comments or recommendations	
System functioning normally during site visit 7/6/2022.	
Cystem full offining from any during site visit 170/2022.	
Certification	
	to determine the compliance status of this system. No determination of wn conditions during system construction, possible abuse of the system,
By typing my name below, I certify the above statements to be true used for the purpose of processing this form.	and correct, to the best of my knowledge, and that this information can be
Business name: Zierke Soil Testing	Certification number: 9594
Inspector signature: Benjamin Zierke	License number: 119
(This document has been electronically sign	ned) Phone: 651-249-1346
Necessary or locally required supporting do	cumentation (must be attached)
Soil observation logs	equired forms $\ \square$ Tank Integrity Assessment $\ \square$ Operating Permit
☐ Other information (list):	

Compliance criteria:		Attached supporting documentation:
System discharges sewage to the ground surface	☐ Yes* ☑ No	☐ Other: ☐ Not applicable
System discharges sewage to drain ille or surface waters.	☐ Yes* ☒ No	
System causes sewage backup into dwelling or establishment.	☐ Yes* ⊠ No	
Any "yes" answer above indicates mminent threat to public health an		
Describe verification methods and	results:	
None of the above observed during s	site visit 7/6/2022.	
nk integrity – Compliance	component #2	of 5
nk integrity – Compliance Compliance criteria:	component #2	of 5 Attached supporting documentation:
Compliance criteria: System consists of a seepage pit,	component #2	
Compliance criteria:	· ·	Attached supporting documentation:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	· ·	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	Yes* ⊠ No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: Smilies
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	Yes* ⊠ No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: Smilles License number of maintenance business: 2428
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	Yes* ⊠ No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 7/6/2022
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	Yes* ⊠ No Yes* ⊠ No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 7/6/2022 □ Existing tank integrity assessment (Attach) Date of maintenance
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	Yes* ⊠ No Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 7/6/2022 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain by
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	Yes* No Yes* No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 7/6/2022 □ Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies Minn. R. 7082.0700 subp. 4 B (1))


Property Address: 12555 Keller Ave N Hugo, MN 55038	
Business Name: Zierke Soil Testing	Date: <u>7/6/2022</u>
3. Other compliance conditions – Compliance component #3 of	5
3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, et	tc.), or unsecured?
☐ Yes* ☑ No ☐ Unknown	
3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public hea	alth or safety? ☐ Yes* No ☐ Unknown
*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
3c. System is non-protective of ground water for other conditions as determined by ins	pector? ☐ Yes* ☒ No
3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* No
*Yes to 3c or 3d - System is failing to protect groundwater.	
Describe verification methods and results:	
Attached supporting documentation: Not applicable	
a a	
4. Operating permit and nitrogen BMP* – Compliance components	ent #4 of 5 🗵 Not applicable
Is the system operated under an Operating Permit?	es \square No If "yes", A below is required
Is the system required to employ a Nitrogen BMP specified in the system design? $\ \square$ Ye	es 🗌 No If "yes", B below is required
BMP = Best Management Practice(s) specified in the system design	
If the answer to both questions is "no", this section does not need to be	completed.
Compliance criteria:	
a. Have the operating permit requirements been met? ☐ Yes ☐ No	
b. Is the required nitrogen BMP in place and properly functioning? $\ \square$ Yes $\ \square$ No	
Any "no" answer indicates noncompliance.	
Describe verification methods and results:	
Attached supporting documentation: ☐ Operating permit (Attach) ☐	

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021 800-657-3864

usiness Name: Zierke Soil Testing		Date: _	7/6/2022
Soil separation – Compliance cor	mponent #5 o	f 5	
Date of installation 5/4/1992 (mm/dd/yyyy)	Unknown		
Shoreland/Wellhead protection/Food	⊠ Yes □ No	Attached supporting documentation:	
beverage lodging?		$oxed{\boxtimes}$ Soil observation logs completed for the	ne report
Compliance criteria (select one):		☐ Two previous verifications of required	l vertical separatio
5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	Yes No*	☐ Not applicable (No soil treatment area ☐	a)
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.			
5b.Non-performance systems built	⊠ Yes □ No*	Indicate depths or elevations	
April 1, 1996, or later or for non- performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*		A. Bottom of distribution media	96.7'
		B. Periodically saturated soil/bedrock	93.3'
		C. System separation	3.4'
		D. Required compliance separation*	3.0'
		*May be reduced up to 15 percent if allowed by Lo Ordinance.	
5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day)	☐ Yes ☐ No*		
Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.			

Describe verification methods and results:

Upgrade requirements: (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.



Logs of Soil Borings

Location of Project: 12555 Keller Ave N Hugo, MN 55038 Borings Made by Ben Zierke 7/6/2022 Date: Hand bucket auger used for borings; USDA - SCS Soil Classification used. Depth, in Depth, in **Boring Number 1 Boring Number 2** Inches Inches 0-11" 10YR 3/2 silt loam 11-20" 10YR 5/4 silt loam 20-28" 10YR 5/4 fine sand 28-64" 7.5YR 5/4 fine sand, various banding layers 4/6, 5/6, and 3/3 64-80" 7.5YR 5/4 medium sand, 4/3 loamy fine sand bands, 7% rock End of boring at End of boring at Standing water table: Standing water table: feet of depth Hours after boring feet of depth Hours after boring Present at Present at Standing water not present in hole Standing water not present in hole Mottled Soil: Mottled Soil: feet of depth Observed at Observed at Mottled soil not present in bore hole Х Mottled soil not present in bore hole Comments: Comments:

Depth, in Inches	Boring Number 3	Depth, in Inches	Boring Number 4
0		0	
End of boring at	feet	End of boring at	feet

Hours after boring

Standing water table:

Standing water not present in hole

Mottled soil not present in bore hole

Present at

Mottled Soil:

Observed at

Comments:

Hours after boring

Standing water table:

Standing water not present in hole

Mottled soil not present in bore hole

Present at

Mottled Soil:

Observed at

Comments: