

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	9/22/22 Reason	for Maintenance: _	Routine		
Property Address: 78	55 44th St Ct N Oakdale, I	MN P	roperty Owner's Na	ame:Julia Sne	:II
Municipality:	ZIP: 5512	28 Property Ider	ntification Number:		
	o; ^				White the second
maintenance Fernic N	O N	nameanier name an	d License No.		
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped		Liquid Level of Tank in			
NOTIFIC CONTROL VICTOR CONTROL		Sludge Level in Tank in Scum Level in Tank in			
□ Sludge and scum measured     Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
26 - 27 <u>(626</u>	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
□ 163 □ 140 (II	no provide measurements)				
1. Access used to remove septage:   Maintenance Hole  Other (enter authorization code)					
2. Were all covers securely replaced?					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?  No - couldn't confirm precast via					
				camera	
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	─────────────────────────────────────	☐ Yes ☐ No	☐ Yes ☐ No	
	Court of tradition of Touris #2		known. Pumped thro		
	Septic/Holding Tank #2	─────────────────────────────────────	☐ Yes ☐ No	Yes LINO	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Dump Topk				
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
		15.			
4. How many gallons of septage were removed?  Tank #1 1250 gal Tank #2 500 gal Pretreatment tank gal Pump Tank gal					
	: List any troubleshooting		illucted, tallk sale	ety concerns, or our	er concerns.
Some answers unknown. Pumped through inspection pipe.					
/ Lambian of acutous	o disposale Matro MCES WA	A/TD			
o. Lucation of septag	e disposal: Metro MCES WI	VIF		Service and an artist and a service and a se	and the same of the same of the same of

Schlomka Services, LLC 1904 Vermillion St. Hastings, MN 55033 License# 2989 P: 651-459-3718